



# Staff Report for Administrative Approval Hillside Review – Notice of Conditional Approval

Weber County Planning Division

## Synopsis

### Application Information

**Application Request:** Consideration and action on a request to approve a Hillside Review for the Blake Kingsbury residence located on Lot 70R in the Summit Eden Phase 1C.

**Applicant:** Blake Kingsbury

**Authorized Representative:** Pamela Russell

**File Number:** HSR 2018-05

### Property Information

**Approximate Address:** 8492 East Spring Park Road

**Project Area:** 0.0637 acres

**Zoning:** DRR-1

**Existing Land Use:** Vacant

**Proposed Land Use:** Single Family Residence

**Parcel ID:** 23-130-0037

**Township, Range, Section:** 7N 2E Sec 8

### Adjacent Land Use

<b>North:</b> Resort	<b>South:</b> Resort
<b>East:</b> Resort	<b>West:</b> Resort

### Staff Information

**Report Presenter:** Ronda Kippen  
[rkippen@co.weber.ut.us](mailto:rkippen@co.weber.ut.us)  
801-399-8768

**Report Reviewer:** RG

## Applicable Ordinances

- Weber County Land Use Code Title 108 (Standards) Chapter 14 (Hillside Development Review)
- Weber County Land Use Code Title 108 (Standards) Chapter 22 (Natural Hazards Areas)

## Background

The subject lot is described as *All of Lot 70R, Summit Eden Phase 1C*. The subdivision was approved by the Weber County Commission on January 21, 2014 and was recorded with the Weber County Recorder’s office on January 27, 2014 as entry# 2672945. The subject property has been identified as having an average slope in excess of 25%; therefore, the lot has been identified with an “R” which mandates a Hillside Review per the Uniform Land Use Code of Weber County (LUC) Title 108 Chapter 14, prior to the issuance of a land use and building permit.

GeoStrata has performed the required geologic and geotechnical investigation, as required in LUC Title 108 Chapter 22, to determine if there is a geologic hazard located on the site and to assess the subsurface soils in order to better design the home for slope stability and safety purposes. Information related to the construction of the dwelling including a site plan, and the geologic/geotechnical report, have been distributed to the Hillside Review Board for comment. The plans have been reviewed and approved and/or conditionally approved by all applicable review agencies.

## Planning Division Review

The Planning Division Staff has determined that the requirements and standards provided by the Hillside Review Chapter have been met for the excavation and construction of the dwelling. The following submittals were required:

1. Proposed Building Plans including a site plan(see Exhibit A)
2. Geotechnical and Geologic Investigation Report (see Exhibit B)
3. Utah Pollution Discharge Elimination system (UPDES) Permit with Storm Water Pollution Prevention Plan (See Building Permit Application Packet for Approved UPDES and SWPPP)

## Weber County Hillside Review Board comments

The Weber County Hillside Review Board, on this particular application, made comments related to the following:

Weber County Engineering Division: The Engineering Division granted approval on August 21, 2018. The approval is subject to the following conditions:

1. Follow all the recommendations of the geologic and geotechnical reports including to have a geotechnical engineer evaluate the suitability of the soils after the excavation has been dug.

Weber Fire District: The Fire district has granted approval on August 16, 2018 subject to the following conditions:

Water Supply:

S1. Fire Flow: Fire flow for the residential subdivision shall be 1000 GPM.

Fire Detection and Suppression Systems:

S2. Fire Suppression Systems: This home will require a fire suppression system.

S3. SEPERATE SUBMITAL NOTICE: Fire suppression systems and fire alarm systems require a separate submittal. A permit shall be applied for before any installation of either fire suppression system or fire alarm system. The permit shall be on the job site and be available for review by any inspector. The APPROVED STAMPED set of plans shall also be on the job site and available for review by any inspector. If there is no permit and/or approved stamped plans on the job site, there will be a Stop Work Order issued until both are on the job site. Submit plans at Weber Fire District, 2023 W. 1300 N. Farr West. (See IFC section 901.2 and 907.1.1).

S4. Exterior Notification Device: There shall be a weather proof horn/strobe device located on the street side of the building as approved by the Fire Prevention Division (coordinate with fire inspector regarding location). Such sprinkler waterflow alarm devices shall be activated by water flow equivalent to the flow of a single sprinkler of the smallest orifice size installed in the system. (See IFC 903.4.2)

Fire Department Access:

S5. Provide a temporary address marker at the building site during construction. The address numbers, whether on the building or the sign, shall be legible font. (See IFC 505.1) (See IFC 505.1).

S6. Fire access roads for this project shall be completed and approved prior to any combustible construction. Temporary roads shall meet the same requirements for height, width, and imposed loads as permanent roads (See IFC section 503.2.3; 3310; and D102.1).

Building Comments:

S7. There shall be an address on the building or on a sign visible from the street. If the address is on a sign-monument the sign-monument shall meet the requirements of the appropriate city/county planning department. The address numbers, whether on the building or the sign, shall be Arabic font with a minimum of 4" (four inches) in height with a .5" (half inch) stroke and be in contrasting colors from the background. All suites shall have number/letter designation on the doors meeting the same size requirements and contrasting color. (See IFC 505.1)

General Comments:

G1. Fire Access roads to any property shall have a minimum clear width of 20 feet (face of curb to face of curb) and a vertical clearance of 13 foot 6 inches and shall be capable of supporting a 75,000-pound load. Roads that are less than 26 feet in width shall be posted with "NO PARKING FIRE LANE" on both sides of the roadway. Roads more than 26 but less than 32 feet in width shall be posted on one side of the roadway. (Roadways and signage shall comply with appendix D of the 2015 International Fire Code as adopted by Weber Fire District).

G2. Roads shall have a maximum grade of 10% unless specifically approved. Approval requires both the Fire Marshal's approval and Weber County Engineering approval (See IFC section 503.2.7; D103.2; and Weber County ordinances).

G3. Radius on all corners shall be a minimum of 28'-0". Roads and driveways shall also comply with City/County standards as applicable. In cases of differing requirements, contact the Fire Marshal for

clarification.

G4. Roads and bridges shall be designed, constructed, and maintained to support an imposed load of 75,000 lbs. (See IFC section D102.1)

G5. All roads shall be designed, constructed, surfaced, and maintained to provide an all-weather driving surface. All weather surface may include road-base material however, the roadway must be maintained open and accessible year-round (See IFC section 503.2.3 and D102.1).

Weber County Building Inspection Department: The Building Inspection Office granted approval on August 21, 2018 based on the condition that the Geotechnical Engineer must approve the placement of footings.

Weber-Morgan Health Department: The Health Department has verified that that they will not impose any requirements or conditions for this application due to the proposed residence connecting to the Powder Mountain Water and Sewer District for culinary and wastewater services.

Weber County Planning Division: The Planning Division has granted approval subject to the applicant complying with all Board requirements and conditions. This approval is also subject to the applicant strictly adhering to the recommendations outlined in the geologic and geotechnical investigation report dated July 11, 2018 provided by GeoStrata (Geologic Job No. 594-005 and Geotechnical Job No. 594-004) including the following recommendations:

1. The recommendations contained in the geotechnical report should be incorporated into the grading and drainage design for the lot. Saturated soil conditions should be considered in maintaining the slope stability.
2. All recommendations to reduce the risks of slope stability hazards contained in the site specific geotechnical report should be followed and incorporated in the design of the site.
3. Because the landslide risk is rated low to moderate on the property, a GeoStrata geologist or geotechnical engineer must observe the foundation excavations to confirm the absence of landslide deposits.
4. A GeoStrata representative shall observe all foundation soils in footing excavations prior to placing reinforcing steel or concrete.
5. Due to the possibility of moisture reaching the foundation elements during spring runoff, it is recommended that a foundation drain be constructed around the proposed residence.

### **Planning Division Recommendations**

Based on site inspections and review agency comments, the Planning Division Staff has determined that it is necessary to impose additional requirements and conditions as part of approving HSR 2018-05. The recommendation for approval is subject to adherence to all review agencies conditions and based on the following conditions:

1. As a condition it is understood, by the applicant, the geo-technical engineer and engineering geologist that if any geologic hazards are revealed during the excavation and construction phase of the dwelling, work on Lot 70R in the Summit Eden Phase 1C will cease pending the development of appropriate mitigation measures and subsequent approval by the County.
2. Any landscaping must be approved by Weber County after receiving a recommendation from GeoStrata prior to the planting or installation on the site due to a landscaping plan not being provided as part of this application.

The recommendation is based on the following findings:

1. The application was submitted and with the required conditions, has been deemed complete.
2. The requirements and standards found in the Hillside Development Review Procedures and Standards Chapter have been met or will be met during the excavation and construction phase of the dwelling.
3. The Hillside Review Board members reviewed the application individually and have provided their comments.
4. The applicant has met or will meet, as part of the building permit process and/or during the excavation and construction phase of the dwelling, the requirements and conditions set forth by the Hillside Review Board.
5. The Planning Division Staff has determined that the proposed improvements have been sited within the required setbacks for the DRR-1 zone with the exception of the driveway and retaining wall(s).

## Administrative Approval

Administrative approval of Lot 70R in the Summit Eden Phase 1C Hillside Review (HRS 2018-05) is hereby granted based upon its compliance with the Weber County Land Use Code. This approval is subject to the requirements of applicable review agencies and is based on the recommendations, conditions and findings listed in this staff report.

Date of Administrative Approval: 8/24/18

  
Rick Grover  
Weber County Planning Director

## Exhibits

- A. Proposed Building Plans including site plan, grading plan and landscape plan
- B. Geotechnical and Geologic Investigation Report


## Map 1





**Exhibit A: Building Plans**

Building  
*dreams into*  
**legacies**




**KINGSBURY AND CHESSON  
Powder Mountain, Lot # 70**

8492 E. Spring Park,  
Weber County, Utah

Build by:  
**Scandinavian LLC**

- DRAWING INDEX:
- 1.0 COVER SHEET
  - 1.1 SITE PLAN
  - 2.1 MAIN LEVEL FLOOR PLAN
  - 2.2 UPPER LEVEL FLOOR PLAN
  - 2.5 ROOF LEVEL FLOOR PLAN
  - 2.5 AREA CALCULATION PLANS
  - 3.1 BUILDING ELEVATIONS
  - 4.1 BUILDING SECTIONS
  - 5.0 STRUCTURAL NOTES
  - S1 FOOTING AND FOUNDATION PLAN
  - S2 LOWER LEVEL FLOOR FRAMING PLAN
  - S3 MAIN LEVEL FLOOR FRAMING PLAN
  - S3 UPPER LEVEL FLOOR FRAMING PLAN
  - ROOF FRAMING PLAN
  - S380 ROOF PENETRATION DETAILS
  - S381-S388 DETAILS
  - E1 ELECTRICAL PLAN
  - E2 ELECTRICAL PLAN
  - S801 SCANDINAVIAN WALL SECTION (TYP.)



**DEFERRED  
SUBMITTAL ITEMS**

BUILDING CODES USED FOR DESIGN:  
IRC 2015 AS AMENDED BY THE STATE OF UTAH.


-FIRE SPRINKLER  
SYSTEM

-RADIANT HEATING  
SYSTEM

-FIREPLACE PRODUCT  
INFORMATION

-AIR LEAKAGE TEST AS  
PERFORMANCE METHOD  
(BLOWER DOOR TEST)  
CODE N1102.4.1.2

# Exhibit A: Building Plans





**INSTALLATION:**

- When possible, layout the slit fence 5 to 10 feet beyond the top of slope.
- Align the fence along the contour of slope as close as possible.
- When the ground is uneven, use machinery that will produce no more than the desired tolerances in the trench. Use machinery that will produce no more than the desired tolerances in the trench.
- Place posts 6 feet on center along contour (or use preassembled unit) and drive 2 inches into ground.
- Use fabric to required width, unroll along length of barrier and staple over barrier trench.
- Cut fabric to allow over lap, or overlap, with varying ridge extending into barrier trench.
- Buttlet trench over fabric to anchor.

**MAINTENANCE:**

- Inspect immediately after any rainfall and at least during prolonged rainfall.
- Repair or replace damaged areas within 72 hours.
- Repair or replace damaged areas within 72 hours and remove accumulated sediment.
- Repair or replace damaged areas within 72 hours and remove accumulated sediment.
- Remove accumulated sediment when it reaches 1/2 the height of the fence.



INSPECTION DESCRIPTION/REQUIREMENTS	CONTACT
<b>FOUNDATION</b> REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FOUNDATION TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOFING</b> REQUIRED: ROOF TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>FRONT WALL</b> REQUIRED: FRONT WALL TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FRONT WALL TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FRONT WALL TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FRONT WALL TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: FRONT WALL TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF DRAIN</b> REQUIRED: ROOF DRAIN TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF DRAIN TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF DRAIN TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF DRAIN TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF DRAIN TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING

INSPECTION DESCRIPTION/REQUIREMENTS	CONTACT
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF WATER</b> REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF WATER TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING
<b>ROOF SPRINGERS</b> REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER. REQUIRED: ROOF SPRINGERS TO BE INSURED BY A BUILDING ENGINEER.	ENGINEERING



**NOTE:**

1. ALL WORK IS TO BE DONE IN ACCORDANCE WITH THE 2018 INTERNATIONAL RESIDENTIAL CODE BOOK (IRC) AND THE 2018 INTERNATIONAL BUILDING CODE (IBC).

2. ALL WORK IS TO BE DONE IN ACCORDANCE WITH THE 2018 INTERNATIONAL RESIDENTIAL CODE BOOK (IRC) AND THE 2018 INTERNATIONAL BUILDING CODE (IBC).

3. ALL WORK IS TO BE DONE IN ACCORDANCE WITH THE 2018 INTERNATIONAL RESIDENTIAL CODE BOOK (IRC) AND THE 2018 INTERNATIONAL BUILDING CODE (IBC).

4. ALL WORK IS TO BE DONE IN ACCORDANCE WITH THE 2018 INTERNATIONAL RESIDENTIAL CODE BOOK (IRC) AND THE 2018 INTERNATIONAL BUILDING CODE (IBC).

5. ALL WORK IS TO BE DONE IN ACCORDANCE WITH THE 2018 INTERNATIONAL RESIDENTIAL CODE BOOK (IRC) AND THE 2018 INTERNATIONAL BUILDING CODE (IBC).

**SCANDINAVIA N LLC**

11

**BLAKE KINGSBURY AND MERRIT CHESSON**

Summit Powder Mountain, Lot # 70  
8492 E. Spring Park, Weber County, Utah

**SCANDINAVIA N LLC**


11

**SCANDINAVIA N LLC**





Page 6 of 98

# Exhibit A: Building Plans


## GLASS ELEMENT SIZE



## GLASS ELEMENT SIZE



1 ELEMENT FRAME ELEVATIONS  
SCALE: 1/4" = 1'-0"





OPERATION LEGEND FOR WINDOW & DOOR ONLY  
INSULATED CORE  
L - LEFT HANDED  
R - RIGHT HANDED  
B - BOTTOM HANDED WINDOW  
F - OPENED WINDOW  
C - CLOSED WINDOW  
O - OPERATION AREA BY SWP

SCANDINAVIAN WINDOW SCHEDULE										
ID	TYPE	Size (mm)	Size (Inches)	Opening type	Wall type	Wall thickness	Flashing	Screen	Notes	Quantity
W1	MSEI31A	180 x 150	70.9" x 59.1"	L+R	164	164		90x150	tempered	2
W2	MSEI31A	60 x 150	23.6" x 59.1"	(1)L, (2)R	164	164		60x150	tempered	3
W3	MSEI31A	110 x 120	43.3" x 47.2"	L	195	195		110x120	tempered	1
<b>TOTAL</b>										<b>6</b>

SCANDINAVIAN WINDOW SCHEDULE										
ID	TYPE	Size (mm)	Size (Inches)	Opening type	Wall type	Wall thickness	Flashing	Screen	Notes	Quantity
FW1	EKJ31A	170 x 240	66.9" x 94.5"	FIXED	164	164			tempered	1
FW2	EKJ31A	190 x 240	74.8" x 94.5"	FIXED	164	164			tempered	1
FW3	EKJ31A	160 x 150	63.0" x 59.1"	FIXED	164	164			tempered	1
FW4	EKJ31A	140 x 150	55.1" x 59.1"	FIXED	164	164			tempered	1
FW5	EKJ31A	120 x 240	47.2" x 90.6"	FIXED	164	164			tempered	1
FW6	EKJ31A	310 x 120	122.0" x 47.2"	FIXED	164	164			tempered (2590x1190/2000)	1
FW7	EKJ31A	260 x 200	102.4" x 78.7"	FIXED	164	164			625x(2005/0)	1
FW8	EKJ31A	63 x 200	24.8" x 78.7"	FIXED	164	164			625x(2005/0)	1
FW9	EKJ31A	310 x 210	122.0" x 82.7"	FIXED	164	164			2590x(2000/1190)	1
FW10	EKJ31A	63 x 200	24.8" x 78.7"	FIXED	164	164			2590x(2000/1190)	1
<b>TOTAL</b>										<b>11</b>

SCANDINAVIAN DOOR SCHEDULE										
ID	TYPE	Size (mm)	Size (Inches)	Opening type	Wall type	Wall thickness	Flashing	Screen	Notes	Quantity
SD1	SD	330 x 230	129.9" x 90.6"	(1)L, (1)R	195	195			tempered (sage) - TF-FRAME)	2
SD2	SD	200 x 240	78.7" x 94.5"	R	195	195			tempered	1
SD3	SD	360 x 230	141.7" x 90.6"	R	195	195			tempered	1
SD4	SD	300 x 230	118.1" x 90.6"	R	195	195			tempered	1
D1	IO	90 x 200	35.4" x 78.7"	R	195	195			tempered (opening inside)	1
<b>TOTAL</b>										<b>6</b>





2 TYP. WINDOW DTL #1  
SCALE: 1" = 1'-0"

3 TYP. GLASS ELEMENT DTL  
SCALE: 1" = 1'-0"



# Exhibit A: Building Plans





**A New Residence:**  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
Summit Powder Mountain, Lot # 70  
8492 E. Spring Park, Weber County, Utah





# Exhibit A: Building Plans




**A New Residence:**  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
 Summit Powder Mountain, Lot # 70  
 8492 E. Spring Park, Weber County, Utah


**SCANDINAVIAN N**  
**LLC**  
 Page 9 of 98

DATE	02-27-2018
SCALE	1/8" = 1'-0"
PROJECT	UPPER & ROOF LEVEL FLOORS
CLIENT	SCANDINAVIAN N, LLC
ARCHITECT	SCANDINAVIAN N, LLC
DRAWN BY	
CHECKED BY	
DATE	
DESCRIPTION	
DATE	
DESCRIPTION	


# Exhibit A: Building Plans




# Exhibit A: Building Plans




1 EAST BUILDING ELEVATION  
SCALE 1/4" = 1'-0"  
0 2 4 8



2 NORTH BUILDING ELEVATION  
SCALE 1/4" = 1'-0"  
0 2 4 8



3 SOUTH BUILDING ELEVATION  
SCALE 1/4" = 1'-0"  
0 2 4 8



4 WEST BUILDING ELEVATION  
SCALE 1/4" = 1'-0"  
0 2 4 8

NOTE: ALL ROOFING MATERIALS SHALL BE 12" MINIMUM THICKNESS UNLESS OTHERWISE NOTED.  
ALL ROOFING SHALL BE INSTALLED IN ACCORDANCE WITH THE MANUFACTURER'S INSTALLATION INSTRUCTIONS.  
THE ROOF SHALL BE FINISHED WITH A GRADE FINISH.


© COMMERCIAL 2018  
SCANDINAVIA N LLC  
1000 10TH AVENUE, SUITE 200  
DENVER, CO 80202  
TEL: 303.733.8800  
WWW.SCANDINAVIANLLC.COM

**BUILDING ELEVATIONS**  
DATE: 11/14/2018  
SCALE: 1/4" = 1'-0"  
DRAWN BY: [Name]  
CHECKED BY: [Name]

**A New Residence:**  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
Summit Powder Mountain, Lot #70  
8492 E. Spring Park, Weber County, Utah

**SCANDINAVIA N LLC**  
Page 11 of 98  
ARCHITECTURAL OFFICE  
1000 10TH AVENUE, SUITE 200  
DENVER, CO 80202  
TEL: 303.733.8800  
WWW.SCANDINAVIANLLC.COM

# Exhibit A: Building Plans



**1 BUILDING SECTION**  
 4:1 SCALE  
 0 2 4 8

STAIR BALUSTERS SHALL BE SPACED SO A 4" OBJECT CANNOT PASS BETWEEN.

SPACE UNDER THE STAIRS WILL BE PROTECTED WITH A MIN. 1/2" GYPSUM BOARD

- ROOF 1**
- WEATHERED STEEL ROOF PANELS
  - UNDEPLOYMENT
  - PLYWOOD 5/8" OSB
  - TJI 230 RAFTERS @16"O.C. (t.p.)
  - SEE ROOF FRAMING PLAN
  - \*R-49 BATT INSULATION
  - MOISTURE BARRIER
  - CEILING BOARDS

- ROOF 2**
- WEATHERED STEEL ROOF PANELS
  - UNDEPLOYMENT
  - PLYWOOD 5/8" OSB
  - TJI 230 RAFTERS @16"O.C. (t.p.)
  - SEE ROOF FRAMING PLAN
  - PLYWOOD 7/16"
  - TYVEK
  - 3/4" CEDAR SOFFIT

- FLOOR 1**
- FLOORING
  - 4" REINFORCED CONC. SLAB (WEILED WIRE FABRIC)
  - 6-MIL POLYETHENE VAPOR BARRIER
  - RIGID INSULATION 2" MINIMUM
  - COMPACTED GRANULAR BASE COURSE

- FLOOR 2**
- FLOORING
  - 3/4" OSB PLYWOOD SUBFLOOR
  - TJI 230 JOISTS @16"O.C. (t.p.)
  - \* SOUND INSULATION
  - CEILING BOARDS

- FLOOR 3**
- 1/4" TILE FLOORING
  - 1/4" WONDER BOARD & WATERPROOFING MEMBRANE
  - 3/4" OSB PLYWOOD SUBFLOOR
  - TJI 230 JOISTS @16"O.C. (t.p.)
  - PLYWOOD 7/16"
  - TYVEK
  - 3/4" CEDAR SOFFIT

- FLOOR 4**
- 1/4" TILE FLOORING
  - 1/4" WONDER BOARD & WATERPROOFING MEMBRANE
  - 3/4" OSB PLYWOOD SUBFLOOR
  - TJI 230 JOISTS @16"O.C. (t.p.)
  - SEE ROOF FRAMING PLAN
  - \*R-49 BATT INSULATION
  - MOISTURE BARRIER
  - CEILING BOARDS

- FLOOR 5**
- FLOORING
  - 3/4" OSB PLYWOOD SUBFLOOR
  - TJI 230 JOISTS @16"O.C. (t.p.)
  - SEE ROOF FRAMING PLAN
  - \*R-49 BATT INSULATION
  - PLYWOOD 7/16"
  - TYVEK
  - 3/4" CEDAR SOFFIT

ROOF LEVEL TOP OF PLYWOOD +8588-8-1/4"  
 UPPER LEVEL TOP OF PLYWOOD +8578-8"  
 MAIN LEVEL TOP OF PLYWOOD [F0-0] +8568-0"  
 GARAGE TOP OF SLAB +8557-6"

EXISTING GRADE


0 2 4 8

A New Residence:  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
 Summit Powder Mountain, Lot # 70  
 8492 E. Spring Park, Weber County, Utah





# Exhibit A: Building Plans



## 1 FOOTING AND FOUNDATION PLAN

1. FOUNDATION REINFORCEMENT SHALL BE CAST IN PLACE.
2. ALL WALLS AND FOUNDATIONS SHALL BE CONCRETE UNLESS NOTED OTHERWISE.
3. ALL WALLS AND FOUNDATIONS SHALL BE CAST IN PLACE.
4. ALL WALLS AND FOUNDATIONS SHALL BE CONCRETE UNLESS NOTED OTHERWISE.
5. ALL WALLS AND FOUNDATIONS SHALL BE CONCRETE UNLESS NOTED OTHERWISE.


ALL WALLS AND FOUNDATIONS SHALL BE CAST IN PLACE.

MARK	SIZE	LONG	SPACING	TRANS	REMARKS
WF1-S	18\"/>				
WF2-S	20\"/>				
WF3-S	24\"/>				
WF4-S	24\"/>				
WF5-S	24\"/>				
WF6-S	24\"/>				
WF7-S	24\"/>				
WF8-S	24\"/>				
F1-S	4\"/>				
F2-S	4\"/>				
F3-S	4\"/>				
F4-S	4\"/>				
F5-S	4\"/>				
F6-S	4\"/>				
F7-S	4\"/>				
F8-S	4\"/>				
F9-S	4\"/>				
F10-S	4\"/>				
F11-S	4\"/>				
F12-S	4\"/>				
F13-S	4\"/>				
F14-S	4\"/>				
F15-S	4\"/>				
F16-S	4\"/>				
F17-S	4\"/>				
F18-S	4\"/>				
F19-S	4\"/>				
F20-S	4\"/>				
F21-S	4\"/>				
F22-S	4\"/>				
F23-S	4\"/>				
F24-S	4\"/>				
F25-S	4\"/>				
F26-S	4\"/>				
F27-S	4\"/>				
F28-S	4\"/>				
F29-S	4\"/>				
F30-S	4\"/>				
F31-S	4\"/>				
F32-S	4\"/>				
F33-S	4\"/>				
F34-S	4\"/>				
F35-S	4\"/>				
F36-S	4\"/>				
F37-S	4\"/>				
F38-S	4\"/>				
F39-S	4\"/>				
F40-S	4\"/>				
F41-S	4\"/>				
F42-S	4\"/>				
F43-S	4\"/>				
F44-S	4\"/>				
F45-S	4\"/>				
F46-S	4\"/>				
F47-S	4\"/>				
F48-S	4\"/>				
F49-S	4\"/>				
F50-S	4\"/>				
F51-S	4\"/>				
F52-S	4\"/>				
F53-S	4\"/>				
F54-S	4\"/>				
F55-S	4\"/>				
F56-S	4\"/>				
F57-S	4\"/>				
F58-S	4\"/>				
F59-S	4\"/>				
F60-S	4\"/>				
F61-S	4\"/>				
F62-S	4\"/>				
F63-S	4\"/>				
F64-S	4\"/>				
F65-S	4\"/>				
F66-S	4\"/>				
F67-S	4\"/>				
F68-S	4\"/>				
F69-S	4\"/>				
F70-S	4\"/>				
F71-S	4\"/>				
F72-S	4\"/>				
F73-S	4\"/>				
F74-S	4\"/>				
F75-S	4\"/>				
F76-S	4\"/>				
F77-S	4\"/>				
F78-S	4\"/>				
F79-S	4\"/>				
F80-S	4\"/>				
F81-S	4\"/>				
F82-S	4\"/>				
F83-S	4\"/>				
F84-S	4\"/>				
F85-S	4\"/>				
F86-S	4\"/>				
F87-S	4\"/>				
F88-S	4\"/>				
F89-S	4\"/>				
F90-S	4\"/>				
F91-S	4\"/>				
F92-S	4\"/>				
F93-S	4\"/>				
F94-S	4\"/>				
F95-S	4\"/>				
F96-S	4\"/>				
F97-S	4\"/>				
F98-S	4\"/>				
F99-S	4\"/>				
F100-S	4\"/>				

### FOUNDATION WALL SCHEDULE

WALL TYPE	THICKNESS	BARS	DIMENSIONS	BARS	DIMENSIONS	CORNER
WF1	18"	#4 @ 18"	4# @ 18"	#4 @ 18"	#4 @ 18"	#4 @ 24"
WF2	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF3	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF4	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF5	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF6	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF7	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF8	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF9	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"
WF10	18"	#4 @ 12"	4# @ 12"	#4 @ 12"	#4 @ 12"	#4 @ 12"

- NOTE: ANCHOR BOLTS DO NOT ALWAYS OCCUR. SEE DETAILS.
- FOUNDATION PLAN NOTES:
1. ALLOWABLE SOIL PRESSURE USED IN DESIGN = 1500 PSF (ASSUMED) AND TO BE FIELD VERIFIED AS REQUIRED PER THE CITY BY A LICENSED GEOTECHNICAL ENGINEER BEFORE PROCEEDING WITH CONSTRUCTION.
  2. REFER TO ARCHITECTURAL PLAN FOR TOP OF SLAB ELEVATION DENOTED T.O.S.
  3. VERIFY WITH ARCHITECTURAL PLANS ALL STEPS IN SLAB.
  4. SLAB ON GRADE SHALL BE 4" CONCRETE OVER 4" FREE DRAINING GRAVEL. REINFORCE SLAB WITH #6 MAT 1' W/8" OR #4 MAT 2' ON EACH WAY UNLESS NOTED OTHERWISE.
  5. TO ACTUAL SITE ELEVATIONS AND CONDITIONS.
  6. FOOTING TYPES NOTED THIS PLAN AND W/8" REFER TO SCHEDULE FOR SIZE AND REINFORCEMENT. REFER TO PLAN AND SECTIONS FOR TOP OF FOOTING ELEVATION.
  7. CENTER FOOTINGS ON WALLS AND COLUMNS UNLESS DIMENSIONED OTHERWISE ON PLANS.
  8. "T.O.W." DENOTES TOP OF WALL ELEVATION.
  9. "T.O.F." DENOTES TOP OF FOOTING ELEVATION.
  10. W/S - DENOTES FOUNDATION WALL STEPS.
  11. "W" DENOTES FOUNDATION WALL TYPE.
  12. ALL FOUNDATIONS ARE TYPE "W" UNLESS NOTED OTHERWISE.
  13. "S" DENOTES FOOTING STEPS. REFER TO DETAIL G500.
  14. REFER TO GENERAL NOTES ON SHEET SO FOR ADDITIONAL INFORMATION.
  15. COLUMNS AND PRECAST CONCRETE ELEMENTS SHALL BE APPROXIMATE ALL FINAL GRADING SHALL BE FIELD VERIFIED.
  16. AROUND OPENINGS LARGER THAN 12" IN ANY DIRECTION IN CONCRETE WALLS, ADD (2) #4 BARS ALL SIDES IN ADDITION TO REGULAR WALL REINFORCING AND EXTEND 24" EACH WAY BEYOND OPENING. WHERE 24" IS NOT AVAILABLE, EXTEND BARS AS FAR AS POSSIBLE AND TERMINATE WITH A STANDARD HOOK.



## 2 LOWER LEVEL FRAMING PLAN

PROFESSIONAL SEAL

DATE: 10/11/2018

PROJECT: BLAKE KINGSBURY AND MERRIT CHESSON

ENGINEER: JAMES A. MERRITT

CONTRACTOR: SCANDINAVIA N LLC

10. ALL EXTERIOR SKIDPADS AND PROFILE WALLS SHALL BE TYPE "S" SHEAR WALL CONSTRUCTION UNLESS NOTED OTHERWISE.

### STEEL WALL SCHEDULE

TYPE	MATERIAL	PAINTING	ANCHORS	SECUREMENT	NOTES
SW1	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW2	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW3	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW4	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW5	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW6	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW7	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW8	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW9	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW10	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW11	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW12	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW13	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW14	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW15	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW16	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW17	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW18	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW19	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW20	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW21	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW22	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW23	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW24	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW25	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW26	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW27	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW28	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW29	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS
SW30	STEEL WALL	AS REQUIRED	AS NOTED	AS NOTED	SEE DETAILS FOR ANCHORS AND CONNECTIONS

### STUD HEIGHT CHART

STUD	HEIGHT	LOCATION
STUD 1	4'-0"	INTERIOR WALLS
STUD 2	8'-0"	INTERIOR WALLS
STUD 3	10'-0"	EXTERIOR WALLS
STUD 4	12'-0"	EXTERIOR WALLS
STUD 5	16'-0"	EXTERIOR WALLS

FOR THE MULTIPLE DIMENSIONS TOGETHER (DOT 282)

### FLOOR BEAM SCHEDULE

MARK	MATERIAL	SIZE	LOCATION
MB1	STEEL I-BEAM	12" x 10"	W/8
MB2	STEEL I-BEAM	12" x 10"	W/8
MB3	STEEL I-BEAM	12" x 10"	W/8
MB4	STEEL I-BEAM	12" x 10"	W/8
MB5	STEEL I-BEAM	12" x 10"	W/8


### WOOD JOIST SCHEDULE

MARK	TYPE	SIZE	SPACING
WJ1	2x6	16" O.C.	TYPICAL
WJ2	2x6	16" O.C.	TYPICAL
WJ3	2x6	16" O.C.	TYPICAL
WJ4	2x6	16" O.C.	TYPICAL
WJ5	2x6	16" O.C.	TYPICAL
WJ6	2x6	16" O.C.	TYPICAL
WJ7	2x6	16" O.C.	TYPICAL
WJ8	2x6	16" O.C.	TYPICAL
WJ9	2x6	16" O.C.	TYPICAL
WJ10	2x6	16" O.C.	TYPICAL




# Exhibit A: Building Plans

### SHEAR WALL SCHEDULE

TYPE	FINISH	BOLTS	SPACING	REINFORCING	REMARKS
W-1	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-2	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-3	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-4	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-5	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-6	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-7	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-8	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-9	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-10	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE



- #### REMARKS:
1. ALL STEEL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  2. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  3. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  4. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  5. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  6. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  7. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  8. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  9. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
  10. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.



### SHEAR WALL SCHEDULE

TYPE	FINISH	BOLTS	SPACING	REINFORCING	REMARKS
W-1	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-2	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-3	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-4	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-5	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-6	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-7	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-8	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-9	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE
W-10	TYPE 1	5/8" W/ 24"	36"	4# X 36"	ON PLAN SEE SCHEDULE

1. ALL STEEL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
2. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
3. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
4. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
5. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
6. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
7. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
8. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
9. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.
10. ALL WALL PARTS SHALL BE COMPRESSED BY THE END OF SHEAR WALLS.

### FLOOR BEAM SCHEDULE

MARK	GLULAM (FIN. LVL) BE. SPAN	REMARKS
MB01	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE
MB02	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE
MB03	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE
MB04	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE
MB05	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE
MB06	1.5X11 @ 12' 0" x 11' 2"	ON PLAN SEE SCHEDULE


### STUD HEIGHT CHART

STUD	GRADE	SEALING	MAX. HT.	LOCATION	NOTES
2-6	S-TUD	BE-SE	10'-0"	EXTERIOR	
2-6	S-TUD	BE-SE	10'-0"	EXTERIOR	
2-6	BE-SE	BE-SE	10'-0"	EXTERIOR	

1. ALL BEAMS TO BEAS CONTINUOUS OR TO CROSS OTHERS. LVL. ON PLAN.
2. ALL BEAMS TO BEAS CONTINUOUS OR TO CROSS OTHERS. LVL. ON PLAN.
3. SHEAR WALL TYPES AND LOCATION IS INDICATED THIS: **△** ON PLAN SEE SCHEDULE.
4. ALL INTERIOR WALLS SHALL BE TYPE **△** SHEAR WALL CONSTRUCTION.
5. ALL INTERIOR WALLS SHALL BE TYPE **△** SHEAR WALL CONSTRUCTION.
6. REFER TO GENERAL STRUCTURAL NOTES SHEET 9 FOR ADDITIONAL INFORMATION.
7. WHERE ROCK SHEAR OCCURS REFER TO DETAIL R6500.
8. SCANDINAVIAN ROOFING SHEAR WALL TYPES AND LOCATION ARE SHOWN THIS: **◇** ON PLAN SEE SCHEDULE.
9. SCANDINAVIAN ROOFING SHEAR WALL TYPES AND LOCATION ARE SHOWN THIS: **◇** ON PLAN SEE SCHEDULE.
10. ALL STEEPS SCANDINAVIAN PROFILE WALLS SHALL BE TYPE **◇** SHEAR WALL CONSTRUCTION.

### HOLD DOWNS

TYPE	NOTES	SPACING	SPACING	REMARKS
H-1	CONCRETE	18" X 18"	48"	ON PLAN SEE SCHEDULE
H-2	CONCRETE	18" X 18"	48"	ON PLAN SEE SCHEDULE
H-3	CONCRETE	18" X 18"	48"	ON PLAN SEE SCHEDULE
H-4	CONCRETE	18" X 18"	48"	ON PLAN SEE SCHEDULE
H-5	CONCRETE	18" X 18"	48"	ON PLAN SEE SCHEDULE



A New Residence:  
 BLAKE KINGSBURY AND MERRIT CHESSON  
 Summit Powder Mountain, Lot # 70  
 8492 E. Spring Park, Weber County, Utah



DATE: 02-27-2018

PROJECT: MAIN LEVEL FRAMING PLAN

CLIENT: BLAKE KINGSBURY AND MERRIT CHESSON

ARCHITECT: SCOTT A. HANSEN


SCALE: AS SHOWN

REVISIONS:

NO.	DATE	DESCRIPTION
1		ISSUED FOR PERMIT
2		
3		
4		
5		

# Exhibit A: Building Plans


## 1 UPPER LEVEL FRAMING PLAN




MARK	QUANTITY	TYPE	SPAN	BEAMS
MB1	1	GLULAM L10S-D	15'-0"	15'-0" x 15'
MB2	1	GLULAM L10S-D	6'-1 1/2"	6'-1 1/2" x 14'-4"
MB3	1	STEEL IWB x 68		
MB4	1	STEEL IWB x 40		
MB5	1	STEEL IWB x 58		
MB6	1	STEEL IWB x 58		
MB7	2	STEEL W8 x 21	14'-0"	14'-0" x 11'-7 1/2"
MB8	1	STEEL W8 x 21	6'-0"	6'-0" x 11'-7 1/2"
MB9	1	GLULAM L10S-D	6'-1 1/2"	6'-1 1/2" x 14'-4"

WALL	SECTION	DESCRIPTION	STARTING COURSE	ENDING COURSE
W1	1	8" CMU	1	1
W2	1	8" CMU	1	1

## 2 ROOF FRAMING PLAN



MARK	QUANTITY	TYPE	SPAN	BEAMS
R1	1	GLULAM L10S-D	11'-7 1/2"	11'-7 1/2" x 17'-6"
R2	1	GLULAM L10S-D	11'-7 1/2"	11'-7 1/2" x 17'-6"
R3	1	GLULAM L10S-D	11'-7 1/2"	11'-7 1/2" x 17'-6"











ROOFING:  
ICE BARRIER AT LEAST 24" INSIDE  
THE INSIDE THE EXTERIOR WALL LINE  
OF THE BUILDING. 1905.2.7.1

TYPE	MATERIAL	THICKNESS	REINFORCEMENT	REMARKS
W1	8" CMU	8"	#4 @ 16"	
W2	8" CMU	8"	#4 @ 16"	


STUD	GRADE	SECTION	MAX. ALLOWED HEIGHT
1	1	1	10'-0"
2	2	2	10'-0"

TYPE	MATERIAL	SIZE	HEIGHT	REMARKS
H1	1/2" A307	1/2"	3'	
H2	1/2" A307	1/2"	3'	





# Exhibit A: Building Plans



SCANDINAVIAN PROFILE (MIL 164)

MAXIMUM LENGTH	39 ft
MINIMUM LENGTH	1 ft
APPROXIMATE WEIGHT	14 lb / ft
LOG WALL INSTALLATION PER MANUFACTURER'S GUIDELINES AND INSTRUCTIONS	

THE CHARACTERISTIC VALUES FOR SCANDINAVIAN


MATERIAL	FB	Ft	Fv	FcT	FcII	MOE
SCOTCH SPRUCE (125), [P25]	1390	914	139	348	914	943000

THE CHARACTERISTIC VALUES FOR SCANDINAVIAN GLUE LAM BEAMS (L30), [P9]


MATERIAL	FB	Ft	Fv	FcT	FcII	MOE
SCOTCH SPRUCE	1741	1190	167	348	1190	1015965

DENSITY: 51.2 lb/ft<sup>3</sup> (MOISTURE CONTENT 12 %)


1 SCANDINAVIAN WALL PROFILE  
S307 SCALE: 1" = 1'-0"




5 TYPICAL GABLE END  
S307 SCALE: 1" = 1'-0"




7 TYPICAL EAVES DTL  
S307 SCALE: 1" = 1'-0"




3 TYPICAL CORNER DETAIL  
S307 SCALE: 1" = 1'-0"




4 TYPICAL COLUMN / BEAM DETAIL  
S307 SCALE: 1" = 1'-0"



8 FULL DEPTH TRUSS BLOCKING DETAIL  
S307 SCALE: 1" = 1'-0"




9 TRUSS AT SHEAR WALL  
S307 SCALE: 1" = 1'-0"




6 TYPICAL EAVES DTL  
S307 SCALE: 1" = 1'-0"

# Exhibit A: Building Plans



ALL FASTENERS (IE NAILS, SCREWS, ANCHOR BOLTS, ETC.) WHICH ARE TO BE INSTALLED IN PRESERVATIVE TREATED WOOD ARE TO BE CORROSION RESISTANT. (IE SILV. PAINT) SHALL MEET THE REQUIREMENTS OF SEC. 2304.10.5

1 TYP. MAIN HOUSE WALL SECTION  
SCALE: 1" = 1'-0"



ALL FASTENERS (IE NAILS, SCREWS, ANCHOR BOLTS, ETC.) WHICH ARE TO BE INSTALLED IN PRESERVATIVE TREATED WOOD ARE TO BE CORROSION RESISTANT. (IE SILV. PAINT) SHALL MEET THE REQUIREMENTS OF SEC. 2304.10.5

2 TYP. MAIN HOUSE WALL SECTION  
SCALE: 1" = 1'-0"

0 - COPYRIGHT 2018  
SCANDINAVIA N LLC  
1000 22ND AVENUE  
ALEXANDRIA, VA 22304  
703.555.1111


**A New Residence:**  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
Summit Powder Mountain, Lot # 70  
8492 E. Spring Park, Weber County, Utah

**SCANDINAVIA N LLC**  
Page 19 of 98

S302

WT-T 3/8" x 11 7/8" SCREWS = WT-T-8,2x300  
WT-T 3/8" x 6 1/4" SCREW = WT-T-8,2x160

# Exhibit A: Building Plans



ALL FASTENERS (IE NAILS, SCREWS, ANCHORS, BOLTS, ETC.) SHALL BE 304 STAINLESS STEEL OR PRESERVATIVE TREATED WOOD (IE SILL PLATES) SHALL MEET THE REQUIREMENTS OF WDC 17.03.005

**1** TIMBER FRAME WALL (TYPICAL)  
SCALE: 1" = 1'-0"



**A New Residence:**  
BLAKE KINGSBURY AND MERRIT CHESSON  
Summit Powder Mountain, Lot # 70  
8492 E. Spring Park, Weber County, Utah



REVISION	DATE	DESCRIPTION

DATE: 8-14-22  
SCALE: 1/8" = 1'-0"  
DETAILS


© CONCEPT 2018  
ALL RIGHTS RESERVED. NO PART OF THIS DOCUMENT IS TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF CONCEPT ARCHITECTURAL.



# Exhibit A: Building Plans





**A New Residence:**  
**BLAKE KINGSBURY AND MERRIT CHESSON**  
 Summit Powder Mountain, Lot # 70  
 8492 E. Spring Park, Utah



B 1

# Exhibit A: Building Plans



© SCANDINAVIA 2018  
 3490 W. 9000 S. SUITE 100, SALT LAKE CITY, UT 84119  
 801.973.3333



## A New Residence: BLAKE KINGSBURY AND MERRIT CHESSON

Summit Powder Mountain, Lot # 70  
 8492 E. Spring Park, Utah

**SCANDINAVIAN  
 LLC**

DATE	09-27-2018
SCALE	3/2" = 1'-0"
PROJECT	BLAKE KINGSBURY AND MERRIT CHESSON
OWNER	BLAKE KINGSBURY AND MERRIT CHESSON
DESIGNER	SCANDINAVIAN LLC
ARCHITECT	SCANDINAVIAN LLC
ENGINEER	SCANDINAVIAN LLC
CONTRACTOR	

ARCHITECT/OWNER OFFICE	
OWNER NAME	
ADDRESS	
CITY	
STATE	
ZIP	
PHONE	
CUSTOMER	
DATE	





14425 South Center Point Way Bluffdale, Utah 84065  
Phone (801) 501-0583 | Fax (801) 501-0584

**Geotechnical Investigation**  
**Lot 70R – Summit Eden Phase 1C Development**  
**8492 East Spring Park**  
**Weber County, Utah**

GeoStrata Job No. 594-004

July 11, 2018

Prepared for:

**Jake Vainio**  
**435-513-0990**  
**jakev@myscandinavian.com**  
**Scandinavian Homes**  
**6410 North Business Loop Road Unit E**  
**Park City, Utah**



Learn More

Exhibit B: Geotechnical Report



Prepared for:

Jake Vainio  
Scandinavian Homes  
6410 North Business Loop Road, Unit E  
Park City, Utah

**Geotechnical Investigation**  
**Lot 70R – Summit Eden Phase 1C Development**  
**8492 East Spring Park**  
**Weber County, Utah**

GeoStrata Job No. 594-004

Prepared by:



---

J. Scott Seal, P.E.  
Associate Engineer

---

Daniel J. Brown, P.E.  
Senior Geotechnical Engineer

**GeoStrata**  
14425 South Center Point Way  
Bluffdale, UT 84065  
(801) 501-0583

July 11, 2018



**TABLE OF CONTENTS**

**1.0 EXECUTIVE SUMMARY .....1**

**2.0 INTRODUCTION.....3**

    2.1 PURPOSE AND SCOPE OF WORK .....3

    2.2 PROJECT DESCRIPTION.....3

**3.0 METHODS OF STUDY .....4**

    3.1 LITERATURE REVIEW .....4

    3.2 FIELD INVESTIGATION.....4

    3.3 LABORATORY INVESTIGATION.....4

    3.4 ENGINEERING ANALYSIS .....5

**4.0 GENERALIZED SITE CONDITIONS .....6**

    4.1 SURFACE CONDITIONS .....6

    4.2 SUBSURFACE CONDITIONS .....6

        4.2.1 Soils .....6

        4.2.2 Groundwater .....7

**5.0 GEOLOGIC CONDITIONS.....8**

    5.1 GEOLOGIC SETTING.....8

**6.0 ENGINEERING CONCLUSIONS AND RECOMMENDATIONS.....9**

    6.1 GENERAL CONCLUSIONS .....9

    6.2 EARTHWORK.....9

        6.2.1 General Site Preparation and Grading .....9

        6.2.2 Excavation Stability .....10

        6.2.3 Soft Soil Stabilization .....10

        6.2.4 Structural Fill and Compaction.....11

    6.3 FOUNDATIONS .....12

    6.4 SLOPE STABILITY .....13

    6.5 FOUNDATION DRAINAGE.....14

    6.6 CONCRETE SLAB-ON-GRADE CONSTRUCTION .....14

    6.7 EARTH PRESSURES AND LATERAL RESISTANCE .....14

    6.8 MOISTURE PROTECTION AND SURFACE DRAINAGE.....16

**7.0 CLOSURE .....17**

    7.1 LIMITATIONS .....17

    7.2 ADDITIONAL SERVICES .....17

**8.0 REFERENCES CITED .....19**

# Exhibit B: Geotechnical Report

## APPENDICES

### Appendix A

Plate A-1 .....Site Vicinity Map

Plate A-2 .....Exploration Location Map

### Appendix B

Plate B-1 to B-2 .....Test Pit Logs

Plate B-3.....Key to Soil Symbols and Terminology

### Appendix C

Plate C-1.....Summary of Laboratory Test Results Table

Plate C-2.....Atterberg Limits Test Results

Plate C-3.....Grain-Size Distribution Test Results

Plate C-4.....Direct Shear Test Results

### Appendix D

Slope Stability Results

# Exhibit B: Geotechnical Report

## **1.0 EXECUTIVE SUMMARY**

This report presents the results of a geotechnical investigation conducted for the proposed residential structure to be constructed on Lot 70R of the Summit Eden Phase 1C development located in Weber County, Utah. The purposes of this investigation were to assess the nature and engineering properties of the subsurface soils at the site and to provide recommendations for general site grading and the design and construction of foundations, slab-on-grades, and exterior concrete flatwork.

Based on the results of our geotechnical laboratory testing, it is our opinion that the site is suitable for the proposed development provided that the recommendations contained in this report are incorporated into the design and construction of the project.

Subsurface soils were investigated through the advancement of a single exploratory trench excavated to a depth ranging from of 5½ to 9 feet below the existing site grade. Two soil profiles exposed in our trench were logged as test pits, TP-1 and TP-2. The soils encountered within our test pits at the site generally consisted of 6-inches of sandy topsoil overlying sediments that have been mapped as consisting of the Tertiary Wasatch Formation. Where observed, these sediments consisted of dense, moist, red-brown Silty GRAVEL (GM) with sand, Poorly Graded GRAVEL (GP-GM) with silt, sand, cobbles and boulders, and Poorly Graded SAND (SP-SM) with silt. Gravels, cobbles and boulders were typically subrounded to rounded, and had a maximum observed diameter of approximately 7 inches. Considering the rounded nature of the cobbles, it is considered possible that these sediments actually represent a unit of alluvial deposits. Groundwater was not encountered in any of the test pits completed for this investigation, and is not expected to impact the development, although strategic site grading should be implemented in order to account for potential perched groundwater units during spring months.

The foundation for the proposed structure may consist of conventional strip footings founded entirely on undisturbed native soils or entirely on bedrock (if exposed). If footing excavations expose a combination of soil and bedrock, the bedrock should be over-excavated at least 18 inches to allow placement of 18 inches of structural fill to limit the potential for differential settlement. We recommend that a GeoStrata representative observe all foundation soils in footing excavations prior to placing reinforcing steel or concrete. Conventional continuous/spread footings may be proportioned using a maximum net allowable bearing pressure of **1,700 pounds per square foot (psf)** for dead plus live load conditions.

## Exhibit B: Geotechnical Report

Due to the possibility of moisture reaching the foundation elements during spring runoff, it is recommended that a foundation drain be constructed around the proposed residence.

**NOTE: The scope of services provided within this report are limited to the assessment of the subsurface conditions at the subject site. The executive summary is provided solely for purposes of overview and is not intended to replace the report of which it is part and should not be used separately from the report.**

# Exhibit B: Geotechnical Report

## 2.0 INTRODUCTION

### 2.1 PURPOSE AND SCOPE OF WORK

This report presents the results of a geotechnical investigation conducted for the proposed residential structure to be constructed on Lot 70R of the Summit Eden Phase 1C located at approximately 8492 East Spring Park in Weber County, Utah. The purposes of this investigation were to assess the nature and engineering properties of the subsurface soils at the site and to provide recommendations for general site grading and the design and construction of foundations, slab-on-grades, and exterior concrete flatwork.

The scope of work completed for this study included a site reconnaissance, subsurface exploration, soil sampling, laboratory testing, engineering analyses, and preparation of this report. Our services were performed in accordance with our proposal, dated September 9, 2016 and your signed authorization.

The recommendations contained in this report are subject to the limitations presented in the "Limitations" section of this report (Section 7.1).

### 2.2 PROJECT DESCRIPTION

The subject lot is located at approximately 8492 East Spring Park, approximately 600 feet east of the intersection of Copper Crest Drive and Summit Pass Drive in unincorporated Weber County, Utah (see Plate A-1, *Site Vicinity Map*). Our understanding of the proposed development is based on information provided by the client. We understand that the development will consist of the construction of a single family residential structure with associated driveway and landscaping on the lot, which has a total area of approximately 0.064 acres. Construction plans were not available for review at the time report was prepared; however, we anticipate that the proposed structure will consist of one to two story wood-framed building with a basement founded on conventional strip footings.

It should also be noted that GeoStrata is concurrently completing a geologic hazards assessment for the subject lot. The results of that study will be summarized in a separate report.



## Exhibit B: Geotechnical Report

### 3.0 METHODS OF STUDY

#### 3.1 LITERATURE REVIEW

In preparation of this report, we have reviewed geologic hazards maps created by the Utah Geologic Survey (UGS) for Weber County. These maps include surficial geologic maps completed by Coogan and others (2001) for the Ogden 30' by 60' Quadrangle. Based on our review of these maps, the subject site is underlain by bedrock composed of the Tertiary-aged Wasatch Formation, although numerous young landslides are mapped in areas adjacent to the subject lot. As such, a slope stability analysis is included as part of this investigation.

#### 3.2 FIELD INVESTIGATION

As a part of this investigation, subsurface soil conditions were explored by excavating a trench across the full width of the property. This trench extended to depths ranging from 5½ feet to 9 feet in depth. Two locations along the profile of the trench were logged as test pits for the purposes of this geotechnical investigation, although a full log of the trench was completed as part of our geologic hazards assessment. The approximate locations of the explorations are shown on the *Exploration Location Map*, Plate A-2 in Appendix A. Subsurface soil conditions as encountered in the explorations were logged at the time of our investigation by qualified personnel and are presented on the enclosed Test Pit Logs, Plates B-1 and B-2 in Appendix B. A *Key to Soil Symbols and Terminology* is presented on Plate B-3.

The trench was excavated with a trackhoe. Bulk soil samples were obtained in the test pit explorations which were transported to our laboratory for testing to evaluate engineering properties of the various earth materials observed. Due to the granular nature of the exposed soils, it was not feasible to obtain relatively 'undisturbed' soil samples. The soils were classified according to the *Unified Soil Classification System* (USCS) by the Geotechnical Engineer. Classifications for the individual soil units are shown on the attached Test Pit Logs.

#### 3.3 LABORATORY INVESTIGATION

Geotechnical laboratory tests were conducted on selected soil samples obtained during our field investigation. The laboratory testing program was designed to evaluate the engineering characteristics of onsite earth materials. Laboratory tests conducted during this investigation include:

## Exhibit B: Geotechnical Report

- Grain Size Distribution Analysis (ASTM D422)
- Atterberg Limits Test (ASTM D4318)
- Direct Shear Test (ASTM D3080)

The results of laboratory tests are presented on the test pit logs in Appendix B (Plates B-1 and B-2), the Lab Summary Report (Plate C-1), on the test result plates presented in Appendix C (Plates C-2 to C-4) and the slope stability analysis in Appendix D (Plates D-1 and D-2).

### 3.4 ENGINEERING ANALYSIS

Engineering analyses were performed using soil data obtained from the laboratory test results and empirical correlations from material density, depositional characteristics and classification. Appropriate factors of safety were applied to the results consistent with industry standards and the accepted standard of care.

Excavation stability was evaluated based on the field conditions encountered, laboratory test results, and soil type. Occupational Safety and Health (OSHA) minimum requirements are typically prescribed unless conditions warrant further flattening of excavation walls.

## Exhibit B: Geotechnical Report

### 4.0 GENERALIZED SITE CONDITIONS

#### 4.1 SURFACE CONDITIONS

The site is in a relatively natural state and is currently heavily vegetated with brush and grasses. The lot slopes upward moderately to the north at an approximate 4H:1V slope. The property sits at an elevation ranging from 8,560 to 8,600 feet above sea level with a total topographic relief of approximately 40 feet. No structures or other improvements were observed on the subject property at the time of our investigation.

#### 4.2 SUBSURFACE CONDITIONS

As previously discussed, the subsurface soil conditions were explored at the site by excavating a trench across the subject lot. The test trench extended to depths ranging from 5½ to 9 feet below existing site grade. The soils encountered in the test pit explorations were visually classified and logged during our field investigation and are included on the test pit logs in Appendix B (Plates B-1 and B-2). The subsurface conditions encountered during our investigation are discussed below.

##### 4.2.1 Soils

Based on our observations, the subject site is overlain by approximately 6-inches of sandy topsoil. Underlying the topsoil, we encountered units that are mapped consisting of highly- to completely-weathered exposures of the Tertiary-aged Wasatch Formation, however occasional cobbles and boulders with a sub-rounded to rounded nature were observed throughout this unit. This suggests that the material encountered may consist of an alluvial deposit. This unit persisted for the full depth of our investigation.

Topsoil: Generally consists of dark brown Silty SAND (SM) with gravel, cobbles, and boulders. This unit has an organic appearance and texture with roots throughout. Topsoil was encountered along the full profile exposed during our trenching activities and is anticipated to overlie the majority of the site.

Tertiary-aged Wasatch Formation: Where observed, this unit consisted of granular material, and could represent either highly- to completely-weathered bedrock unit or an alluvial unit. From an engineering perspective, this unit consists of a dense, moist, red-brown to brown Silty GRAVEL

## Exhibit B: Geotechnical Report

(GM) with sand, Poorly Graded GRAVEL (GP-GM), with silt, cobble, and boulders, and Poorly Graded SAND (SP-SM) with silt and gravel. In general, the gravel, cobbles and boulders were subrounded to rounded, and had a maximum observed diameter of approximately 7-inches. The Wasatch Formation in this area is mapped by Coogan and others (2001) as consisting of “brown-red siltstone, sandstone, mudstone, and conglomerate with minor grey limestone and marlstone”. These deposits persisted to the full depth of our investigation.

The stratification lines shown on the enclosed test pit logs represent the approximate boundary between soil types (Plates B-1 and B-2). The actual in-situ transition may be gradual. Due to the nature and depositional characteristics of the native soils, care should be taken in interpolating subsurface conditions between and beyond the exploration locations.

### 4.2.2 Groundwater

Groundwater was not encountered in any of the test pits excavated as part of our investigation, and is anticipated to be relatively deep; however, due to the alpine location of the subject lot, localized near perched groundwater may occur during the spring months. Fluctuations in the groundwater level should be expected over time.

### 5.0 GEOLOGIC CONDITIONS

#### 5.1 GEOLOGIC SETTING

The site is located at an elevation ranging from approximately 8,560 to 8,600 feet above mean sea level within the James-Sharp Mountain area located at the southern part of the Bear River Range, Utah, which itself is located in the Middle Rocky Mountain province. James Peak is a structural high between the Cache Valley graben to the north and the Ogden Valley graben to the south. Sharp Mountain, on the other hand, is within the main part of the Bear River Range. The Bear River Range is formed from Paleozoic rocks that are broadly and gently folded. A major syncline and major anticline, trending north-northeast to northeast, were identified in the 30-minute Logan Quadrangle. Ogden Valley and the surrounding areas are underlain by rocks that range in age from Precambrian to Quaternary. The Precambrian rocks are mainly metasedimentary. Carbonate rocks predominate in the Paleozoic sequence, whereas deposits of Cenozoic age are predominately alluvial in origin. At its highest stage of about 5,090 feet (Blau, 1975) Pleistocene Lake Bonneville extended into Ogden Valley through Ogden Canyon. Unconsolidated lacustrine sediments undoubtedly were deposited in the valley.

Additional information concerning the geologic nature and condition of the subject property may be found in our Geologic Hazards Assessment concurrently being completed by GeoStrata.



### **6.0 ENGINEERING CONCLUSIONS AND RECOMMENDATIONS**

#### **6.1 GENERAL CONCLUSIONS**

Based on the geotechnical soils testing results, it is our opinion that the soils at the subject site are suitable for the proposed construction provided that the recommendations contained in this report are complied with. The recommendations presented in this report are based on our understanding of the proposed project, the subsurface conditions observed during field exploration, the results of laboratory testing, and our engineering analyses. If subsurface conditions other than those described herein are encountered in conjunction with construction, and/or if design and layout changes are initiated, we must be informed so that the recommendations herein can be reviewed and revised as changes or conditions may require.

#### **6.2 EARTHWORK**

Prior to the placement of foundations, general site grading is recommended to provide proper support for foundations, exterior concrete flatwork, and concrete slab-on-grade. Site grading is also recommended to provide proper drainage and moisture control on the subject property and to aid in preventing differential settlement of foundations as a result of variations in subgrade moisture conditions.

##### **6.2.1 General Site Preparation and Grading**

In areas beneath footings and concrete flat work, topsoil should be stripped and stockpiled for use in landscape areas or disposal. Debris, undocumented fill, vegetation, roots (including tree roots), loose, soft or other deleterious materials should also be removed and replaced with structural fill. If over-excavation is required, the excavation should extend a minimum of one foot laterally for every foot of depth of over-excavation. Excavations should extend laterally at least two feet beyond flatwork, pavements, and slabs-on-grade. If materials are encountered that are not represented in the test pit logs or may present a concern, GeoStrata should be notified so observations and further recommendations as required can be made. The exposed native soils should then be proof-rolled with heavy rubber-tired equipment. If soft soils are observed, they should be stabilized in accordance with our recommendations in the Soft Soil Stabilization Section (Section 6.2.3); if loose soils are observed, they should be compacted as recommended in Section 6.2.4.

## Exhibit B: Geotechnical Report

### 6.2.2 Excavation Stability

Based on Occupational Safety and Health Administration (OSHA) guidelines for excavation safety, trenches with vertical walls up to 5 feet in depth may be occupied, however, the presence of fill soils, loose soils, or wet soils may require that the walls be flattened to maintain safe working conditions. When the trench is deeper than 5 feet, we recommend a trench-shield or shoring be used as a protective system to workers in the trench. Based on our soil observations, laboratory testing, and OSHA guidelines, native soils at the site classify as Type C soils. Deeper excavations, if required, should be constructed with side slopes no steeper than one and one half horizontal to one vertical (1.5H:1V). If wet conditions are encountered, side slopes should be further flattened to maintain slope stability. Alternatively, shoring or trench boxes may be used to improve safe work conditions in trenches. The contractor is ultimately responsible for trench and site safety. Pertinent OSHA requirements should be met to provide a safe work environment. If site specific conditions arise that require engineering analysis in accordance with OSHA regulations, GeoStrata can respond and provide recommendations as needed.

We recommend that a GeoStrata representative be on-site during all excavations to assess the exposed foundation soils. We also recommend that the Geotechnical Engineer be allowed to review the grading plans when they are prepared in order to evaluate their compatibility with these recommendations.

### 6.2.3 Soft Soil Stabilization

Although not anticipated, soft or pumping soils may be exposed in excavations at the site. Once exposed, all subgrade surfaces beneath proposed structure, pavements, and flat work concrete should be proof rolled with heavy wheeled-construction equipment. If soft or pumping soils are encountered, these soils should be stabilized prior to construction of footings. Stabilization of the subgrade soils can be accomplished using a clean, coarse angular material worked into the soft subgrade. We recommend the material be greater than 2-inch diameter, but less than 6 inches. A locally available pit-run gravel may be suitable but should contain a high percentage of particles larger than 2 inches and have less than 7 percent fines (material passing the No. 200 sieve). A pit-run gravel may not be as effective as a coarse, angular material in stabilizing the soft soils and may require more material and greater effort. The stabilization material should be worked (pushed) into the soft subgrade soils until a firm relatively unyielding surface is established. Once a firm, relatively unyielding surface is achieved, the area may be brought to final design grade using structural fill.

## Exhibit B: Geotechnical Report

In large areas of soft subgrade soils, stabilization of the subgrade may not be practical using the method outlined above. In these areas it may be more economical to place a woven geotextile fabric against the soft soils covered by 18 inches of coarse, sub-rounded to rounded material over the woven geotextile. An inexpensive non-woven geotextile “filter” fabric should also be placed over the top of the coarse, sub-rounded to rounded fill prior to placing structural fill or pavement section soils to reduce infiltration of fines from above. The woven geotextile should be Amoco 2004 or prior approved equivalent. The filter fabric should consist of an Amoco 4506, Amoco 4508, or equivalent as approved by the Geotechnical Engineer.

### 6.2.4 Structural Fill and Compaction

All fill placed for the support of the structure or flatwork concrete should consist of structural fill. Structural fill may consist of native, granular soils provided it is first screened to remove debris, vegetation, and material exceeding 4-inches in nominal diameter. Alternatively, structural fill may consist of an imported granular soil with maximum fines content (minus No.200 mesh sieve) of 30 percent. All structural fill should be free of vegetation and debris and contain no materials larger than 3-inches in nominal size. All structural fill soils should be approved by the Geotechnical Engineer prior to placement. Clay and silt particles in imported structural fill should have a liquid limit less than 35 and a plasticity index less than 15 based on the Atterberg Limit’s test (ASTM D-4318). The contractor should have confidence that the anticipated method of compaction will be suitable for the type of structural fill used. The contractor should anticipate testing all soils used as structural fill frequently to assess the maximum dry density, fines content, and moisture content, etc.

All structural fill should be placed in maximum 6-inch loose lifts if compacted by small hand-operated compaction equipment, maximum 8-inch loose lifts if compacted by light-duty rollers, and maximum 12-inch loose lifts if compacted by heavy duty compaction equipment that is capable of efficiently compacting the entire thickness of the lift. We recommend that all structural fill be compacted on a horizontal plane, unless otherwise approved by the geotechnical engineer. Structural fill with an overall thickness of 6 feet or less should be compacted to at least 95% of the maximum dry density (MDD), as determined by ASTM D-1557 (modified proctor). The moisture content should be within 3% of the optimum moisture content (OMC) at the time of placement and compaction. Also, prior to placing any fill, the excavations should be observed by the geotechnical engineer to observe that any unsuitable materials or loose soils have been

## Exhibit B-Geotechnical Report

removed. In addition, proper grading should precede placement of fill, as described in the *General Site Preparation and Grading* subsection of this report (Section 6.2.1).

Fill soils placed for subgrade below exterior flat work should be within 3% of the OMC when placed and compacted to at least 95% of the MDD as determined by ASTM D-1557. All utility trenches backfilled below the proposed structure, pavements, and flatwork concrete, should be backfilled with structural fill that is within 3% of the OMC when placed and compacted to at least 95% of the MDD as determined by ASTM D-1557. All other trenches, in landscape areas, should be backfilled and compacted to at least 90% of the MDD (ASTM D-1557).

The gradation, placement, moisture, and compaction recommendations contained in this section meet our minimum requirements but may not meet the requirements of other governing agencies such as city, county, or state entities. If their requirements exceed our recommendations, their specifications should override those presented in this report.

### 6.3 FOUNDATIONS

Due to the type of investigation performed, soil strength and stiffness parameters were estimated using conservative values to estimate the bearing capacity and settlement. The foundation for the proposed structure may consist of conventional strip footings founded entirely on undisturbed native soils or entirely on bedrock. If footing excavations expose a combination of soil and bedrock, the bedrock should be over-excavated at least 18 inches to allow placement of 18 inches of structural fill to limit the potential for differential settlement. Strip footings should be a minimum of 20-inches wide and exterior shallow footings should be embedded at least 36-inches below final grade for frost protection and confinement. Interior footings not subject to frost should be embedded at least 18 inches below final grade to provide confinement. To provide adequate support and confinement, we recommend that footings be placed at least 15 feet, measured horizontally, from the face of existing or fill slopes at the site.

Conventional strip footings founded entirely on native soils or on properly compacted structural fill may be proportioned for a maximum net allowable bearing capacity of **1,700 psf**. The net allowable bearing capacity may be increased (typically by one-third) for temporary loading conditions such as transient wind and seismic loads. All footing excavations should be observed by the Geotechnical Engineer prior to footing placement.

## Exhibit B-Geotechnical Report

Settlements of properly designed and constructed conventional footings, founded as described above, are anticipated to be less than 1 inch. Differential settlements should be on the order of half the total settlement over 30 feet.

### 6.4 SLOPE STABILITY

The global stability of Lot 70R was modeled using the SLIDE computer application and the Janbu's Corrected Method of analysis. Calculations for stability were developed by searching for the minimum factor of safety for a circular-type and user-defined slope parallel failure surfaces. Homogenous earth materials and arcuate failure surfaces were assumed. The profile for the lot was obtained from ARC GIS data. A surcharge of approximately 1,700 psf was applied to our model within the anticipated vicinity of the residence. Slope stability was performed for the static and pseudo-static conditions. The pseudo-static assessment used one half of the peak ground acceleration of 0.35g as presented in Section 6.1 of our Geologic Hazards Assessment Report. Groundwater is presumed to be relatively deep and was not incorporated into the model.

Our slope stability model consists of two soil layers parallel to the surface profile. The first layer is a 1-foot thick unit of topsoil mantling the property, which is underlain by a unit of highly- to completely-weathered bedrock/alluvial deposits. The following strength parameters were applied to our model;

**Soil Strength Parameters**

<b>Soil Type</b>	<b>Friction Angle (phi) (degrees)</b>	<b>Cohesion (psf)</b>
Topsoil*	30	100
Bedrock/Alluvium**	26	260

\* assumed value

\*\* laboratory obtained value

The strength parameters for the bedrock/alluvial deposits was increased to consist of a friction angle of 34 degrees and a cohesion of 50 psf to account for the fact that the material consisted of approximately 63% gravel, which was screened from our sample prior to testing. As such, it is considered likely that the results of our direct shear testing significantly underestimate the actual strength of the soils present at the site. Groundwater was not encountered during our field investigations and is anticipated to be located at a relatively great depth. As such, groundwater was not incorporated into our slope stability modeling. Slopes with factors of safety of 1.5 and



## Exhibit B-Geotechnical Report

1.0 for static and pseudo-static conditions, respectively, are considered stable. The analyses performed for this report indicated that the site has a static factor of safety of 2.5 and a pseudo static factor of safety of 1.56.

### 6.5 FOUNDATION DRAINAGE

Due to the possibility of moisture reaching the foundation elements during spring runoff, it is recommended that a foundation drain be constructed around any subgrade walls. The foundation drain should consist of a 4-inch perforated pipe placed at or below the footing elevation. The pipe should be covered with at least 12 inches of free draining gravel (containing less than 5 percent passing the No 4 sieve) and be graded to a free gravity out fall or to a pumped sump. A separator fabric, such as Mirafi 140N, should separate the free draining gravel and native soil (i.e. the separator fabric should be placed between the gravel and the native soils at the bottom of the gravel, the side of the gravel where the gravel does not lie against the concrete footing or foundation and at the top of the gravel). We recommend that the gravel extend up the foundation wall to within 3 feet of the final ground surface. As an alternative, the gravel extending up the foundation wall may be replaced with a prefabricated drain panel, such as Ecodrain-E.

### 6.6 CONCRETE SLAB-ON-GRADE CONSTRUCTION

Concrete slabs-on-grade should be constructed over at least 4 inches of compacted gravel overlying undisturbed native soil or a zone of structural fill that is at least 12 inches thick. Disturbed native soils should be compacted to at least 95% of the MDD as determined by ASTM D-1557 (modified proctor) prior to placement of gravel. The gravel should consist of road base or clean drain rock with a ¾-inch maximum particle size and no more than 12 percent fines passing the No. 200 mesh sieve. The gravel layer should be compacted to at least 95 percent of the MDD of modified proctor or until tight and relatively unyielding if the material is non-proctorable. The maximum load on the floor slab should not exceed 300 psf; greater loads would require additional subgrade preparation and additional structural fill. All concrete slabs should be designed to minimize cracking as a result of shrinkage. Consideration should be given to reinforcing the slab with welded wire, re-bar, or fiber mesh.

### 6.7 EARTH PRESSURES AND LATERAL RESISTANCE

Lateral forces imposed upon conventional foundations due to wind or seismic forces may be resisted by the development of passive earth pressures and friction between the base of the

## Exhibit B-Geotechnical Report

footing and the supporting soils. In determining the frictional resistance against concrete, a coefficient of friction of 0.44 for native granular soils should be used.

Ultimate lateral earth pressures from natural soils and *granular* backfill acting against retaining walls and buried structures may be computed from the lateral pressure coefficients or equivalent fluid densities presented in the following table:

<b>Condition</b>	<b>Lateral Pressure Coefficient</b>	<b>Equivalent Fluid Density</b>
		<b>(pounds per cubic foot)</b>
Active*	0.25	31
At-rest**	0.44	53
Passive*	8.95	1074
Seismic Active***	0.31	37
Seismic Passive***	-2.45	-294

\* Based on Coulomb's equation

\*\* Based on Jaky

\*\*\* Based on Mononobe-Okabe Equation

These coefficients and densities assume level, granular backfill with no buildup of hydrostatic pressures. The force of the water should be added to the presented values if hydrostatic pressures are anticipated. If sloping backfill is present, we recommend the geotechnical engineer be consulted to provide more accurate lateral pressure parameters once the design geometry is established.

Walls and structures allowed to rotate slightly should use the active condition. If the element is constrained against rotation, the at-rest condition should be used. These values should be used with an appropriate factor of safety against overturning and sliding. A value of 1.5 is typically used. Additionally, if passive resistance is calculated in conjunction with frictional resistance, the passive resistance should be reduced by ½.

For seismic analyses, the *active* and *passive* earth pressure coefficient provided in the table is based on the Mononobe-Okabe pseudo-static approach and only accounts for the dynamic horizontal thrust produced by ground motion. Hence, the resulting dynamic thrust pressure *should be added* to the static pressure to determine the total pressure on the wall. The pressure distribution of the dynamic horizontal thrust may be closely approximated as an inverted triangle with stress decreasing with depth and the resultant acting at a distance approximately 0.6 times the loaded height of the structure, measured upward from the bottom of the structure.

## Exhibit B-Geotechnical Report

The coefficients shown assume a vertical wall face. Hydrostatic and surcharge loadings, if any, should be added. Over-compaction behind walls should be avoided. Resisting passive earth pressure from soils subject to frost or heave, or otherwise above prescribed minimum depths of embedment, should usually be neglected in design.

### 6.8 MOISTURE PROTECTION AND SURFACE DRAINAGE

Precautions should be taken during and after construction to minimize the potential for saturation of foundation soils. Over wetting the soils prior to or during construction may result in increased softening and pumping, causing equipment mobility problems and difficulty in achieving compaction.

Infiltrate of moisture in the vicinity of structures should be minimized. We recommend that roof runoff devices be installed to direct all runoff a minimum of 10 feet away from structures. The grade within 10 feet of the structures should be sloped a minimum of 5% away from the structure in accordance with the IBC, 2015.

## 7.0 CLOSURE

### 7.1 LIMITATIONS

The recommendations contained in this report are based on our limited field exploration, laboratory testing, and understanding of the proposed construction. The subsurface data used in the preparation of this report were obtained from the explorations made for this investigation. It is possible that variations in the soil and groundwater conditions could exist between the points explored. The nature and extent of variations may not be evident until construction occurs. If any conditions are encountered at this site that are different from those described in this report, we should be immediately notified so that we may make any necessary revisions to recommendations contained in this report. In addition, if the scope of the proposed construction changes from that described in this report, GeoStrata should be notified.

This report was prepared in accordance with the generally accepted standard of practice at the time the report was written. No warranty, expressed or implied, is made.

It is the Client's responsibility to see that all parties to the project including the Designer, Contractor, Subcontractors, etc. are made aware of this report in its entirety. The use of information contained in this report for bidding purposes should be done at the Contractor's option and risk.

### 7.2 ADDITIONAL SERVICES

The recommendations made in this report are based on the assumption that an adequate program of tests and observations will be made during construction. GeoStrata staff should be on site to verify compliance with these recommendations. These tests and observations should include, but not necessarily be limited to, the following.

- Observations and testing during site preparation, earthwork and structural fill placement.
- Observation of foundation soils to assess their suitability for footing placement.
- Observation of soft/loose soils over-excavation.
- Observation of temporary excavations and shoring.
- Consultation as may be required during construction.
- Quality control and observation of concrete placement.

## Exhibit B-Geotechnical Report

We also recommend that project plans and specifications be reviewed by us to verify compatibility with our conclusions and recommendations. Additional information concerning the scope and cost of these services can be obtained from our office.

We appreciate the opportunity to be of service on this project. Should you have any questions regarding the report or wish to discuss additional services, please do not hesitate to contact us at your convenience at (801) 501-0583.

## Exhibit B-Geotechnical Report

### 8.0 REFERENCES CITED

- Black, B.D., McDonald, G.N., and Hecker, S., compilers, 1999, Fault number 2378, *James Peak fault*, in Quaternary fault and fold database of the United States: U.S. Geological Survey
- Blau, Jan, 1975 Geology of southern part of the James Peak quadrangle, Utah. Thesis Report Pages 16-18.
- Bryant, B., 1992, Geologic and Structures Map of the Salt Lake City 1X2 Quadrangle, Utah and Wyoming: U.S. Geological Survey Map I-1997, Scale 1:125,000.
- Coogan, J.C., King, J.K., 2001, Progress Report Geologic Map of the Ogden 30' by 60' Quadrangle, Utah and Wyoming, Year 3 of 3, Utah Geological Survey, Open File Report 380.
- Federal Emergency Management Agency [FEMA], 1997, *NEHRP Recommended Provisions for Seismic Regulations for New Buildings and Other Structures*, FEMA 302, Washington, D.C.
- Frankel, A., Mueller, C., Barnard, T., Perkins, D., Leyendecker, E.V., Dickman, N., Hanson, S., and Hopper, M., 1996, *National Seismic-hazard Maps: Documentation*, U.S. Geological Survey Open-File Report 96-532, June.
- Harty, K.M., 1992, Landslide Map of the Salt Lake City 30' X 60' Quadrangle, Utah Geological Survey, Open File Report 236, Scale 1:100,000.
- Hecker, S., 1993, Quaternary Tectonics of Utah with Emphasis on Earthquake-Hazard Characterization: Utah Geological Survey Bulletin 127, 157p.
- Hintze, L. F., 1980, Geologic Map of Utah: Utah Geological and Mineral Survey Map-A-1, scale 1:500,000.
- Hintze, L.F. 1993, Geologic History of Utah, Brigham Young University Studies, Special Publication 7, 202p.
- Hintze, L.F., Willis, G.C., Laes, D.Y.M., 2000, Digital Geologic Map of Utah, Utah Geological Survey.
- International Building Code [IBC], 2006, International Code Council, Inc.

## Exhibit B-Geotechnical Report

King, J.K, Yonkee, W.A., Coogan, J.C., 2008, Interim Geologic Map of the Snow Basin Quadrangle and Part of the Huntsville Quadrangle, Davis, Morgan, and Weber Counties, Utah. Utah Geological Survey, Open File Report 536.

McCalpin, J.P., Foreman, S.L., Lowe, M. 1994, Reevaluation of Holocene faulting at the Kaysville site, Weber segment of the Wasatch fault zone, Utah, Tectonics, American Geophysical Union Publication, Vol. 13, No. 1, Pages 1-16

Stokes, W.L., 1986, Geology of Utah, Utah Museum of Natural History, University of Utah and Utah Geological and Mineral Survey, Department of Natural Resources: Occasional paper number 6.

Utah Department of Public Safety, 2009, Natural Hazard Pre-Disaster Mitigation Plan Part X, Morgan County



# Exhibit B-Geotechnical Report



200 0 200 400 600 800 ft



1:5,000



**GeoStrata**

Copyright, 2018

## Legend

 Apprximate Site Boundary

Scandinavian Homes  
Powder Mountain Lot 70  
Eden, Utah  
Project Number: 594-004


**Exploration Location Map**

Page 48 of 98

**Plate  
A-1**





# Exhibit B-Geotechnical Report



1:300



## Legend

-  Approximate Test Pit Location
-  Approximate Trench Location

Scandinavian Homes  
 Powder Mountain Lot 70  
 Eden, Utah  
 Project Number: 594-004

Page 49 of 98  
**Exploration Location Map**

**Plate  
 A-2**

# Exhibit B-Geotechnical Report

DATE		STARTED: 7/2/18			Summit Eden Phase 1C-Lot 70R			GeoStrata Rep: A. Peay			TEST PIT NO:		
		COMPLETED: 7/2/18			8492 East Spring Park			Rig Type: Trackhoe			TP-1		
		BACKFILLED: 7/2/18			Weber County, Utah						Sheet 1 of 1		
DEPTH		LOCATION									Moisture Content and Atterberg Limits		
		NORTHING EASTING ELEVATION									Plastic Limit Moisture Content Liquid Limit		
METERS FEET		MATERIAL DESCRIPTION			Dry Density (pcf)			Moisture Content %			Plasticity Index		
SAMPLES WATER LEVEL GRAPHICAL LOG UNIFIED SOIL CLASSIFICATION					Percent minus 200			Liquid Limit			10 20 30 40 50 60 70 80 90		
0	0				TOPSOIL; Silty SAND with gravel - brown, moist, organics and roots up to 1 inch in diameter extending to 3 feet below the existing site grade								
				GM	Silty GRAVEL with sand - dense to very dense, reddish-brown, moist, organics and large roots throughout with pinhole or root cast structures, gravels are sub-rounded to rounded up to 5 inches in diameter								
				GP-GM	Poorly Graded GRAVEL with silt, cobbles and boulders - dense to very dense, reddish-brown, moist, organics throughout, sub-rounded to rounded cobbles and boulders up to 1 1/2 feet in diameter								
				SP-SM	Poorly Graded SAND with silt - dense, reddish brown, moist, occasional gravels less than 1/4 inch in diameter	2.6	11.3	NP	NP				
					Bottom of Test Pit @ 5.5 Feet								

LOG OF TEST PITS (B) TRENCH LOGS.GPJ GEOSTRATA.GDT 7/11/18



Copyright (c) 2018, GeoStrata.

**SAMPLE TYPE**  
 □ - GRAB SAMPLE  
 ▣ - 3" O.D. THIN-WALLED HAND SAMPLER

**WATER LEVEL**  
 ▼ - MEASURED  
 ▽ - ESTIMATED

**NOTES:**  
 South end of trench

**Plate  
 B-1**



# Exhibit B-Geotechnical Report

DATE		STARTED: 7/2/18		Summit Eden Phase 1C-Lot 70R 8492 East Spring Park Weber County, Utah Project Number 594-004				GeoStrata Rep: A. Peay		TEST PIT NO: <b>TP-2</b> Sheet 1 of 1																								
		COMPLETED: 7/2/18						Rig Type: Trackhoe																										
		BACKFILLED: 7/2/18																																
DEPTH		METERS		FEET		SAMPLES		WATER LEVEL		GRAPHICAL LOG		UNIFIED SOIL CLASSIFICATION		LOCATION		NORTHING		EASTING		ELEVATION		Dry Density(pcf)		Moisture Content %		Percent minus 200		Liquid Limit		Plasticity Index		Moisture Content and Atterberg Limits		
MATERIAL DESCRIPTION														Plastic Limit																		Moisture Content		
		0																														10 20 30 40 50 60 70 80 90		
		1																																
		5																																
		2																																
		3																																
		Bottom of Test Pit @ 9.5 Feet																																

LOG OF TEST PITS (B) TRENCH LOGS.GPJ GEOSTRATA.GDT 7/11/18



Copyright (c) 2018, GeoStrata.

<b>SAMPLE TYPE</b>	
□	- GRAB SAMPLE
▼	- 3" O.D. THIN-WALLED HAND SAMPLER
<b>WATER LEVEL</b>	
▼	- MEASURED
▽	- ESTIMATED

**NOTES:**  
North end of trench

## Plate B-2

# Exhibit B-Geotechnical Report

## UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR DIVISIONS	USCS SYMBOL	TYPICAL DESCRIPTIONS	
<b>COARSE GRAINED SOILS</b> (More than half of material is larger than the #200 sieve)	GRAVELS (More than half of coarse fraction is larger than the #4 sieve)	CLEAN GRAVELS WITH LITTLE OR NO FINES GW	WELL-GRADED GRAVELS, GRAVEL-SAND MIXTURES WITH LITTLE OR NO FINES
		GRAVELS WITH OVER 12% FINES GP	POORLY-GRADED GRAVELS, GRAVEL-SAND MIXTURES WITH LITTLE OR NO FINES
	SANDS (More than half of coarse fraction is smaller than the #4 sieve)	CLEAN SANDS WITH LITTLE OR NO FINES GM	SILTY GRAVELS, GRAVEL-SILT-SAND MIXTURES
		GRAVELS WITH OVER 12% FINES GC	CLAYEY GRAVELS, GRAVEL-SAND-CLAY MIXTURES
		CLEAN SANDS WITH LITTLE OR NO FINES SW	WELL-GRADED SANDS, SAND-GRAVEL MIXTURES WITH LITTLE OR NO FINES
		SANDS WITH OVER 12% FINES SP	POORLY-GRADED SANDS, SAND-GRAVEL MIXTURES WITH LITTLE OR NO FINES
<b>FINE GRAINED SOILS</b> (More than half of material is smaller than the #200 sieve)	SILTS AND CLAYS (Liquid limit less than 50)	SM	SILTY SANDS, SAND-GRAVEL-SILT MIXTURES
		SC	CLAYEY SANDS SAND-GRAVEL-CLAY MIXTURES
		ML	INORGANIC SILTS & VERY FINE SANDS, SILTY OR CLAYEY FINE SANDS, CLAYEY SILTS WITH SLIGHT PLASTICITY
	SILTS AND CLAYS (Liquid limit greater than 50)	CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYS, SANDY CLAYS, SILTY CLAYS, LEAN CLAYS
		OL	ORGANIC SILTS & ORGANIC SILTY CLAYS OF LOW PLASTICITY
		MH	INORGANIC SILTS, MICACEOUS OR DIATOMACEOUS FINE SAND OR SILT
<b>HIGHLY ORGANIC SOILS</b>	CH	INORGANIC CLAYS OF HIGH PLASTICITY, FAT CLAYS	
	OH	ORGANIC CLAYS & ORGANIC SILTS OF MEDIUM-TO-HIGH PLASTICITY	
	PT	PEAT, HUMUS, SWAMP SOILS WITH HIGH ORGANIC CONTENTS	

### LOG KEY SYMBOLS

	BORING SAMPLE LOCATION		TEST-PIT SAMPLE LOCATION
	WATER LEVEL (level after completion)		WATER LEVEL (level where first encountered)

### CEMENTATION

DESCRIPTION	DESCRIPTION
WEAKLY	CRUMBLES OR BREAKS WITH HANDLING OR SLIGHT FINGER PRESSURE
MODERATELY	CRUMBLES OR BREAKS WITH CONSIDERABLE FINGER PRESSURE
STRONGLY	WILL NOT CRUMBLE OR BREAK WITH FINGER PRESSURE

### OTHER TESTS KEY

C	CONSOLIDATION	SA	SIEVE ANALYSIS
AL	ATTERBERG LIMITS	DS	DIRECT SHEAR
UC	UNCONFINED COMPRESSION	T	TRIAXIAL
S	SOLUBILITY	R	RESISTIVITY
O	ORGANIC CONTENT	RV	R-VALUE
CBR	CALIFORNIA BEARING RATIO	SU	SOLUBLE SULFATES
COMP	MOISTURE/DENSITY RELATIONSHIP	PM	PERMEABILITY
CI	CALIFORNIA IMPACT	-200	% FINER THAN #200
COL	COLLAPSE POTENTIAL	G <sub>s</sub>	SPECIFIC GRAVITY
SS	SHRINK SWELL	SL	SWELL LOAD

### MODIFIERS

DESCRIPTION	%
TRACE	<5
SOME	5 - 12
WITH	>12

### GENERAL NOTES

- Lines separating strata on the logs represent approximate boundaries only. Actual transitions may be gradual.
- No warranty is provided as to the continuity of soil conditions between individual sample locations.
- Logs represent general soil conditions observed at the point of exploration on the date indicated.
- In general, Unified Soil Classification designations presented on the logs were evaluated by visual methods only. Therefore, actual designations (based on laboratory tests) may vary.

### MOISTURE CONTENT

DESCRIPTION	FIELD TEST
DRY	ABSENCE OF MOISTURE, DUSTY, DRY TO THE TOUCH
MOIST	DAMP BUT NO VISIBLE WATER
WET	VISIBLE FREE WATER, USUALLY SOIL BELOW WATER TABLE

### STRATIFICATION

DESCRIPTION	THICKNESS	DESCRIPTION	THICKNESS
SEAM	1/16 - 1/2"	OCCASIONAL	ONE OR LESS PER FOOT OF THICKNESS
LAYER	1/2 - 12"	FREQUENT	MORE THAN ONE PER FOOT OF THICKNESS

### APPARENT / RELATIVE DENSITY - COARSE-GRAINED SOIL

APPARENT DENSITY	SPT (blows/ft)	MODIFIED CA. SAMPLER (blows/ft)	CALIFORNIA SAMPLER (blows/ft)	RELATIVE DENSITY (%)	FIELD TEST
VERY LOOSE	<4	<4	<5	0 - 15	EASILY PENETRATED WITH 1/2-INCH REINFORCING ROD PUSHED BY HAND
LOOSE	4 - 10	5 - 12	5 - 15	15 - 35	DIFFICULT TO PENETRATE WITH 1/2-INCH REINFORCING ROD PUSHED BY HAND
MEDIUM DENSE	10 - 30	12 - 35	15 - 40	35 - 65	EASILY PENETRATED A FOOT WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER
DENSE	30 - 50	35 - 60	40 - 70	65 - 85	DIFFICULT TO PENETRATED A FOOT WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER
VERY DENSE	>50	>60	>70	85 - 100	PENETRATED ONLY A FEW INCHES WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER

### CONSISTENCY - FINE-GRAINED SOIL

CONSISTENCY	SPT (blows/ft)	TORVANE UNTRAINED SHEAR STRENGTH (tsf)	POCKET PENETROMETER UNCONFINED COMPRESSIVE STRENGTH (tsf)	FIELD TEST
VERY SOFT	<2	<0.125	<0.25	EASILY PENETRATED SEVERAL INCHES BY THUMB. EXUDES BETWEEN THUMB AND FINGERS WHEN SQUEEZED BY HAND.
SOFT	2 - 4	0.125 - 0.25	0.25 - 0.5	EASILY PENETRATED ONE INCH BY THUMB. MOLDED BY LIGHT FINGER PRESSURE.
MEDIUM STIFF	4 - 8	0.25 - 0.5	0.5 - 1.0	PENETRATED OVER 1/2 INCH BY THUMB WITH MODERATE EFFORT. MOLDED BY STRONG FINGER PRESSURE.
STIFF	8 - 15	0.5 - 1.0	1.0 - 2.0	INDENTED ABOUT 1/2 INCH BY THUMB BUT PENETRATED ONLY WITH GREAT EFFORT.
VERY STIFF	15 - 30	1.0 - 2.0	2.0 - 4.0	READILY INDENTED BY THUMBNAIL.
HARD	>30	>2.0	>4.0	INDENTED WITH DIFFICULTY BY THUMBNAIL.



Copyright GeoStrata, 2018

### Soil Symbols Description Key

Lot 70 - Summit Eden Phase 1C  
8492 East Spring Park  
Weber County, Utah  
Project Number: 594-004

Plate

B-3

# Exhibit B-Geotechnical Report

Test Pit No.	Sample Depth (feet)	USCS Soil Classification	Natural Moisture Content (%)	Natural Dry Density (pcf)	Gradation			Atterberg		Direct Shear	
					Gravel (%)	Sand (%)	Fines (%)	LL	PI	Apparent Cohesion (psf)	Internal Friction (°)
TP-1	4.5	GP-GM	2.6		80.3	8.4	11.3	NP	NP		
TP-2	6	GP-GM						NP	NP		
TP-2	9	GP-GM	7	113	62.7	23.4	13.9	NP	NP	260	26



Copyright GeoStrata, 2018

## Lab Summary Report


Scandinavian Homes  
 Summit Eden Phase 1C - Lot 70R  
 8492 East Springs Park  
 Weber County, Utah  
 Project Number: 594-004

Plate  
 C - 1





# Exhibit B-Geotechnical Report



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Sample Location	Depth	Classification	LL	PL	PI	Cc	Cu
● TP-1	4.5	Poorly Graded GRAVEL with silt	NP	NP	NP	3316.1	5377.03
■ TP-2	6.0	Poorly Graded GRAVEL with silt	NP	NP	NP		

Sample Location	Depth	D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay
● TP-1	4.5	75	57.21	26.568		80.3	8.4	11.3	
■ TP-2	6.0	37.5	22.781	1.161		62.7	23.4	13.9	



## GRAIN SIZE DISTRIBUTION - ASTM D422



Summit Eden Phase 1C-Lot 70R  
 8492 East Spring Park  
 Weber County, Utah  
 Project Number: 594-004

**Plate**  
**C - 3**

# DIRECT SHEAR TEST




Sample Location:	TP-2 @ 9 ft
Type of Test:	Consolidated Drained/Saturated

Test No. (Symbol)	1 (◆)	2 (■)	3 (▲)
Sample Type	Remolded		
Initial Height, in.	0.984	0.982	0.989
Diameter, in.	2.5	2.5	2.5
Dry Density Before, pcf	115.7	115.2	113.4
Dry Density After, pcf	117.6	117.2	115.4
Moisture % Before	5.9	7.5	7.9
Moisture % After	13.9	14.4	14.7
Saturation, % Before	36.3	45.9	45.6
Saturation, % After	90.5	92.7	90.0
Normal Load, ksf	4.0	2.0	1.0
Shear Stress, ksf	2.22	1.24	0.75
Strain Rate	IN/MIN		

Sample Properties	
Cohesion, psf	260
Friction Angle, $\phi$	26
Liquid Limit, %	NP
Plasticity Index, %	NP
Percent Gravel	62.7
Percent Sand	23.4
Percent Passing No. 200 sieve	13.9
Classification	GP-GM

PROJECT: Summit Eden Phase 1C- Lot 70R

# Exhibit B-Geotechnical Report



Material Name	Color	Unit Weight (lbs/ft3)	Strength Type	Cohesion (psf)	Phi (deg)	Water Surface	Ru
Topsoil		110	Mohr-Coulomb	100	30	None	0
Bedrock/Alluvium		120	Mohr-Coulomb	50	34	None	0




## Lot 70R - Static Slope Stability

Lot 70R - Summit Eden Phase 1C  
 8492 East Spring Park  
 Weber County, Utah  
 GeoStrata Project No. 594-004

**Plate  
D-1**

# Exhibit B-Geotechnical Report



## Lot 70R - PStatic Slope Stability

Lot 70R - Summit Eden Phase 1C  
8492 East Spring Park  
Weber County, Utah  
GeoStrata Project no. 594-004

**Plate  
D-2**



14425 South Center Point Way Bluffdale, Utah 84065  
Phone (801) 501-0583 | Fax (801) 501-0584

**Geologic Hazards Screening Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Parcel # 23-130-0037**

GeoStrata Job No. 594-005

July 17, 2018

Prepared for:

**Scandinavian LLC  
c/o Jake Vainio  
6410 North Business Loop Road  
Park City, Utah 84098  
435-513-0990 cell  
jakev@myscandinavian.com**



Learn More

Exhibit B-Geologic Report



Prepared for:

Scandinavian LLC  
c/o Jake Vainio  
6410 North Business Loop Road  
Park City, Utah 84098  
435-513-0990 cell  
jakev@myscandinavian.com

**Geologic Hazards Screening Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Parcel # 23-130-0037**

GeoStrata Job No. 594-005

Prepared by:

---

Sofia Agopian  
Geologic Staff



---

Timothy J. Thompson, P.G.  
Senior Geologist

**GeoStrata**  
14425 South Center Point Way  
Bluffdale, UT 84065  
(801) 501-0583

July 17, 2018

**TABLE OF CONTENTS**

<b>1.0</b>	<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<b>2.0</b>	<b>INTRODUCTION.....</b>	<b>6</b>
2.1	PURPOSE AND SCOPE OF WORK .....	6
2.2	PROJECT DESCRIPTION.....	6
<b>3.0</b>	<b>METHODS OF STUDY .....</b>	<b>8</b>
3.1	OFFICE INVESTIGATION .....	8
3.2	FIELD INVESTIGATION.....	8
<b>4.0</b>	<b>GEOLOGIC CONDITIONS.....</b>	<b>9</b>
4.1	GEOLOGIC SETTING.....	9
4.2	SITE GEOLOGY .....	9
<b>5.0</b>	<b>GENERALIZED SITE CONDITIONS .....</b>	<b>11</b>
5.1	SURFACE CONDITIONS .....	11
<b>6.0</b>	<b>GEOLOGIC HAZARDS.....</b>	<b>12</b>
6.1	EARTHQUAKE GROUND SHAKING HAZARD.....	13
6.2	SURFACE FAULT RUPTURE HAZARD.....	14
6.3	TECTONIC DEFORMATION.....	15
6.4	LIQUEFACTION .....	15
6.5	ROCKFALL AND TOPPLE .....	16
6.6	LANDSLIDE, SLUMP, CREEP.....	16
6.7	AVALANCHE.....	18
6.8	ALLUVIAL FAN FLOODING .....	19
6.9	SHALLOW GROUNDWATER.....	20
6.10	STREAM FLOODING HAZARD .....	20
6.11	CANAL FLOODING.....	21
6.12	DAM FAILURE .....	21
6.13	PROBLEM SOILS.....	21
6.14	RADON .....	22
6.15	KARST AND SINK HOLES.....	22
<b>7.0</b>	<b>GEOLOGIC HAZARDS SUMMARY AND CONCLUSIONS.....</b>	<b>23</b>
<b>8.0</b>	<b>CLOSURE .....</b>	<b>25</b>
8.1	LIMITATIONS .....	25
<b>9.0</b>	<b>REFERENCES CITED .....</b>	<b>26</b>

# Exhibit B-Geologic Report

## APPENDICES

Appendix	Plate 1 – Site Vicinity Map
	Plate 2 – Topographic Map
	Plate 3 – Hillshade Map
	Plate 4 – Site Vicinity Geologic Map
	Plate 5 – Site Vicinity 30' X 60' Geologic Map
	Plate 6 – Quaternary Fault Map
	Plate 7 – Landslide Hazard Map
	Plate 8 – Hydrology Map



## **1.0 EXECUTIVE SUMMARY**

The purpose of this investigation and report is to assess the approximately 0.06 acre single family residential lot, Lot 70R Summit Eden Phase 1C, located at 8492 East Spring Park Road in Eden, Utah for the presence of geologic hazards that may impact the planned development of the site. The work performed for this report was performed in accordance with our proposal, dated June 22, 2018.

The subject site is located in Eden, Utah above Ogden Valley and in the Powder Mountain Ski Resort at an elevation of approximately 8,580 feet above sea level. We understand that the project site is currently an undeveloped lot approximately 0.06 acre in size and located on a native hillside. Proposed development, as currently planned, will consist of a single family residential structure as well as associated driveway, utilities and landscape areas. The subject site and the area surrounding the subject site remains in a relatively native condition apart from grading for the roadways. Some parcels along Spring Park Road are currently under development.

The earthquake ground shaking hazard that would potentially impact the subject site was assessed as part of our study. Given our office investigations, it is the opinion of GeoStrata that the earthquake ground shaking hazard within the subject site is considered low. It is the opinion of GeoStrata that earthquake ground shaking hazard should not preclude development at the subject site.

The surface fault rupture hazard that would potentially impact the subject site was assessed as part of our study. No active faults are located near the subject site. Given our field and office investigations, the surface fault rupture hazard within the subject site is considered low and it is considered unlikely that surface fault rupture will impact the proposed development. It is the opinion of GeoStrata that surface fault rupture hazard should not preclude development at the subject lot.

The tectonic deformation hazard that would potentially impact the site was assessed as part of our study. No active faults are reported or mapped within or adjacent to the subject site. It is the opinion of GeoStrata that the tectonic deformation hazard within the subject site is considered low and it is considered unlikely that tectonic deformation will impact the proposed

## Exhibit B-Geologic Report

development. It is the opinion of GeoStrata that the tectonic deformation hazard should not preclude development at the subject site.

The liquefaction hazard that would potentially impact the site was assessed as part of our study. The site is located in an area currently designated as having a “Very Low” liquefaction potential. The near-surface soils are not considered to be susceptible to liquefaction. It is the opinion of GeoStrata that liquefaction hazard should not preclude development at the subject site.

The rockfall hazards within the subject site were assessed as part of our study. No rockfall or talus deposits are located within or immediately adjacent to the subject lot. Our field investigation revealed no indications that the subject lot has been subjected to previous rockfall. Therefore, the rockfall hazard within the subject site is considered low and it is considered unlikely that rockfall will impact the proposed development. It is the opinion of GeoStrata that rockfall hazard should not preclude development at the subject site.

The landslide, slump and creep hazards that would potentially impact the site were assessed as part of this study. A landslide deposit (Qms) is mapped immediately south of the subject site. A deposit described as landslide undifferentiated from talus and/or colluvial is mapped south and in the vicinity of the subject site as shown on the Landslide Hazard Maps of Utah (Elliot and Harty, 2010). No landslide deposit is mapped within or immediately adjacent to the subject site on the Geologic Map of the Browns Hole and Huntsville Quadrangles. A trench trending north-northwest to south-southeast through the middle of the subject site and at a depth of approximately 5 to 9 feet below existing site grade was excavated as part of the geotechnical study compiled for the subject site. Geologic observations of the near surface geology in the trench exposure were made during our site visit. It is the opinion of GeoStrata that the soils observed in the trench were observed to comprise of colluvium deposits. No shears or deformation features related to a landslide deposit were observed in the trench. Based on our stereographic aerial photograph interpretation, our review of the hillshades derived from 2016 0.5 meter LiDAR and our field observations, no landslide features such as hummocky topography, slumps or scarps were identified within the subject site or observed in the trench excavation. The subject site was observed to be moderately to steeply sloping and to contain outcroppings of well-rounded quartzite cobbles and boulders that were partially buried. Based on the landslide mapped south of the subject site and the moderate to steep grade within the subject site, it is the opinion of GeoStrata that the landslide hazard within the subject site is considered low to moderate. GeoStrata recommends that a slope stability analysis be performed by a professional engineer as part of a comprehensive site specific geotechnical investigation to assess

## Exhibit B-Geologic Report

the potential for slope failure. Slope stability modeling should take landslide deposits and potential landslide deposits into consideration and evaluate all portions of the subject site being considered for development to provide recommendations for construction that will aid in reducing the risk for mass movement within the subject site.

It is the opinion of GeoStrata that landslide hazards should not preclude development at the subject site as long as a slope stability analysis is conducted as a part of a comprehensive site specific geotechnical investigation for the site that indicates that the planned development will not be affected by potential slope failure. All recommendations to reduce the risks of slope stability hazards contained in the site specific geotechnical report should be followed and incorporated in the design of the site. The recommendations contained in the geotechnical report should be incorporated into the grading and drainage design for the lot. Saturated soil conditions should be considered in the slope stability analysis conducted as a part of a comprehensive site specific geotechnical investigation for the site.

Slope stability of the subject site was not assessed as part of this geological hazard assessment. The subject site was observed to be moderately to steeply sloping to the south toward a nearby drainage. The possibility that development of the site could negatively affect slope stability within the subject site is increased if development is planned for areas of the site with slopes steeper than approximately 3 horizontal: 1 vertical. It should be noted that grading or development adjacent to the subject site could potentially impact the stability of the area within the subject site and assessment of that hazard is out of the scope of this assessment.

The snow avalanche hazard that would potentially impact the site was assessed as part of this study. No evidence of prior snow avalanche was observed within the subject site. It is the opinion of GeoStrata that the snow avalanche hazard within the subject site is considered low and it is considered unlikely that this hazard will impact the proposed development. It is the opinion of GeoStrata that snow avalanche hazard should not preclude development at the subject site.

The alluvial-fan flooding hazard that would potentially impact the site was assessed as part of this study. No Holocene age alluvial fan deposit is mapped within or adjacent to the subject site. Given our field and office investigations, the alluvial fan flooding hazards within subject site is considered low and it is considered unlikely that debris flows will impact the proposed development. It is the opinion of GeoStrata that alluvial fan flooding hazard should not preclude development at the subject lot.

## Exhibit B-Geologic Report

The shallow groundwater hazard that would potentially impact the site is out of the scope of this study. Seasonal fluctuations in precipitation, rapid snowmelt, surface runoff from adjacent properties, or other on or offsite sources may increase moisture conditions; groundwater conditions can be expected to rise several feet seasonally depending on the time of year. A trench was excavated within the subject site and to a depth of approximately 9 feet below existing grade. No water was observed at the time of our site visit. Groundwater potential will be evaluated and discussed further in the geotechnical study compiled for the subject site.

The stream flooding hazard that would potentially impact the site was assessed as part of this study. A drainage is located in the downslope and southwest of the subject site. Given our field and office investigations, the stream flooding hazard within the subject lot is considered low and it is considered unlikely that stream flooding will impact the proposed development. It is the opinion of GeoStrata that stream flooding hazard should not preclude development at the subject site. Proper site grading and drainage plans should be developed for the subject site as a part of the civil engineering design for the site to mitigate the potential for stream flooding to impact and damage planned structures or other planned associated infrastructure.

The canal flooding hazard that would potentially impact the site was assessed as part of this study. No canals were observed or are mapped within or adjacent to the subject site. Given our field and office investigations, the canal flooding hazard within the subject lot is considered low and it is considered unlikely that canal flooding will impact the proposed development. It is the opinion of GeoStrata that canal flooding hazard should not preclude development at the subject lot.

The dam failure hazard that would potentially impact the site was assessed as part of this study. No dams or reservoirs are located up-gradient of the subject site. Given our field and office investigations, the dam failure hazard within the subject lot is considered low and it is considered unlikely that dam failure will impact the proposed development. It is the opinion of GeoStrata that dam failure hazard should not preclude development at the subject lot.

The problem soils hazard is out of the scope of this study. Based on our review of published geologic maps and our field observations, the subject site is underlain by granular soils. No laboratory testing was performed on these soils as part of this study and therefore this hazard was not assessed as part of this study. A geotechnical study will be completed for the subject site in order to understand soil properties for use in the design of footing, foundation elements and grading.

## Exhibit B-Geologic Report

The radon gas hazard is out of the scope of this study. No published data that covers the area of the subject sites currently exists. Indoor testing following construction is recommended for determining radon gas levels and mitigation methods needed.

The karst and sink holes hazards is out of the scope of this study. The karst and sink holes hazards within the subject site are considered low and it is unlikely that karst and sink holes hazards will impact the proposed development.

**NOTICE: The scope of services provided within this report are limited to the assessment of the subsurface conditions for the proposed development. This executive summary is not intended to replace the report of which it is part and should not be used separately from the report. The executive summary is provided solely for purposes of overview. The executive summary omits a number of details, any one of which could be crucial to the proper application of this report.**

## 2.0 INTRODUCTION

### 2.1 PURPOSE AND SCOPE OF WORK

The purpose of this investigation and report is to assess the approximately 0.06 acre single family residential lot, Lot 70R Summit Eden Phase 1C, located at 8492 East Spring Park Road in Eden, Utah for the presence of geologic hazards that may impact the planned development of the site. The geologic hazards considered for this site are presented in Table 2 of this report. The work performed for this report was performed in accordance with our proposal, dated June 22, 2018. Our scope of services included the following:

- Review of available references and maps of the area.
- Stereographic aerial photograph interpretation of aerial photographs covering the site area.
- Review of 2016 0.5 meter LiDAR obtained from the State of Utah AGRC.
- Geologic reconnaissance and field mapping of the site by an engineering geologist to observe and document pertinent surface features indicative of geologic hazards.
- Evaluation of our observations combined with existing information and preparation of this written report with conclusions and recommendations regarding possible surface rupture hazards or any other geologic hazards observed to affect the site.

The recommendations contained in this report are subject to the limitations presented in the Limitations section of this report.

### 2.2 PROJECT DESCRIPTION

The subject site is located in Eden, Utah above Ogden Valley and in the Powder Mountain Ski Resort at an elevation of approximately 8,580 feet above sea level. We understand that the project site is currently an undeveloped lot approximately 0.06 acre in size and located on a native hillside. Proposed development, as currently planned, will consist of a single family residential structure as well as associated driveway, utilities and landscape areas. The hillside in the area of the subject lot slopes moderately to steeply to the south toward a nearby drainage. It is our understanding that the general area of the subject lot was first developed within the last few years. The subject site and the area surrounding the subject site remains in a relatively native condition apart from grading for the roadways. Some parcels along Spring Park Road are

## Exhibit B-Geologic Report

currently under development. The subject site is shown on the Site Vicinity Map and Topographic Map included in the Appendix of this report (Plate 1; Plate 2).

## 3.0 METHODS OF STUDY

### 3.1 OFFICE INVESTIGATION

To prepare for the investigation, GeoStrata reviewed pertinent literature and maps listed in the references section of this report, which provided background information on the local geologic history of the area and the locations of suspected or known geologic hazards (Elliot and Harty, 2010; Black and others, 2016; Coogan and King, 2016; Crittenden, 1972; Sorensen and Crittenden, 1979). A stereographic aerial photograph interpretation was performed for the subject site using two sets of stereo aerial photographs obtained from the UGS as shown in Table 1.

Source	Photo Number	Date	Scale
ASCS	AAI_4K-35	September 14, 1952	1:20,000
ASCS	AAI_4K-36	September 14, 1952	1:20,000

**Table 1: Aerial Stereosets.**

GeoStrata also conducted a review of hillshades derived from 2016 0.5 meter LiDAR obtained from the State of Utah AGRC to assess the subject site for visible alluvial fan deposits, scarps associated with landslide geomorphology and lineations related to stream flooding hazards or surface fault rupture related geomorphology. The LiDAR elevation data was used to create hillshade imagery that could be reviewed for assessment of geomorphic features related to geologic hazards (Plate 3 Hillshade Map).

### 3.2 FIELD INVESTIGATION

An engineering geologist investigated the geologic conditions within the general site area. A field geologic reconnaissance was conducted to observe existing geologic conditions and to assess existing geomorphology for surficial evidence of geologic hazards. During our fieldwork we conducted site observations to assess geologic hazards that might impact the lot. We used our field observations to confirm the observations made during our office research and to observe any evidence of geologic hazards that were not evident in our office research, but which could be observed in the field.



## 4.0 GEOLOGIC CONDITIONS

### 4.1 GEOLOGIC SETTING

The site is located in the mountains of the Powder Mountain Ski Resort located in Eden, Utah and in the eastern region of Ogden Valley at approximately 8,580 feet above sea level. The Ogden Valley is a northwest trending deep, lacustrine sediment-filled structural basin of Cenozoic age bounded on the northeast and southwest by two normal faults that dip towards the center of the valley. The Ogden Valley is a fault graben flanked by two uplifted blocks, the Wasatch Range on the west and unnamed flat-topped mountains to the east (King and others 2008). The Wasatch Range is the easternmost expression of pronounced Basin and Range extension in north-central Utah (Stokes, 1986). The Willard Thrust, one of the largest faults in the Sevier mountain belt, bounds the western side of Ogden Valley which uplifted and exposed Proterozoic age sedimentary bedrock.

The near-surface geology of the Ogden Valley is dominated by lake sediments with a maximum thickness of 70 feet which were deposited within the last 30,000 years during the high stand of the Lake Bonneville Cycle when water inundated Ogden Canyon and formed a small lake in Ogden Valley up to an approximate altitude of 4,900 feet (Scott and others, 1983; Hintze, 1993; Leggette and Taylor, 1937; King and others, 2008). As the lake receded, streams began to incise large deltas that had formed at the mouths of major canyons along the Wasatch Range and the unnamed flat-topped mountains bounding the eastern margins of Ogden Valley. The eroded material was then deposited in shallow lakes and marshes in the basin and at the base of nearby canyons and in a series of recessional deltas and alluvial fans that extended into the Ogden Valley and nearby canyons. Sediments toward the center of the valley are predominately deep-water deposits of clay, silt and fine sand whereas sediments closer to the mountain fronts are shallow-water deposits of coarse sand and gravel. However, these deep-water deposits are in places covered by a thin post-Bonneville alluvial cover. Proterozoic age sedimentary bedrock is dominant in the northern portion of Ogden Valley where Tertiary age volcanics are prevalent in the southern portion of Ogden Valley and along knolls or foothills in the central portion of the valley.

### 4.2 SITE GEOLOGY

The surficial deposits within the subject site are shown on Plate 4 Site Vicinity Geologic Map and Plate 5 Site Vicinity 30x60 Geologic Map. On Plate 4, the geology within the subject site is

## Exhibit B-Geologic Report

mapped as Eocene, Paleocene and Upper Cretaceous(?) Wasatch and Evanston(?) Formations, Undivided (Twe) bedrock and is described as unconsolidated pale-reddish-brown Precambrian quartzite pebble, cobble and boulder conglomerate with a matrix of sand and silt (Sorensen and Crittenden, 1979 and Crittenden, 1972). Plate 5 also indicates that the subject site is underlain Eocene and upper Paleocene Wasatch Formation (Coogan and King, 2016). Coogan and King (2016) indicate a Holocene and upper and middle(?) Pleistocene age landslide deposit (Qms) located immediately south of the subject site.

### **5.0 GENERALIZED SITE CONDITIONS**

#### **5.1 SURFACE CONDITIONS**

As stated previously, the project site is located in the eastern mountains above Ogden Valley and within the Powder Mountain Ski Resort. The subject site is located on a moderately to steeply sloping hillside. The hillside slopes at approximately 13° south toward a nearby drainage. A trench was excavated as part of the geotechnical study compiled on the subject site and observed during our site visit. The surficial deposits exposed within the trench were observed to consist of subrounded to rounded gravel, cobbles and boulders in a matrix of silt and sand. Numerous well-rounded quartzite cobbles and boulders up to 2 feet in diameter were observed in the trench and partially buried near the surface. The majority of the cobbles and boulders were observed to be partially buried. The site remains in a relatively natural state and is vegetated with low lying brush, wildflowers, weeds and grasses. No structures were observed on the subject property. Some parcels in the surrounding area of the subject site are under development. The properties bordering the subject site are currently undeveloped.

# Exhibit B-Geologic Report

## 6.0 GEOLOGIC HAZARDS

Geologic hazards can be defined as naturally occurring geologic conditions or processes that could present a danger to human life and property. These hazards must be considered before development of the site. There are several hazards that if present at the site should be considered in the design of habitable structures and other critical infrastructure. The hazards considered for this site are presented on Table 2 and discussed in the following sections of this report.

Hazard	Hazard Rating*					Further Study Recommended
	Not Applicable	Not Assessed	Low	Moderate	High	
Ground Shaking			X			
Surface Fault Rupture			X			
Tectonic Deformation			X			
Liquefaction			X			
Rock Fall and Topple			X			
Landslide			X	X		E
Slump			X	X		E
Creep			X	X		E
Avalanche			X			
Debris Flow			X			
Hyperconcentrated Flow			X			
Stream Flow			X			
Shallow Groundwater		X				E
Stream Flooding			X			
Canal Flooding	X					
Dam Failure			X			
Problem Soils		X				E
Radon		X				
Karst and Sink Hole		X				

**Table 2: Summary of Geologic Hazards.**

## Exhibit B-Geologic Report

Table 2 shows the summary of the geologic hazards assessed and not assessed at the study area. The hazard rating as shown on Table 2 is intended to assess the probability that the hazard could have an impact on the site and not the severity of the hazard. A hazard rating of “Not Assessed” are hazards this report does not consider and no inference is made as to the presence or absence of the hazard at the site. A hazard rating of “Low” indicates that no evidence was found to indicate that the hazard is present and has a low probability of impacting the site, hazard not known or suspect to be present. A hazard rating of “Moderate” indicates that the hazard has a moderate probability of impacting the site, but the evidence is equivocal, based only on theoretical studies, or was not observed and further study is necessary as noted. A hazard rating of “High” indicates that that evidence is strong and suggests that there is a high probability of impacting the site and mitigation measures should be taken. If a hazard is assessed to potentially impact the site then further studies may be recommended. The following are the recommended studies and the letter designation associated with those studies: “E” – geotechnical/engineering, “H” – hydrologic, “A” – avalanche, “G” – additional detailed geologic hazard study out of the scope of this study.

### 6.1 EARTHQUAKE GROUND SHAKING HAZARD

During the event of an earthquake, seismic waves radiate outward from the initial point of rupture and dissipate with distance. The ground shakes as the seismic waves displace the ground both vertically and horizontally. Ground shaking can cause significant damage to and potentially collapse structures and can also trigger landslides, avalanches and liquefaction. The type of soil a seismic wave travels through can amplify or dampen the effects of ground shaking.

Seismic hazard maps depicting probabilistic ground motions and spectral response have been developed for the United States by the U.S. Geological Survey as part of NEHRP/NSHMP (Frankel et al, 1996). These maps have been incorporated into both *NEHRP Recommended Provisions for Seismic Regulations for New Buildings and Other Structures* (FEMA, 1997) and the *International Building Code (IBC)* (International Code Council, 2015). Spectral responses for the Maximum Considered Earthquake ( $MCE_R$ ) are shown in the table below. These values generally correspond to a two percent probability of exceedance in 50 years (2PE50) for a “firm rock” site. To account for site effects, site coefficients which vary with the magnitude of spectral acceleration are used. Based on our field and office investigations, it is our opinion that this location is best described as a Site Class C which represents a “Very Dense Soil and Soft Rock” profile. The spectral accelerations are shown in the table below. The spectral accelerations are calculated based on the site’s approximate latitude and longitude of 41.362942° and

## Exhibit B-Geologic Report

-111.746329° respectively and the United States Geological Survey U.S. Seismic Design Maps web-based application. Based on the IBC, the site coefficients are  $F_a=1.08$  and  $F_v= 1.54$ . From this procedure the peak ground acceleration (PGA) is estimated to be 0.35g.

<b>Site Location:</b>	<b>Site Class C Site Coefficients:</b>
<b>Latitude = 41.362942 N</b>	<b><math>F_a = 1.08</math></b>
<b>Longitude = -111.746329 W</b>	<b><math>F_v = 1.54</math></b>
<b>Spectral Period (sec)</b>	<b>Response Spectrum Spectral Acceleration (g)</b>
0.2	$S_{MS}=(F_a*S_s=1.08*0.812) = 0.87$
1.0	$S_{M1}=(F_v*S_1=1.54*0.269) = 0.41$
<sup>a</sup> IBC 1613.3.4 recommends scaling the $MCE_R$ values by 2/3 to obtain the design spectral response acceleration values; values reported in the table above have not been reduced.	

**Table 3:  $MCE_R$  Seismic Response Spectrum Spectral Acceleration Values for IBC Site Class C<sup>a</sup>.**

Based on the above information, it is the opinion of GeoStrata that the earthquake ground shaking hazard within the subject site is considered low. It is the opinion of GeoStrata that earthquake ground shaking hazard should not preclude development at the subject site.

### 6.2 SURFACE FAULT RUPTURE HAZARD

Movement along faults within the crustal rocks beneath the ground surface generates earthquakes. During large magnitude earthquakes (Richter magnitude 6.5 or greater) along the normal faults in the intermountain region, fault ruptures can propagate to the ground surface resulting in a surface fault rupture (Smith and Arabasz, 1991). The fault scarp formed during a surface fault rupture event along a normal fault is generally nearly vertical. A surface rupture fault may be comprised of a larger single surface rupture or several smaller surface ruptures across a fault zone. For all structures designed for human occupancy, a surface rupturing fault is considered active if it has experienced movement in approximately the past 10,000 years (Christenson and others, 2003).

Based on review of published geologic maps, our stereographic aerial photograph interpretation, our review of the hillshades derived from 2016 0.5 meter LiDAR and our field observations, no active faults are located near the subject site (Plate 6 UGS Quaternary Fault Map). The nearest fault is the Ogden Valley Northeastern Margin Fault which is between 0.75 and 2.6 million years

## Exhibit B-Geologic Report

old with an undetermined reoccurrence interval and a slip rate of less than 0.2 mm/yr (Black and others, 2003). This fault is trending northwest approximately 3 miles southwest of the subject site. Given our field and office investigations, the surface fault rupture hazard within the subject site is considered low and it is considered unlikely that surface fault rupture will impact the proposed development. It is the opinion of GeoStrata that surface fault rupture hazard should not preclude development at the subject lot.

### 6.3 TECTONIC DEFORMATION

Subsidence is a hazard associated with warping, lowering and tilting of a valley floor accompanying surface ruptures on normal faults (Robinson, 1993). Inundation along the shores of lakes and reservoirs and the rise of groundwater levels are the main hazards associated with subsidence. Structures that require gentle gradients or horizontal floors such as waste water treatment plants and sewer lines may be adversely affected by tectonic subsidence. Because subsidence may occur over very large areas, it is not generally practical to avoid the use of potentially affected land except in narrow areas of hazard due to lakeshore inundation (Keaton, 1987; Robison, 1993). According to Gary Christenson (UGS, personal communication 2001), tectonic subsidence is not typically assessed for subdivision development unless the development is located within an area of potential lake flooding.

Based on published geological maps, no active faults are reported or mapped within or adjacent to the subject site. It is the opinion of GeoStrata that the tectonic deformation hazard within the subject site is considered low and it is considered unlikely that tectonic deformation will impact the proposed development. It is the opinion of GeoStrata that the tectonic deformation hazard should not preclude development at the subject site.

### 6.4 LIQUEFACTION

Certain areas within the intermountain region possess a potential for liquefaction during seismic events. Liquefaction is a phenomenon whereby loose, saturated, granular soil deposits lose a significant portion of their shear strength due to excess pore water pressure buildup resulting from dynamic loading, such as that caused by an earthquake. Among other effects, liquefaction can result in densification of such deposits causing settlements of overlying layers after an earthquake as excess pore water pressures are dissipated. The primary factors affecting liquefaction potential of a soil deposit are: (1) level and duration of seismic ground motions; (2) soil type and consistency; and (3) depth to groundwater.

## Exhibit B-Geologic Report

Based on our review of the *Liquefaction Special Study Areas, Wasatch Front and Nearby Areas, Utah* compiled by Christenson and others, 2008, the site is located in an area currently designated as having a “Very Low” liquefaction potential. “Very Low” liquefaction potential indicates that there is less than a 5 percent probability of having an earthquake within a 100-year period that will be strong enough to cause liquefaction. The surface soils we observed during our field investigation are not considered to be susceptible to liquefaction. A liquefaction analysis was beyond the scope of this geologic hazards assessment; however, if the owner wishes to have greater understanding of the liquefaction potential of the soils at greater depths, a liquefaction analysis should be completed at the site. It is the opinion of GeoStrata that liquefaction hazard should not preclude development at the subject site.

### 6.5 ROCKFALL AND TOPPLE

Rockfalls are the fastest moving mass movement that predominantly occurs in mountains where a rock source exists along steep slopes and cliffs greater than 35 degrees. Rockfalls are a result of a loss of support from beneath the rock mass that can be caused by freeze/thaw action, rainfall, weathering and erosion, and/or strong ground shaking resulting from seismic activity. Rockfalls result in the collection of rock fall material, referred to as talus, at the base of the slope. The presence of talus indicates that a rockfall hazard has occurred and may still be present at the site.

Based on review of published geologic maps, our stereographic aerial photograph interpretation and our field observations, no rockfall or talus deposits are located within or immediately adjacent to the subject lot. Boulders observed within the subject site were well rounded, partially buried and are in our opinion not indicative of recent rockfall events. Furthermore, no rockfall sources such as talus deposits or bedrock outcroppings were observed upslope from the subject site. Our field investigation revealed no indications that the subject lot has been subjected to previous rockfall. Therefore, the rockfall hazard within the subject site is considered low and it is considered unlikely that rockfall will impact the proposed development. It is the opinion of GeoStrata that rock fall hazard should not preclude development at the subject site.

### 6.6 LANDSLIDE, SLUMP, CREEP

There are several types of landslides that should be considered when evaluating geologic hazards at a site with moderately to steeply sloping terrain. These include shallow debris slides, deep-seated earth or rock slumps and earth flows. Landslides, slumps, creep and other mass



## Exhibit B-Geologic Report

movements can develop on moderate to steep slopes where the slope has been altered or disturbed. Movement can occur at the top of a slope that has been loaded by fill placement, at the base of a slope that has been undercut, or where local groundwater rises resulting in increased pore pressures within the slope. Slopes that exhibit prior failures and large landslide deposits are particularly susceptible to instability and reactivation.

Based on review of the Interim Geologic Map of the Ogden 30x60 Quadrangle, a landslide deposit (Qms) is mapped immediately south of the subject site (Plate 5 Site Vicinity 30x60 Geologic Map). A deposit described as landslide undifferentiated from talus and/or colluvial is mapped south and in the vicinity of the subject site as shown on Plate 7 Landslide Hazard Map. No landslide deposit is mapped within or immediately adjacent to the subject site on the Geologic Map of the Browns Hole and Huntsville Quadrangles as indicated on and Plate 4 Site Vicinity Geologic Map. A trench trending north-northwest to south-southeast through the middle of the subject site and at a depth of approximately 5 to 9 feet below existing site grade was excavated as part of the geotechnical study compiled for the subject site. Geologic observations of the near surface geology in the trench exposure were made during our site visit. It is the opinion of GeoStrata that the soils observed in the trench were observed to comprise of colluvium deposits. No shears or deformation features related to a landslide deposit were observed in the trench. Based on our stereographic aerial photograph interpretation, our review of the hillshades derived from 2016 0.5 meter LiDAR and our field observations, no landslide features such as hummocky topography, slumps or scarps were identified within the subject site or observed in the trench excavation. The subject site was observed to be moderately to steeply sloping and to contain outcroppings of well-rounded quartzite cobbles and boulders that were partially buried. Based on the landslide mapped south of the subject site and the moderate to steep grade within the subject site, it is the opinion of GeoStrata that the landslide hazard within the subject site is considered low to moderate. GeoStrata recommends that a slope stability analysis be performed by a professional engineer as part of a comprehensive site specific geotechnical investigation to assess the potential for slope failure. Slope stability modeling should take landslide deposits and potential landslide deposits into consideration and evaluate all portions of the subject site being considered for development to provide recommendations for construction that will aid in reducing the risk for mass movement within the subject site.

Due to the presence of a mapped landslide deposit near the subject site and the steep grade observed within the subject site, GeoStrata recommends that a geotechnical report that evaluates the slope stability within the subject site is conducted prior to any development. It is the opinion of GeoStrata that landslide hazards should not preclude development at the subject site as long as

## Exhibit B-Geologic Report

a slope stability analysis is conducted as a part of a comprehensive site specific geotechnical investigation for the site that indicates that the planned development will not be affected by potential slope failure. All recommendations to reduce the risks of slope stability hazards contained in the site specific geotechnical report should be followed and incorporated in the design of the site. The recommendations contained in the geotechnical report should be incorporated into the grading and drainage design for the lot. Saturated soil conditions should be considered in the slope stability analysis conducted as a part of a comprehensive site specific geotechnical investigation for the site.

Slope stability of the subject site was not assessed as part of this geological hazard assessment. The subject site was observed to be moderately to steeply sloping to the south toward a nearby drainage (Plate 2 Topographic Map). The possibility that development of the site could negatively affect slope stability within the subject site is increased if development is planned for areas of the site with slopes steeper than approximately 3 horizontal: 1 vertical. It should be noted that grading or development adjacent to the subject site could potentially impact the stability of the area within the subject site and assessment of that hazard is out of the scope of this assessment.

### 6.7 AVALANCHE

An avalanche is a rapid flow of snow down a hill or mountainside. A snow avalanche can be a hazard in high alpine settings with slopes generally between 35 degrees and 45 degrees that accumulate appreciable amounts of snow. There are three types of avalanches: slough, dry slab and wet slab. Sloughs typically occur right after a heavy snowfall event. This type of slide occurs from a single point and accumulates snow as it moves downslope. Dry slabs are the most common type of avalanche and are the result of a fracture that occurs along a weak layer within the snowpack. Dry slabs can travel upwards of 80 mph removing trees and structures in its path. Wet slabs are triggered when percolating water dissolves bonds and decreases the strength of the weak snow layer. This type of slab can travel up to 20 mph. Several factors that influence a snow avalanche include weather, temperature, slope steepness, slope orientation, wind direction and wind loading, terrain, vegetation, and snowpack conditions. Snow avalanche hazard could affect access and snow removal on roads as well as the safety of habitable structures and critical facilities.

Based on review of our stereographic aerial photograph interpretation, our field observations, the slope within and above the subject site is less than 35 degrees as well as avalanche control work

## Exhibit B-Geologic Report

conducted by the Powder Mountain Ski Resort, it is the opinion of GeoStrata that the avalanche hazard within the subject site and it is considered unlikely that a snow avalanche will impact the proposed developed. It is the opinion of GeoStrata that snow avalanche hazards should not preclude development within the subject lot.

### 6.8 ALLUVIAL FAN FLOODING

Alluvial fan flooding is a potential hazard that may exist in areas containing Holocene alluvial fan deposits. This type of flooding typically occurs as a stream flows, hyperconcentrated flows and debris flows consisting of a mixture of water, soil, organic material, and rock debris with variations in sediment-water concentrations transported by fast-moving water flows. Stream flows contains approximately less than 20% sediment by volume and involves sediment transport by entrained and suspended sediment load (Bowman and Lund, 2016). Unconfined stream flows are referred to as sheetfloods which are spread over and occur in the distal areas of the alluvial fan. Hyperconcentrated flows are alluvial fan flows with 20 to 60% sediment by volume whereas debris flows contain greater than 60% sediment by volume.

Alluvial fan flooding can be a hazard on or below alluvial fans or in stream channels above alluvial fans. Precipitation (rainfall and snowmelt) is generally viewed as an alluvial fan flood “trigger”, but this represents only one of the many factors that contribute to alluvial fan flooding hazard. Vegetation, root depth, soil gradation, antecedent moisture conditions and long term climatic cycles all contribute to the generation of debris and initiation of alluvial fan flooding. Events of relatively short duration, such as a fire, can significantly alter a basin’s absorption of storm water and snowmelt runoff and natural resistance to sediment mobilization for an extended period of time. These factors are difficult to quantify or predict and vary not only between different watersheds, but also within each sub-area of a drainage basin. In general, there are two methods by which alluvial fan flooding can be mobilized: 1) when shallow landslides from channel side-slopes are conveyed in existing channels when mixed with water and 2) channel scour where debris is initially mobilized by moving water in a channel and then the mobilized debris continues to assemble and transport downstream sediments.

Based on review of published geologic maps, review of stereographic aerial photographs and hillshades derived from 2016 0.5 meter LiDAR, no Holocene age alluvial fan deposit is mapped within or adjacent to the subject site (Plate 4 Site Vicinity Geologic Map; Plate 5 Site Vicinity 30’ X 60’ Geologic Map). Given our field and office investigations, the alluvial fan flooding hazards within subject site is considered low and it is considered unlikely that debris flows will

## Exhibit B-Geologic Report

impact the proposed development. It is the opinion of GeoStrata that alluvial fan flooding hazard should not preclude development at the subject lot.

### 6.9 SHALLOW GROUNDWATER

Shallow groundwater flooding is a hazard that can cause the flooding of excavated areas where the depth of excavation exceeds the depth of the local water table. Shallow groundwater flooding should be considered when designing habitable structures that require excavation that may exceed the depth to the shallow groundwater.

Shallow groundwater assessment is out of the scope of this study. Seasonal fluctuations in precipitation, rapid snowmelt, surface runoff from adjacent properties, or other on or offsite sources may increase moisture conditions; groundwater conditions can be expected to rise several feet seasonally depending on the time of year. A trench was excavated within the subject site and to a depth of approximately 9 feet below existing grade. No water was observed at the time of our site visit. Groundwater potential will be evaluated and discussed further in the geotechnical study compiled for the subject site.

### 6.10 STREAM FLOODING HAZARD

Stream flooding can be caused by precipitation, snowmelt or a combination of both. Throughout most of Utah floods are most common in spring during the snowmelt. High flows in drainages can last for a few hours to several weeks. Factors that affect the potential for flooding at a site include surface water drainage patterns and hydrology, site grading and drainage design, and seasonal runoff.

Based on review of our stereographic aerial photograph interpretation, our review of the hillshades derived from 2016 0.5 meter LiDAR and our field observations, a drainage is located in the downslope and southwest of the subject site (Plate 8 Hydrology Map). Given our field and office investigations, the stream flooding hazard within the subject lot is considered low and it is considered unlikely that stream flooding will impact the proposed development. It is the opinion of GeoStrata that stream flooding hazard should not preclude development at the subject site. Proper site grading and drainage plans should be developed for the subject site as a part of the civil engineering design for the site to mitigate the potential for stream flooding to impact and damage planned structures or other planned associated infrastructure.

## Exhibit B-Geologic Report

### 6.11 CANAL FLOODING

High runoff in a short period of time can lead to canal water breaching their banks and flooding the surrounding area. Failure of the canal embankments or a blockage in the canal could also lead to flooding surrounding the canal.

Based on review of published topographic maps, our stereographic aerial photograph interpretation, our review of the hillshades derived from 2016 0.5 meter LiDAR and our field observations, no canals were observed or are mapped within or adjacent to the subject site. Given our field and office investigations, the canal flooding hazard within the subject lot is considered low and it is considered unlikely that canal flooding will impact the proposed development. It is the opinion of GeoStrata that canal flooding hazard should not preclude development at the subject lot.

### 6.12 DAM FAILURE

Dams are structures that store water and diverge and impound water upstream. Most dams have a spillway where water flow from the reservoir is controlled and hydroelectric power is produced. Failure in dams can occur from a collapse or a breach in the structure most commonly due to extended periods of high runoff.

Based on our review of the Mantua, James Peak, Sharp Mountain and Huntsville topographic quadrangles and our field investigation, no dams or reservoirs are located up-gradient of the subject site (Plate 1 Site Vicinity Map; Plate 2 Topographic Map). Given our field and office investigations, the dam failure hazard within the subject lot is considered low and it is considered unlikely that dam failure will impact the proposed development. It is the opinion of GeoStrata that dam failure hazard should not preclude development at the subject lot.

### 6.13 PROBLEM SOILS

Problem soils include collapsible soils and expansive soils. Collapsible soils are low density and typically dry soils that decrease in volume when exposed to water. This type of problem soil typically occurs in alluvial fan flooding deposits, dry loess or eolian deposits or unconsolidated colluvium deposits (Owens and Rollins, 1990). Expansive soils are soils that undergo an increase in volume upon wetting and typically include fine grained soils such as clay.

## Exhibit B-Geologic Report

The problem soils hazard is out of the scope of this study. Based on our review of published geologic maps and our field observations, the subject site is underlain by granular soils. No laboratory testing was performed on these soils as part of this study and therefore this hazard was not assessed as part of this study. A geotechnical study will be completed for the subject site in order to understand soil properties for use in the design of footing, foundation elements and grading.

### 6.14 RADON

Radon is a naturally occurring odorless, tasteless and colorless gas that is released during the breakdown of uranium in well drained permeable soils and uranium rich rocks which include granite, metamorphic rocks, black shales, and some volcanic rocks (Sprinkel and Solomon, 1990). Radon gas moves freely in the air and can also dissolve in water which can potentially migrate through cracks and open spaces in rock, soils, and foundations as well as utility pipes.

The radon gas hazard is out of the scope of this study. No published data that covers the area of the subject sites currently exists. Indoor testing following construction is recommended for determining radon gas levels and mitigation methods needed.

### 6.15 KARST AND SINK HOLES

A karst is a type of underground drainage terrain that is the result of dissolution of soluble bedrock such as limestone, carbonate rock, salt beds or other types of rocks that are easily dissolved by groundwater circulating through them. The most common type of hazard that forms within a karst terrain is subsidence or collapse of soils, these are referred to as sink holes. Sink holes can be a few feet to hundreds of acres wide and 1 to 100 feet deep and can form slowly or collapse suddenly.

Based on our review of published geologic maps, the karst and sink holes hazards within the subject site are considered low and it is unlikely that karst and sink holes hazards will impact the proposed development. It is the opinion of GeoStrata that karst and sink hole hazards should not preclude development at the subject lot.

### **7.0 GEOLOGIC HAZARDS SUMMARY AND CONCLUSIONS**

It is the opinion of GeoStrata that the geologic hazards that we assessed in this study that could impact the subject site or that have not been assessed as a part of this study, but which could impact the subject site include: landslide, shallow groundwater, problem soils and radon gas. Below is a summary of each geologic hazard and GeoStrata's recommendation for mitigation:

- Landslide, slump and creep hazard within the subject site was assessed as part of this study. It is the opinion of GeoStrata that the landslide hazard within the subject site is considered low to moderate. GeoStrata recommends that a slope stability analysis is performed by a professional engineer as part of a comprehensive site specific geotechnical investigation to assess the potential for slope failure. Slope stability modeling should take landslide deposits and potential landslide deposits into consideration and evaluate all portions of the subject site being considered for development to provide recommendations for construction that will aid in reducing the risk for mass movement within the subject site.

It is the opinion of GeoStrata that landslide hazards should not preclude development at the subject site as long as a slope stability analysis is conducted as a part of a comprehensive site specific geotechnical investigation for the site and that indicates that the planned development will not be affected by potential slope failure and that all recommendations to reduce the risks of slope stability hazards contained in the site specific geotechnical report are followed. Saturated soil conditions should be considered in the slope stability analysis conducted as a part of a comprehensive site specific geotechnical investigation for the site.

Slope stability of the subject site was not assessed as part of this geological hazard assessment. The subject site was observed to be moderately to steeply sloping to the south toward a nearby drainage (Plate 2 Topographic Map). The possibility that development of the site could negatively affect slope stability within the subject site is increased if development is planned for areas of the site with slopes steeper than approximately 3 horizontal: 1 vertical. It should be noted that grading or development adjacent to the subject site could potentially impact the stability of the area within the subject site and is out of the scope of this assessment. Due to the presence of mapped landslide deposits near the subject site and the steep grade observed within the subject site, GeoStrata recommends that a geotechnical report that evaluates the slope stability within the subject

## Exhibit B-Geologic Report

site is conducted prior to any development and the recommendations contained in the geotechnical report be followed as a part of the grading and drainage design for the lot.

- Shallow groundwater hazard within the subject site was not assessed as part of this study. Seasonal fluctuations in precipitation, rapid snowmelt, surface runoff from adjacent properties, or other on or offsite sources may increase moisture conditions; groundwater conditions can be expected to rise several feet seasonally depending on the time of year. A trench was excavated within the subject site and to a depth of approximately 9 feet below existing grade. No water was observed at the time of our site visit. Groundwater potential will be evaluated and discussed further in the geotechnical study compiled for the subject site.
- Problem soils hazard within the subject site was not assessed as part of this study. The subject site is underlain by gravel, cobbles and boulders in a matrix of silt and sand. No laboratory testing was performed on these soils as part of this study and therefore this hazard was not assessed as part of this study. A geotechnical study will be completed for the subject site in order to understand soil properties for use in the design of footing, foundation elements and grading.
- The radon gas hazard is out of the scope of this study. No published data that covers the area of the subject sites currently exists. Indoor testing following construction is recommended for determining radon gas levels and mitigation methods needed.

It is the opinion of GeoStrata that these hazards should not preclude the development of the subject site, assuming that these recommendations given above will be followed.



### 8.0 CLOSURE

#### 8.1 LIMITATIONS

The conclusions and recommendations contained in this report, which include professional opinions and judgments, are based on the information available to us at the time of our evaluation, the results of our field observations and our understanding of the proposed site development. If any conditions are encountered at this site that are different from those described in this report, our firm should be immediately notified so that we may make any necessary revisions to recommendations contained in this report. In addition, if the scope of the proposed development changes from that described in this report, our firm should also be notified.

All services were completed in accordance with the current standard of care and generally accepted standard of practice at the time and in the place our services were completed. No other warranty, expressed or implied, is made. Development of property in the immediate vicinity of geologic hazards involves a certain level of inherent risk. It is impossible to predict where geologic hazards will occur. New geologic hazards may develop and existing geologic hazards may expand beyond their current limits.

All services were performed for the exclusive use and benefit of the above addressee. No other person is entitled to rely on GeoStrata's services or use the information contained in this letter without the express written consent of GeoStrata. We are not responsible for the technical interpretations by others of the information described or documented in this report. The use of information contained in this report for bidding purposes should be done at the Contractor's option and risk.

### 9.0 REFERENCES CITED

- Black, B.D., Hecker, S., Hylland, M.D., Christenson, G.E., and McDonald G.N., 2003, Quaternary Fault and Fold Database and Map of Utah: Utah geological Survey Map 193DM.
- Bowman, S.D., Lund, W.R., 2016, Guidelines for Investigating Geologic Hazards and Preparing Engineering-Geology Reports, with a Suggested Approach to Geologic-Hazard Ordinances in Utah: Utah Geological Survey, Circular 122, p. 195.
- Christenson, G. E., Batatian, L. D. and Nelson C. V. 2003, Guidelines for Evaluating Surface-Fault-Rupture Hazards in Utah: Utah Geological Survey Miscellaneous Publication 03-6, p 11.
- Coogan, J.C., King, J.K., 2016, Interim Geologic Map of the Ogden 30' X 60' Quadrangle, Box, Elder, Cache, Davis, Morgan, Rich, and Summit Counties, Utah: Utah Geological Survey Map OFR 653DM, scale: 1:100,000.
- Crittenden, M.D., 1972, Geologic Map of the Browns Hole Quadrangle, Utah: Utah Geological Survey Map GQ-968, scale: 1:24,000.
- Elliot, A.H., Harty, K.M., 2010, Landslide Maps of Utah, Ogden 30' X 60' Quadrangle: Utah Geological Survey Map 246DM.
- Hintze, L.F. 1993, Geologic History of Utah, Brigham Young University Studies, Special Publication 7, p 202.
- Hintze, L.F., 1980, Geologic Map of Utah: Utah Geological and Mineral Survey Map-A-1, scale 1:500,000.
- King, J.K., Yonkee, W.A., Coogan, J.C., 2008, Interim Geologic Map of the Snow Basin Quadrangle and Part of the Huntsville Quadrangle, Davis, Morgan, and Weber Counties, Utah: Utah Geological Survey Map OFR-536, scale 1:24,000.
- Legette, R.M., Taylor, G.H., 1937, Water-Supply Paper 796-D, Geology and Ground-Water Resources of Ogden Valley, Utah: Department of Interior, p 130.
- Scott, W.E., McCoy, W.D., Shorba, R.R., and Rubin, Meyer, 1983, Reinterpretation of the exposed record of the last two cycles of Lake Bonneville, western United States: Quaternary Research, v.20, p 261-285.
- Smith, R.B., and Arabasz, W.J., 1991, Seismicity of the Intermountain Seismic Belt, in Slemmons, D.B., Engdahl, E.R., Zoback, M.D., and Blackwell, D.D., editors, Neotectonics of

## Exhibit B-Geologic Report

North America: Geological Society of America, Decade of North American Geology Map v. 1, p. 185-228.

Sorensen, M.L., Crittenden, M.D., 1979, Geologic Map of the Huntsville Quadrangle, Weber and Cache Counties, Utah: Utah Geological Survey Map GQ-1503, scale 1:24,000.

Stokes, W.L., 1986, Geology of Utah: Utah Museum of Natural History and Utah Geological and Mineral Survey Occasional Paper Number 6, p 280.

U.S. Geological Survey and Utah Geological Survey, 2016, Quaternary fault and fold database for the United States, accessed July 2018, from USGS website: <http://earthquake.usgs.gov/hazards/qfaults/>.

# Appendix



# Exhibit B-Geologic Report




## Legend

 Approximate Site Boundary

0 1,500 3,000 6,000 9,000 12,000 Feet

1 inch = 4,000 feet

Base Map:  
2009 1 meter NAIP aerial imagery and hillshades derived  
from 5 meter digital elevation model (DEM) provided by the  
State of Utah AGRC.



# GeoStrata

Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005


Page 91 of 98

Site Vicinity Map

Plate  
1




# Exhibit B-Geologic Report



Approximate Site Location

## Legend


 Approximate Site Boundary

0 750 1,500 3,000 4,500 6,000 Feet

1 inch = 2,000 feet

Base Map:

Browns Hole, Huntsville, James Peak and Sharp Mountain Quadrangles, Utah 7.5 Minute Series (Topographic), USGS and hillshades derived from 5 meter DEM provided by the State of Utah AGRC.



# GeoStrata

Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005

Page 92 of 98

Topographic Map


Plate  
2




# Exhibit B-Geologic Report



## Legend


 Approximate Site Boundary



1 inch = 200 feet

Base Map:

Hillshades derived from 2016 0.5 meter LiDAR provided by the State of Utah AGRC.



# GeoStrata

Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005


Page 93 of 98

**Hillshade Map**

**Plate  
3**



# Exhibit B-Geologic Report




Approximate Site Boundary

Generalized  
8630  
attitude


**TKwe** WASATCH AND EVANSTON(?) FORMATIONS, UNDIVIDED (Eocene, Paleocene, and Upper Cretaceous?) – Unconsolidated pale-reddish-brown pebble, cobble, and boulder conglomerate; forms boulder-covered slopes. Clasts are mainly Precambrian quartzite and are tan, gray, or purple; matrix is mainly poorly consolidated sand and silt; thickness 0-150 m

**Em** MAXFIELD(?) LIMESTONE (Middle Cambrian) – Upper part thin-bedded, finely crystalline, medium- to dark-gray, ledge-forming dolomite, often with intercalated light-gray silty limestone; near top of unit, includes distinctive light-gray to white laminated dolomite, underlain by light- and dark-gray mottled limestone. Middle part dominantly olive-drab to greenish-brown micaceous shale, with interbedded medium- to dark-gray limestone, overlain by medium- to dark-gray, cliff-forming platy limestone. Lower part dark-blue-gray, light-gray-weathering, cliff-forming limestone and dolomite, with intercalated reddish-gray silty limestone; underlain by 30 m thin-bedded, light-blue-gray, slope-forming limestone and shaly limestone, with some greenish-olive-drab shale. Base of lower unit is finely crystalline, medium-blue-gray, light-gray-weathering limestone, commonly with intercalated tan to orange-brown silty limestone, and locally containing orange-brown oolites near top. Upper and middle parts of formation exposed in Huntsville quadrangle; lower part exposed in North Ogden quadrangle; thickness 290 m




## Legend

Approximate Site Boundary



1 inch = 2,000 feet  
Base Map:

Geologic Map of the Browns Hole Quadrangle, Utah, Crittenden, 1972. Geologic Map of the Huntsville Qudrangle, Weber and Cache Counties, Utah, Sorensen and Crittenden, 1970. Hillshades derived from 2016 0.5 meter LiDAR provided by the State of Utah AGRC.




Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005  
**Site Vicinity Geologic Map**

**Plate**  
**4**



# Exhibit B-Geologic Report



Approximate Site Boundary


Qms, Qms?, Qmsy, Qmsy?, Qmso, Qmso?  
**Landslide deposits (Holocene and upper and middle? Pleistocene)** – Poorly sorted clay- to boulder-sized material; includes slides, slumps, and locally flows and floods; generally characterized by hummocky topography, main and internal scarps, and chaotic bedding in displaced blocks; composition depends on local sources; morphology becomes more subdued with time and amount of water in material during emplacement; Qms may be in contact with Qms when landslides are different/distinct; thickness highly variable, up to about 20 to 30 feet (6-9 m) for small slides, and 80 to 100 feet (25-30 m) thick for larger landslides. Qmsy and Qmso queried where relative age uncertain; Qms queried where classification uncertain. Numerous landslides are too small to show at map scale and more detailed maps shown in the index to geologic mapping should be examined.

Tw, Tw?  
**Wasatch Formation (Eocene and upper Paleocene)** – Typically red to brownish-red sandstone, siltstone, mudstone, and conglomerate with minor gray limestone and marlstone locally; conglomerate clasts mainly rounded Neoproterozoic and Paleozoic sedimentary rocks, typically Neoproterozoic and Cambrian quartzite; basal conglomerate more gray and less likely to be red, and contains more locally derived angular clasts of limestone, dolomite and sandstone, typically from Paleozoic strata; lighter shades of red, yellow, tan, and light gray present locally and more common in uppermost part of Wasatch strata, complicating mapping of contacts with overlying similarly colored Norwood and Fowkes Formations; greatest thickness about 5000 to 6000 feet (1500-1800 m) southeast of Morgan and thinner to north and west with about 2500 feet (760 m) exposed in Peterson quadrangle; thinner east of leading edge of Willard thrust sheet, typically 600 feet (180 m) thick or less in Lost Creek drainage, and up to about 800 feet (240 m) thick in Meachum Ridge quadrangle; thicknesses vary locally due to considerable relief on basal erosional surface, for example along leading edge of Willard thrust, and also note onlap of Wasatch strata north and south of Round Valley, east of Morgan. The Wasatch Formation is at least locally prone to slope failures.

+ Syncline, upright, concealed    — Bedding, strike & dip, upright


## Legend

Approximate Site Boundary



1 inch = 2,000 feet  
 Base Map:

Interim Geologic Map of the Ogden 30' x 60' Quadrangle, Box Elder, Cache, Davis, Morgan, Rich, and Summit Counties, Utah and Uinta County, Wyoming, Coogan and King, 2016. Hillshades derived from 5 meter DEM provided by the State of Utah AGRC.




Copyright GeoStrata 2018

Geologic Hazards Assessment  
 Lot 70R Summit Eden Phase 1C  
 8492 East Spring Park Road  
 Eden, Utah  
 Project Number: 594-005  
**Site Vicinity 30x60 Geologic Map**

**Plate**  
**5**






Approximate Site Boundary

Ogden Valley Northeastern Margin fault

**Legend**

- Approximate Site Boundary
- Quaternary Faults**
- <150 Years, Well Constrained
- <15,000 Years, Well Constrained
- <15,000 Years, Moderately Constrained
- <15,000 Years, Inferred
- <130,000 Years, Well Constrained
- <130,000 Years, Moderately Constrained
- <130,000 Years, Inferred
- <750,000 Years, Well Constrained
- <750,000 Years, Moderately Constrained
- <750,000 Years, Inferred
- <2.6 Million Years, Well Constrained
- <2.6 Million Yeras, Moderately Constrained
- <2.6 Million Years, Inferred


bar and ball symbol on the downthrown side



1 inch = 2,500 feet

Base Map:

UGS Quaternary Fold and Fault Database. 2009 1 meter NAIP aerial imagery and hillshades derived from 5 meter DEM provided by the State of Utah AGRC.




**GeoStrata**  
Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005  
**Quaternary Fault Map**

**Plate**  
**6**




# Exhibit B-Geologic Report





Approximate Site Boundary


## Legend


 Approximate Site Boundary


## Landslide Type

 deep or unclassified landslide


 landslide and/or landslide undifferentiated from talus, colluvial, rock-fall, glacial, and soil-creep deposits

 landslide undifferentiated from talus and/or colluvial deposits

 lateral spread and/or flow failure

 not classified

 shallow landslide

 Landslide Scarp


 Debris Flow Path

0 750 1,500 3,000 4,500 6,000 Feet

1 inch = 2,000 feet

Base Map:

UGS Quaternary Fold and Fault Database. Hillshades derived from 5 meter DEM provided by the State of Utah AGRC.



**GeoStrata**

Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005

Page 97 of 98

**Landslide Hazard Map**



**Plate**  
7




# Exhibit B-Geologic Report



## Legend


-  Approximate Site Boundary
-  Stream (National Hydrology Dataset)



1 inch = 2,000 feet

Base Map:

National Hydrology Dataset, 2009 1 meter NAIP aerial imagery and hillshades derived from 5 meter DEM provided by the State of Utah AGRC.



# GeoStrata

Copyright GeoStrata 2018

Geologic Hazards Assessment  
Lot 70R Summit Eden Phase 1C  
8492 East Spring Park Road  
Eden, Utah  
Project Number: 594-005

Page 98 of 98

**Hydrology Map**

**Plate  
8**