

Intermountain GeoEnvironmental Services, Inc.

12429 South 300 East, Suite 100, Draper, Utah 84120 Phone (801) 748-4044 ~ F: (801) 748-4045 www.igesinc.com

GEOTECHNICAL AND GEOLOGIC HAZARD INVESTIGATION Lot 74R of Summit Eden Phase 1C 8464 E. Spring Park Road Summit Powder Mountain Resort Weber County, Utah

IGES Project No. 02565-001

June 22, 2018

Prepared for:

Mr. Michael Silver



Mr. Michael Silver 10884 Weyburn Avenue Los Angeles, California 90024

Geotechnical and Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C 8464 E. Spring Park Road Summit Powder Mountain Resort Weber County, Utah


IGES Project No. 02810-001

No. 6370734

Prepared by:

David A. Glass, P.E.

Senior Geotechnical Engineer



Peter E. Doumit, P.G., C.P.G. Senior Geologist

IGES, Inc.

12429 South 300 East, Suite 100 Draper, Utah 84120 (801) 748-4044

June 22, 2018

TABLE OF CONTENTS

1.0	INTR	ODUCTION	1
1	1 PI II	RPOSE AND SCOPE OF WORK	1
		DJECT DESCRIPTION	
2.0	MET	HODS OF STUDY	2
2	.1 LIT	ERATURE REVIEW	2
_		Geotechnical	
	2.1.2	Geological	
2	.2 FIE	LD INVESTIGATION	2
2	.3 LA	BORATORY TESTING	3
3.0	GEO	LOGIC CONDITIONS	4
3	.1 GE	NERAL GEOLOGIC SETTING	4
3	.2 SU	RFICIAL GEOLOGY	4
3	.3 HY	DROLOGY	5
3	.4 GE	OLOGIC HAZARDS FROM LITERATURE	6
	3.4.1	Landslides	6
	3.4.2	Faults	6
	3.4.3	Debris Flows	6
	3.4.4	Liquefaction	
3		VIEW OF AERIAL IMAGERY	
		SMICITY	
3		OLOGIC HAZARD ASSESSMENT	
	3.7.1	Landslides/Mass Movement	
	3.7.2	Rockfall	
	3.7.3	Surface-Fault Rupture and Earthquake-Related Hazards	
	3.7.4 3.7.5	Liquefaction	
		Debris-Flows and Flooding Hazards	
4.0	GENI	ERALIZED SITE CONDITIONS	11
4	.1 SIT	E RECONNAISSANCE	11
4	.2 SU	BSURFACE CONDITIONS	11
	4.2.1	Earth Materials	11
	4.2.2	Groundwater	12
4		OPE STABILITY	
		Global Stability	
	4.3.2	Surficial Stability	13
5.0	CON	CLUSIONS AND RECOMMENDATIONS	15

5.1 GENI	ERAL CONCLUS	IONS	15
5.2 GEOI	LOGIC CONCLU	SIONS AND RECOMMENDATIONS	15
5.3 EAR	THWORK		16
5.3.1	General Site Prepar	ration and Grading	16
5.3.2 H	Excavations		16
5.3.3 H	Excavation Stabilit	y	17
		Compaction	
	•	kfill	
		MMENDATIONS	
	•	nt	
		AND LATERAL RESISTANCE	
		N-GRADE CONSTRUCTION	
		CION AND SURFACE DRAINAGE	
		OTENTIAL	
		NSIDERATIONS	
5.10.2	roundwater		22
6.0 CLOSU	RE		24
6.1 LIMI	ΓATIONS		24
6.2 ADD	TIONAL SERVI	CES	25
7.0 REFER	ENCES		26
APPENDICE	ES		
Appendix A	Figure A-1	Site Vicinity Map	
	Figure A-2	Local Geology and Geotechnical Map	
	Figure A-3	Test Pit Log	
	Figure A-4	Key to Soil Symbols and Terminology	
	Figure A-5	Key to Physical Rock Properties	
	Figure A-6	Regional Geology Map 1	
	Figure A-7	Regional Geology Map 2	
	Figure A-8	Regional Geology Map 3	
Appendix B	Laboratory Test	Results	
Appendix C		e Spectra (Design Maps Output)	
Appendix D	Slope Stability A	Analysis	

1.0 INTRODUCTION

1.1 PURPOSE AND SCOPE OF WORK

This report presents the results of a geotechnical and geologic hazard investigation conducted for Lot 74R of Summit Eden Phase 1C, part of the currently on-going expansion at the Powder Mountain Ski Resort in Weber County. The purpose of our investigation was to assess the nature and engineering properties of the subsurface soils at the project site and to provide recommendations for the design and construction of foundations, grading, and drainage. In addition, geologic hazards have been assessed for the property. The scope of work completed for this study included literature review, site reconnaissance, subsurface exploration, engineering analyses, and preparation of this report.

Our services were performed in accordance with our proposal dated April 18, 2018, and your signed authorization. The recommendations presented in this report are subject to the limitations presented in the "Limitations" section of this report (Section 6.1).

1.2 PROJECT DESCRIPTION

Our understanding of the project is based primarily on our previous involvement with the Summit Powder Mountain Resort project, which included two geotechnical investigations for the greater 200-acre Powder Mountain Resort expansion project (IGES, 2012a and 2012b), as well as numerous lot-specific and site-specific geotechnical and geologic hazard investigations in various locations across the greater Powder Mountain Resort expansion area.

The Summit Powder Mountain Resort expansion project is located southeast of SR-158 (Powder Mountain Road), south of previously developed portions of Powder Mountain Resort, in unincorporated Weber County, Utah (Figure A-1, *Site Vicinity Map*). The Summit Powder Mountain project area is accessed by Powder Ridge Road. Lot 74R is located within Phase 1C of the Powder Mountain expansion project (Summit Eden), on the south side of Summit Pass – the street address is 8464 East Spring Park Road. The 0.172-acre residential lot has an approximate buildable area (building envelope) of 4,420 square feet. The proposed improvements will include a single-family home, presumably a high-end vacation home, with associated improvements such as utilities and hardscape. Construction plans were not available for our review; however, based on our experience in this area, the new home will likely be a two- to three-story structure, the lowest story consisting of a partial walk-out basement, founded on conventional spread footings. Foundation loads are expected to be on the order of 1,500 psf or less.

2.0 METHODS OF STUDY

2.1 LITERATURE REVIEW

2.1.1 Geotechnical

The earliest geotechnical report for the area is by AMEC (2001), which was a reconnaissance-level geotechnical and geologic hazard study. IGES later completed a geotechnical investigation for the Powder Mountain Resort expansion in 2012 (2012a, 2012b). Our previous work included twenty-two test pits and one soil boring excavated at various locations across the 200-acre development; as a part of this current study, the logs from relevant nearby test pits and other data from our reports were reviewed. IGES has also completed geotechnical/geologic hazard work for other nearby lots, including Lots 71R, 75R, and 44R.

2.1.2 Geological

Several pertinent publications were reviewed as part of this assessment. Sorensen and Crittenden, Jr. (1979) provides 1:24,000 scale geologic mapping of the Huntsville Quadrangle, and Crittenden, Jr. (1972) provides 1:24,000 scale geologic mapping of the Brown's Hole Quadrangle. Coogan and King (2001) provide more recent geologic mapping of the area, but at a 1:100,000 scale. An updated Coogan and King (2016) regional geologic map (1:62,500 scale) provides the most recent published geologic mapping that covers the project area. Western Geologic (2012) conducted a reconnaissance-level geologic hazard study for the greater 200-acre Powder Mountain expansion project, including the Lot 74R area. The Western Geologic (2012) study modified some of the potential landslide hazard boundaries that had previously been mapped at a regional scale (1:100,000) by Coogan and King (2001) and Elliott and Harty (2010). The corresponding United States Geological Survey (USGS) topographic maps for the Huntsville and Brown's Hole Quadrangles (2014) provide physiographic and hydrologic data for the project area. Regional-scale geologic hazard maps pertaining to landslides (Elliott and Harty, 2010; Colton, 1991), faults (Christenson and Shaw, 2008a; USGS and Utah Geological Survey (UGS), 2006), debris-flows (Christenson and Shaw, 2008b), and liquefaction (Christenson and Shaw, 2008c; Anderson et al., 1994) that cover the project area were also reviewed. The Quaternary Fault and Fold Database (USGS and UGS, 2006), was reviewed to identify the location of proximal faults that have had associated Quaternary-aged displacement.

Stereo-paired aerial imagery for the project site and recent and historic Google Earth imagery was also reviewed to assist in the identification of potential adverse geologic conditions. The aerial photographs reviewed are documented in the *References* section of this report.

2.2 FIELD INVESTIGATION

Subsurface soils were investigated by excavating one test pit at a central location within the property boundary. The approximate location of the test pit is illustrated on the *Geotechnical* &

Geology Map (Figure A-2 in Appendix A). The soil types were visually logged at the time of our field work in general accordance with the *Unified Soil Classification System* (USCS). Soil classifications and descriptions are included on the test pit log, Figure A-3 in Appendix A. A key to USCS symbols and terminology is included as Figure A-4, and a key to physical rock properties is included as Figure A-5.

2.3 LABORATORY TESTING

The majority of materials encountered in the test pit consisted of weathered Wasatch Formation, generally disaggregating to clayey sand with abundant gravel- to cobble-size constituents. As such, soil samples suitable for testing in an oedometer could not be obtained. Therefore, laboratory testing and engineering analysis was based largely on previously completed geotechnical investigations (IGES, 2012a & 2012b, IGES 2017, IGES 2018) and laboratory testing for this project that included index testing (grain size analysis). Results of the laboratory testing are discussed in this report and presented in Appendix B.

3.0 GEOLOGIC CONDITIONS

3.1 GENERAL GEOLOGIC SETTING

The Lot 74R property is situated in the western portion of the northern Wasatch Mountains, approximately 4 miles northeast of Ogden Valley. The Wasatch Mountains contain a broad depositional history of thick Precambrian and Paleozoic sediments that have been subsequently modified by various tectonic episodes that have included thrusting, folding, intrusion, and volcanics, as well as scouring by glacial and fluvial processes (Stokes, 1987). The uplift of the Wasatch Mountains occurred relatively recently during the Late Tertiary Period (Miocene Epoch) between 12 and 17 million years ago (Milligan, 2000). Since uplift, the Wasatch Front has seen substantial modification due to such occurrences as movement along the Wasatch Fault and associated spurs, the development of the numerous canyons that empty into the current Salt Lake Valley and Utah Valley and their associated alluvial fans, erosion and deposition from Lake Bonneville, and localized mass-movement events (Hintze, 1988).

The Wasatch Mountains, as part of the Middle Rocky Mountains Province (Milligan, 2000), were uplifted as a fault block along the Wasatch Fault (Hintze, 1988). Ogden Valley itself is a fault-bounded trough that was occupied by Lake Bonneville (Sorensen and Crittenden, Jr, 1979) before being cut through by the Ogden River and subsequently dammed to form the Pineview Reservoir.

The Wasatch Fault and its associated segments are part of an approximately 230-mile long zone of active normal faulting referred to as the Wasatch Fault Zone (WFZ), which has well-documented evidence of late Pleistocene and Holocene (though not historic) movement (Lund, 1990; Hintze, 1988). The faults associated with the WFZ are all normal faults, exhibiting block movement down to the west of the fault and up to the east. The WFZ is contained within a greater area of active seismic activity known as the Intermountain Seismic Belt (ISB), which runs approximately north-south from northwestern Montana, along the Wasatch Front of Utah, through southern Nevada, and into northern Arizona. In terms of earthquake risk and potential associated damage, the ISB ranks only second in North America to the San Andreas Fault Zone in California (Stokes, 1987).

The WFZ consists of a series of ten segments of the Wasatch Fault that each display different characteristics and past movement, and are believed to have movement independent of one another (UGS, 1996). The Lot 74R property is located approximately 10 miles to the northeast of the Weber Segment of the Wasatch Fault, which is the closest documented Holocene-aged (active) fault to the property and trends north-south along the Wasatch Front (USGS and UGS, 2006).

3.2 SURFICIAL GEOLOGY

According to Sorensen and Crittenden, Jr. (1979), the property is entirely underlain by the undivided Tertiary/Cretaceous Wasatch and Evanston Formations (TKwe), described as

"unconsolidated pale-reddish-brown pebble, cobble, and boulder conglomerate, forms bouldercovered slopes. Clasts are mainly Precambrian quartzite and are tan, gray, or purple; matrix is mainly poorly consolidated sand and silt." A generalized bedding attitude shows this unit striking due north and dipping 10 degrees to the east. This map forms the basemap for the Regional Geology Map 1 (Figure A-6). Coogan and King (2001) produced a regional-scale geologic map that covered the property; this map also shows the property to be largely underlain by the Wasatch Formation. Western Geologic (2012) identified a number of landslide deposits contained within the Powder Mountain Resort expansion area (Regional Geology Map 2, Figure A-7). In this map, the property is not located within mapped landslide deposits, though deposits mapped as "mixed slope colluvium, shallow landslides, and talus" are found approximately 100 feet south of the southern margin of the property, with a large Holocene to Late Pleistocene landslide deposit mapped approximately 300 feet south of the southern margin of the property. Finally, Coogan and King (2016) updated their 2001 map, which shows the property to be entirely underlain by the Wasatch Formation (map unit Tw), with landslide deposits located approximately 275 feet southeast of the property (Regional Geology Map 3, Figure A-8). The landslide deposits (Qms) are described as "poorly sorted clay- to boulder-sized material; includes slides, slumps, and locally flows and floods; generally characterized by hummocky topography, main and internal scarps, and chaotic bedding in displaced blocks." Wasatch Formation bedrock in the area is shown to be striking approximately to the north-northeast, and dipping approximately 5 degrees to the eastsoutheast.

3.3 HYDROLOGY

The USGS topographic maps for the Huntsville and Brown's Hole Quadrangles (2014) show that the Lot 74R project area is situated on a slope, with the local topographic gradient down to the southwest towards a larger west-trending ephemeral drainage locally known as Lefty's Canyon (see Figure A-1). No active or ephemeral stream drainages are found on or adjacent to the property, and no springs are known to occur on the property, though it is possible that springs may occur on various parts of the property during peak runoff. Groundwater seepage is known to occur at the base of the slope at the Lot 75R road cut in the spring (IGES, 2017).

Baseline groundwater depths for the Lot 74R property are currently unknown, but are anticipated to fluctuate both seasonally and annually. Localized seeping water was observed in the test pit excavation and observed to be at approximately 12 feet below existing grade. This water source is likely a localized spring or seepage point and may represent a phreatic surface – conditions indicative of a perennial spring were observed in the foundation excavation for the adjacent Lot 75R in May/June of 2018, where water was observed to be continuously flowing along the north side of the excavation for several weeks. A known spring is located approximately 830 feet south-southeast of the property (Figure A-1); it is possible that the Lot 74R and 75R excavations have intersected the hydrologic pathways for this spring.

3.4 GEOLOGIC HAZARDS FROM LITERATURE

Based upon the available geologic literature, regional-scale geologic hazard maps that cover the Lot 74R project area have been produced for landslide, fault, debris-flow, and liquefaction hazards. The following is a summary of the data presented in these regional geologic hazard maps.

3.4.1 Landslides

Two regional-scale landslide hazard maps have been produced that cover the project area. Colton (1991) does not show the property to be underlain by or adjacent to landslide deposits, though south-trending landslide deposits are noted nearby to the west. Elliott and Harty (2010) similarly does not show the property to be located within mapped landslide deposits, though deposits mapped as "Landslide undifferentiated from talus and/or colluvial deposits" are noted both west and south of the property. As noted above, both Western Geologic (2012; Figure A-7) and Coogan and King (2016; Figure A-8) show the property to be located outside of mapped landslide deposits, though mass-movement deposits are mapped both west and south of the property.

3.4.2 Faults

Neither Christensen and Shaw (2008a) nor the Quaternary Fault and Fold Database of the United States (USGS and UGS, 2006) show any Quaternary-aged (~2.6 million years ago to the present) faults to be present on or projecting towards the subject property. The Weber County Natural Hazards Overlay Districts defines an active fault to be "a fault displaying evidence of greater than four inches of displacement along one or more of its traces during Holocene time (about 11,000 years ago to the present)" (Weber County, 2015). The closest active fault to the property is the Weber Segment of the Wasatch Fault Zone, located approximately 10 miles southwest of the western margin of the property (USGS and UGS, 2006).

3.4.3 Debris Flows

Christensen and Shaw (2008b) do not show the project area to be located within a debris-flow hazard special study area.

3.4.4 Liquefaction

Anderson, et al. (1994) and Christensen and Shaw (2008c) both show the project area to be located in an area with very low potential for liquefaction.

3.5 REVIEW OF AERIAL IMAGERY

A series of aerial photographs that cover project area were taken from the UGS Aerial Imagery Collection and analyzed stereoscopically for the presence of adverse geologic conditions across the property. This included a review of photos collected from the years 1946, 1952, and 1963. A table displaying the details of the aerial photographs reviewed can be found in the *References* section at the end of this report.

No geologic lineaments, fault scarps, landslide headscarps, or landslide deposits were observed on the subject property in the aerial photography.

Google Earth imagery of the property from between the years of 1993 and 2017 were also reviewed. No landslide or other geological hazard features were noted in the imagery.

At the time of this report, no LiDAR data for the project area was available to be reviewed.

3.6 SEISMICITY

Following the criteria outlined in the 2015 International Building Code (IBC, 2015), spectral response at the site was evaluated for the *Maximum Considered Earthquake* (MCE) which equates to a probabilistic seismic event having a two percent probability of exceedance in 50 years (2PE50). Spectral accelerations were determined based on the location of the site using the *U.S. Seismic "DesignMaps" Web Application* (USGS, 2012/15); this software incorporates seismic hazard maps depicting probabilistic ground motions and spectral response data developed for the United States by the U. S. Geological Survey as part of NEHRP/NSHMP (Frankel et al., 1996). These maps have been incorporated into both *NEHRP Recommended Provisions for Seismic Regulations for New Buildings and Other Structures* (FEMA, 1997) and the *International Building Code* (IBC) (International Code Council, 2015).

Table 3.6
Short- and Long-Period Spectral Accelerations for MCE

Parameter	Short Period (0.2 sec)	Long Period (1.0 sec)
MCE Spectral Response Acceleration (g)	$S_S = 0.812$	$S_1 = 0.269$
MCE Spectral Response Acceleration Site Class C (g)	$S_{MS} = S_s F_a = 0.873$	$S_{M1} = S_1 F_v = 0.412$
Design Spectral Response Acceleration (g)	$S_{DS} = S_{MS}*^2/_3 = 0.582$	$S_{D1} = S_{M1}*^2/_3 = 0.275$

To account for site effects, site coefficients that vary with the magnitude of spectral acceleration and *Site Class* are used. Site Class is a parameter that accounts for site amplification effects of soft soils and is based on the average shear wave velocity of the upper 100 feet; based on our field exploration and our understanding of the geology in this area, the subject site is appropriately classified as Site Class C (*soft rock*). Based on IBC criteria, the short-period (F_a) coefficient is 1.075 and long-period (F_v) site coefficient is 1.531. Based on the design spectral response accelerations for a *Building Risk Category* of I, II or III, the site's *Seismic Design Category* is D. The short- and long-period *Design Spectral Response Accelerations* are presented in Table 3.6; a

summary of the *Design Maps* analysis is presented in Appendix C. The *peak ground acceleration* (PGA) may be taken as $0.4*S_{MS}$.

3.7 GEOLOGIC HAZARD ASSESSMENT

Geologic hazard assessments are necessary to determine the potential risk associated with particular geologic hazards that are capable of adversely affecting a proposed development area. As such, they are essential in evaluating the suitability of an area for development and provide critical data in both the planning and design stages of a proposed development. The geologic hazard assessment discussion below is based upon a qualitative assessment of the risk associated with a particular geologic hazard, based upon the data reviewed and collected as part of this investigation.

A "low" hazard rating is an indication that the hazard is either absent, is present in such a remote possibility so as to pose limited or little risk, or is not anticipated to impact the project in an adverse way. Areas with a low-risk determination for a particular geologic hazard do not require additional site-specific studies or associated mitigation practices with regard to the geologic hazard in question. A "moderate" hazard rating is an indication that the hazard has the capability of adversely affecting the project at least in part, and that the conditions necessary for the geologic hazard are present in a significant, though not abundant, manner. Areas with a moderate-risk determination for a particular geologic hazard may require additional site-specific studies, depending on location and construction specifics, as well as associated mitigation practices in the areas that have been identified as the most prone to susceptibility to the particular geologic hazard. A "high" hazard rating is an indication that the hazard is very capable of or currently does adversely affect the project, that the geologic conditions pertaining to the particular hazard are present in abundance, and/or that there is geologic evidence of the hazard having occurred at the area in the historic or geologic past. Areas with a high-risk determination always require additional site-specific hazard investigations and associated mitigation practices where the location and construction specifics are directly impacted by the hazard. For areas with a high-risk geologic hazard, simple avoidance is often considered.

The following is a summary of the geologic hazard assessment for the Lot 74R property.

3.7.1 Landslides/Mass Movement

According to the several most recent geologic maps produced that cover the property, the property is not situated within mapped landslide deposits, though landslide deposits have been mapped within 100 to 300 feet southwest of the southern margin of the property boundary (Coogan and King, 2016; Western Geologic, 2012; Elliott and Harty, 2010). Additionally, landslide deposits or geomorphic features indicative of landsliding were not observed on the property in the aerial imagery, during the site reconnaissance, or in the subsurface. Given the geologic data alone, the

risk associated with landslides is considered low to moderate, given the proximity to mapped landslide deposits.

However, shallow groundwater is known to be present downslope during peak runoff in the spring and may possibly be representative of a perennial condition. This condition (possible shallow groundwater) provides an increased risk to slope instabilities. Slope stability modeling as part of our assessment indicates that the slope is stable under current conditions for both static and seismic cases, though surficial instabilities may arise under saturated conditions (see Section 4.3). The slope stability modeling confirms the landslide hazard risk classification for the property as being low to moderate.

3.7.2 Rockfall

Though the property is on a slope, no bedrock outcrops are exposed upslope of the property. As such, the rockfall hazard associated with the property is considered to be low.

3.7.3 Surface-Fault Rupture and Earthquake-Related Hazards

No faults are known to be present on or project across the property, and the closest active fault to the property is the Weber Segment of the Wasatch Fault Zone, located approximately 10 miles to the west of the property (USGS and UGS, 2006). Given this information, the risk associated with surface-fault-rupture on the property is considered low.

The entire property is subject to earthquake-related ground shaking from a large earthquake generated along the active Wasatch Fault. Given the distance from the Wasatch Fault, the hazard associated with ground shaking is considered to be moderate. Proper building design according to appropriate building code and design parameters can assist in mitigating the hazard associated with earthquake ground shaking.

3.7.4 Liquefaction

The site is underlain by the Wasatch Formation, a poorly consolidated sedimentary rock unit (conglomerate). Rock units such as these are not considered susceptible to liquefaction; as such, the potential for liquefaction occurring at the site is considered low.

3.7.5 Debris-Flows and Flooding Hazards

The property does not contain and is not located adjacent to any active or ephemeral drainages. Additionally, there are no debris-flow source areas upslope of the property, and the property is on a consistent slope downhill to the southwest. Given these conditions, the debris-flow and flooding hazard associated with the property is considered to be low.

3.7.6 Shallow Groundwater

Localized seeping water was observed in the test pit excavation at approximately 12 feet below existing grade; similar conditions were observed in the test pit excavated during the geotechnical work for the adjacent Lot 75R (IGES, 2017), as well as in the foundation excavation for Lot 75R in May/June of 2018, where potential perennial spring conditions were observed in the subsurface..

Based on our observations, groundwater is not anticipated to adversely impact the proposed construction provided the basement excavation does not extend more than about 8 to 10 feet below natural grade. However, groundwater levels could rise at any time from several factors, including recent heavy or protracted precipitation, on- or off-site runoff, irrigation, and time of year (e.g., spring run-off). Seeps and/or springs may be present on the foundation excavation during spring run-off, and may also possibly represent a perennial condition, based upon observations made in the foundation excavation from Lot 75R. Should the groundwater become a concern during the proposed construction, IGES should be contacted so that dewatering recommendations may be provided. It is possible that some temporary dewatering could be necessary during construction, depending on the time of year and depth of excavation. Also, constructing the foundations late in the year (July or later) could potentially result in improved conditions and better constructability.

4.0 GENERALIZED SITE CONDITIONS

4.1 SITE RECONNAISSANCE

Mr. Peter E. Doumit, P.G., C.P.G., of IGES conducted reconnaissance of the site and the immediate adjacent properties on May 31, 2018. The site reconnaissance was conducted with the intent to assess the general geologic conditions present across the property, with specific interest in those areas identified in the geologic literature and aerial imagery reviews as potential geologic hazard areas. Additionally, the site reconnaissance provided the opportunity to geologically map the surficial geology of the area. Figure A-2 is a site-specific geologic map of the Lot 74R property and adjacent areas.

At the time of the site reconnaissance and excavation, the lot was in a relatively natural state and was covered with a sparse vegetative cover including native grasses and shrubs. Common variously-sized quartzite cobbles and boulders were observed throughout the site, with the maximum clast size observed to be approximately 5 feet in diameter. The lot drains to the southwest; the gradient of the lot is roughly 3.6H:1V on the upslope side of the lot transitioning to ~5H:1V within the proposed building footprint. On the south end of the lot (where the lot fronts E. Spring Park Road), an approximate 8-foot high, 2H:1V cut slope descends to the south to daylight with the road. Groundwater was observed to be actively seeping from the base of this cut slope at the time of site reconnaissance.

There is about 18 feet of vertical relief across the building envelope. Site-specific geologic mapping of the property found the local geology to be consistent with that as-mapped by Coogan and King (2016), consisting of a relatively thin veneer of topsoil and colluvium that is underlain by the Wasatch Formation (see Figure A-2).

4.2 SUBSURFACE CONDITIONS

On May 31, 2018, a single exploration test pit was excavated in the north-central portion of the lot (see Figure A-2). The test pit was excavated to a depth of approximately 12.5 feet below existing grade with the aid of a Caterpillar 315C tracked excavator. Upon completion of logging, the test pit was backfilled without compactive effort. A detailed log of the test pit is displayed in Figure A-3. Three distinct geologic units were encountered in the subsurface. The soil and moisture conditions encountered during our investigation are discussed in the following paragraphs.

4.2.1 Earth Materials

<u>A/B Soil Horizon</u>: This topsoil unit was found to be between approximately 1.5 feet thick. The unit was a dark yellowish brown, medium stiff, moist, silty CLAY with gravel (CL-ML), with gravel and larger-sized quartzite clasts comprising between approximately 10 and 20% of the unit. The topsoil was found to be forming upon the underlying colluvium unit.

<u>Colluvium:</u> This unit was approximately 1½ feet thick. The unit consisted of a dark yellowish brown, loose to medium stiff, moist, sandy lean CLAY with gravel (CL). Gravel and larger-sized subrounded to subangular quartzite clasts comprised between approximately 30 and 40% of the unit. Individual clasts were as much as 10 inches in diameter, though the mode clast size was approximately 3 to 5 inches in diameter. The unit also contained a topsoil matrix.

Wasatch Formation: This unit was at least 11 feet thick and extended to the maximum depth of exploration within the test pit. The unit consisted of weakly consolidated conglomerate bedrock that had been largely disaggregated into a moderate reddish brown, medium-dense to dense, moist to wet mixture of clay, sand, and gravel that collectively classifies as silty SAND with gravel (SM) grading to poorly-graded GRAVEL with silt and sand (GP-GM). Gravel and larger-sized subrounded quartzite clasts comprised between approximately 30 and 65% of the unit, with individual clasts up to 21 inches in diameter, with a mode clast size of 2 to 4 inches. The basal approximately 2 feet of the unit exposed in the test pit consisted primarily of fine- to medium-grained sand from which groundwater was actively seeping.

4.2.2 Groundwater

Localized seeping water was observed in the test pit excavation and observed to be at approximately 12 feet below existing grade. This water source is likely a localized spring or seepage point and may represent a local phreatic surface.

4.3 SLOPE STABILITY

4.3.1 Global Stability

The stability of the existing natural slope has been assessed in accordance with methodologies set forth in Blake et al. 2002 and AASHTO LRFD for Bridge Design Specifications with respect to a representative cross-section, illustrated on Plate D-1 in Appendix D (the section is identified in planview on Figure A-2). The stability of the slope was modeled using SLIDE, a computer application incorporating (among others) Spencer's Method of analysis. Calculations for stability were developed by searching for the minimum factor of safety for a translational-type failure occurring through surficial soils (colluvium), just above the underlying conglomerate bedrock, plus a second analysis modeling a circular-type failure mode. Analysis was performed for both static and seismic (pseudo-static) cases.

Groundwater, e.g. a piezometric groundwater surface, was not encountered during our subsurface investigation; however, seepage was noted in the test pit, potentially a perennial spring, as well as the test pit for Lot 75R (IGES, 2017). To assess the potential impact of shallow groundwater, groundwater was also modeled in our limit-equilibrium analysis, assumed to be at a depth of 10 feet below exiting grade (localized). Saturated parallel seepage has been modeled in a separate analysis (see Section 4.3.2).

Soil strength parameters were selected based on soil types observed, local experience, correlation with index properties (Atterberg Limits, clay content), and an evaluation of soil strength laboratory data from a nearby sites. Based on this assessment, the following soil strength parameters were selected for this analysis:

Table 4.3.1a Soil Strength Parameters

Earth Materials	Friction angle (degrees)	Cohesion (psf)	Unit Weight (pcf)
Colluvium (Qc)	30	100	120
Bedrock (Tw)	40	100	130
Embankment Fill (Af)	37	75	125

Pseudo-static (seismic screening) analysis of the proposed slope was performed in general conformance with Blake et al. 2002, ASCE 7-10 and AASHTO LRFD for Bridge Design Specifications. The design seismic event was taken as the ground motion with a 2 percent probability of exceedance in 50 years (2PE50). Based on information provided on the USGS website ground motion calculator, the Peak Ground Acceleration (PGA) associated with a 2PE50 event is estimated to be 0.35g. Half of the PGA, (0.17g), was taken as the horizontal seismic coefficient (kh) (Hynes and Franklin, 1984), and used in the pseudo-static seismic screen analysis. The results of the analyses have been summarized in Table 4.3.1b.

Table 4.3.1b
Results of Slope Stability Analyses

Analysis	Static Factor of Safety	Pseudo-Static Factor of Safety
Existing Condition, circular	2.51	1.67
Existing Condition, translational	3.25	1.88

The results of the analysis indicated the existing conditions meet the minimum required factors-of-safety of 1.5 and 1.0 for both the static and seismic (pseudo-static) case, respectively. The planned improvements will likely include a basement level, which would tend to unload the slope and further improve the stability of the slope; significant fill placement on the slope, which would tend to load the slope and decrease stability, is not anticipated. Since the controlling failure surfaces tended to exit at the toe of the slope at street level, the impact of assuming groundwater at 10 feet was negligible. A summary of the slope stability analysis is presented in Appendix D.

4.3.2 Surficial Stability

Our subsurface investigation indicates that the near-surface soils generally consist of sandy lean clay with gravel (CL). Material identified as 'topsoil' (A/B Horizon) is generally on the order of

18 inches thick; the topsoil has developed on the prevailing colluvial cover, and therefore consists largely of gravelly clay, but with a higher organic component (abundant roots).

IGES assessed the potential for the upper four feet to become mobilized under saturated parallel seepage conditions. Our assessment assumes four feet of clayey colluvium or topsoil, fully saturated, and a 3.5H:1V slope (this would be a transient condition that could occur during primary spring run-off and snowmelt). Our model assumes an estimated effective friction angle of 30 degrees and a cohesion of 100 psf, and a saturated unit weight of 136 pcf. Based on this model, a factor-of-safety of 1.79 results. Sample calculations are presented in Appendix D.

Our calculations do not take into account the beneficial effects of plant roots, which were commonly observed throughout the topsoil units. Many of the existing natural slopes are thickly vegetated, which is expected to reduce the likelihood of shallow surficial slope instability.

Based on our infinite slope model, and the foregoing discussion, IGES considers the potential for surficial slope instability on this site to be low.

5.0 CONCLUSIONS AND RECOMMENDATIONS

5.1 GENERAL CONCLUSIONS

Based on the results of the field observations, literature review, and slope stability analyses, the subsurface conditions are considered suitable for the proposed development provided that the recommendations presented in this report are incorporated into the design and construction of the project.

Supporting data upon which the following conclusions and recommendations are based have been presented in the previous sections of this report. The recommendations presented herein are governed by the physical properties of the earth materials encountered in the subsurface explorations. If subsurface conditions other than those described herein are encountered in conjunction with construction, and/or if design and layout changes are initiated, IGES must be informed so that our recommendations can be reviewed and revised as deemed necessary.

5.2 GEOLOGIC CONCLUSIONS AND RECOMMENDATIONS

Based upon the data collected and reviewed as part of the geologic hazard assessment, IGES makes the following conclusions regarding the geological hazards present at the Lot 74R project area:

- The Lot 74R project area does appear to have geological hazards that are capable of adversely impacting the development as currently proposed under the existing conditions, in the form of a shallow underground spring. However, the shallow spring observed may be a seasonal condition, and/or can be appropriately mitigated with adequate draining if found to be a perennial condition.
- Shallow groundwater conditions were observed in the test pit, and groundwater seepage was observed emanating from the cut slope on the southern end of the lot during the site reconnaissance. Additionally, significant groundwater flow was observed to be entering the foundation excavation on the adjacent Lot 75R in May/June of 2018, possibly representing a perennial spring. As such, shallow groundwater conditions represent a considerable geologic hazard risk to development of the property.
- Though recent geologic mapping shows the site to be located near landslide deposits, no
 evidence of landsliding was observed on the surface or subsurface of the property.
 Therefore, the risk of landslide hazards is considered to be low to moderate, but should not
 be considered zero given the proximity to mapped landslide deposits and existing shallow
 groundwater conditions.
- Earthquake ground shaking may potentially affect all parts of the project area and is considered to pose a moderate risk.

• Rockfall, surface-fault-rupture, liquefaction, debris-flow, and flooding hazards are considered to be low for the property.

Given the conclusions listed above, IGES makes the following recommendations:

- Given the nature of the shallow groundwater conditions, foundation drains should be installed across every planned subgrade level. Temporary drains may need to be used during construction operations to minimize groundwater seepage onto the foundation excavation. Alternatively, an on-grade structure (no basement) would preclude the need for extensive shallow groundwater mitigation.
- Because landslide deposits are noted near the property, an IGES engineering geologist or geotechnical engineer should observe the foundation excavation to assess the absence (or presence) of landslide-induced shearing.
- Effort should be made to limit the introduction of water into the subsurface near the proposed residence. Appropriate grading and drainage away from the home and xeriscape or natural landscaping will assist in reducing the risk of landsliding.

5.3 EARTHWORK

5.3.1 General Site Preparation and Grading

Below proposed structures, fills, and man-made improvements, all vegetation, topsoil, debris and undocumented fill (if any) should be removed. Any existing utilities should be re-routed or protected in place. The exposed native soils should then be proof-rolled with heavy rubber-tired equipment such as a scraper or loader*. Any soft/loose areas identified during proof-rolling should be removed and replaced with structural fill. All excavation bottoms should be observed by an IGES representative during proof-rolling or otherwise prior to placement of engineered fill to evaluate whether soft, loose, or otherwise deleterious earth materials have been removed, and to assess compliance with the recommendations presented in this report.

5.3.2 Excavations

Soft, loose, or otherwise unsuitable soils beneath structural elements, hardscape or pavements may need to be over-excavated and replaced with structural fill. If over-excavation is required, the excavations should extend one foot laterally for every foot of depth of over-excavation. Excavations should extend laterally at least two feet beyond flatwork, pavements, and slabs-ongrade. Structural fill should consist of granular materials and should be placed and compacted in accordance with the recommendations presented in this report.

^{*}not required where bedrock is exposed in the foundation subgrade

Prior to placing engineered fill, all excavation bottoms should be scarified to at least 6 inches, moisture conditioned as necessary at or slightly above optimum moisture content (OMC), and compacted to at least 90 percent of the maximum dry density (MDD) as determined by ASTM D-1557 (Modified Proctor). Scarification is not required where hard bedrock is exposed.

5.3.3 Excavation Stability

The contractor is responsible for site safety, including all temporary trenches excavated at the site and the design of any required temporary shoring. The contractor is responsible for providing the "competent person" required by Occupational Safety and Health (OSHA) standards to evaluate soil conditions. For planning purposes, Soil Type C is expected to predominate at the site (sands and gravels). Close coordination between the competent person and IGES should be maintained to facilitate construction while providing safe excavations.

Based on OSHA guidelines for excavation safety, trenches with vertical walls up to 5 feet in depth may be occupied. Where very moist soil conditions or groundwater is encountered, or when the trench is deeper than 5 feet, we recommend a trench-shield or shoring be used as a protective system to workers in the trench. As an alternative to shoring or shielding, trench walls may be laid back at one and one-half horizontal to one vertical (1½H:1V) (34 degrees) in accordance with OSHA Type C soils. Trench walls may need to be laid back at a steeper grade pending evaluation of soil conditions by the geotechnical engineer. Soil conditions should be evaluated in the field on a case-by-case basis. Large rocks exposed on excavation walls should be removed (scaled) to minimize rock fall hazards.

5.3.4 Structural Fill and Compaction

All fill placed for the support of structures, flatwork or pavements should consist of structural fill. Structural fill should consist of granular native soils, which may be defined as soils with less than 25% fines, 10-60% sand, and contain no rock larger than 4 inches in nominal size (6 inches in greatest dimension). Structural fill should also be free of vegetation and debris. All structural fill should be 1 inch minus material when within 1 foot of any base coarse material. Soils not meeting these criteria may be suitable for use as structural fill; however, such soils should be evaluated on a case by case basis and should be approved by IGES prior to use.

All structural fill should be placed in maximum 4-inch loose lifts if compacted by small hand-operated compaction equipment, maximum 6-inch loose lifts if compacted by light-duty rollers, and maximum 8-inch loose lifts if compacted by heavy duty compaction equipment that is capable of efficiently compacting the entire thickness of the lift. Additional lift thickness may be allowed by IGES provided the Contractor can demonstrate sufficient compaction can be achieved with a given lift thickness with the equipment in use. We recommend that all structural fill be compacted on a horizontal plane, unless otherwise approved by IGES. Structural fill underlying all shallow

footings and pavements should be compacted to at least 95 percent of the MDD as determined by ASTM D-1557. **The moisture content should be at, or slightly above, the OMC for all structural fill**. Any imported fill materials should be approved prior to importing. Also, prior to placing any fill, the excavations should be observed by IGES to confirm that unsuitable materials have been removed. In addition, proper grading should precede placement of fill, as described in the General Site Preparation and Grading subsection of this report.

Specifications from governing authorities such as Weber County and/or special service districts having their own precedence for backfill and compaction should be followed where more stringent.

5.3.5 Oversize Material

Based on our observations, there is a significant potential for the presence of oversize materials (larger than 6 inches in greatest dimension). Large rocks, particularly boulders (>12 inches), may require special handling, such as segregation from structural fill, and disposal.

5.3.6 Utility Trench Backfill

Utility trenches should be backfilled with structural fill in accordance with Section 5.3.4 of this report. Utility trenches can be backfilled with the onsite soils free of debris, organic and oversized material. Prior to backfilling the trench, pipes should be bedded in and shaded with a uniform granular material that has a Sand Equivalent (SE) of 30 or greater. Pipe bedding may be water-densified in-place (jetting). Alternatively, pipe bedding and shading may consist of clean ¾-inch gravel. Native earth materials can be used as backfill over the pipe bedding zone. All utility trenches backfilled below pavement sections, curb and gutter, and hardscape, should be backfilled with structural fill compacted to at least 95 percent of the MDD as determined by ASTM D-1557. All other trenches should be backfilled and compacted to approximately 90 percent of the MDD (ASTM D-1557). However, in all cases the pipe bedding and shading should meet the design criteria of the pipe manufacturer. Specifications from governing authorities having their own precedence for backfill and compaction should be followed where they are more stringent.

5.4 FOUNDATION RECOMMENDATIONS

Based on our field observations and considering the presence of relatively competent native earth materials, we recommend that the footings for the proposed home be founded either *entirely* on competent native earth materials <u>or *entirely*</u> on structural fill. Native/fill transition zones are not allowed. Furthermore, if part of the foundation excavation exposes hard/cemented colluvium and/or conglomerate bedrock, all foundations should be deepened such that the entire foundation system is placed on similarly firm earth materials.

If soft, loose, or otherwise deleterious earth materials are exposed in the footing excavations, then the footings should be deepened such that all footings bear on relatively uniform, competent native earth materials. Alternatively, the foundation excavation may be over-excavated a minimum of 2

feet below the bottom of proposed footings and replaced with structural fill, such that the footings bear entirely on a uniform fill blanket. We recommend that IGES assess the bottom of the foundation excavation prior to the placement of steel or concrete to identify the competent native earth materials as well as any unsuitable soils or transition zones. Additional over-excavation may be required based on the actual subsurface conditions observed.

Shallow spread or continuous wall footings constructed entirely on competent, uniform native earth materials or on a minimum of 2 feet of *structural fill* may be proportioned utilizing a maximum net allowable bearing pressure of **2,900 pounds per square foot (psf)** for dead load plus live load conditions. The net allowable bearing value presented above is for dead load plus live load conditions. The minimum recommended footing width is 20 inches for continuous wall footings and 30 inches for isolated spread footings.

All conventional foundations exposed to the full effects of frost should be established at a minimum depth of 42 inches below the lowest adjacent final grade. Interior footings, not subjected to the full effects of frost (i.e., *a continuously heated structure*), may be established at higher elevations, however, a minimum depth of embedment of 12 inches is recommended for confinement purposes.

Foundation drains must be installed around below-ground foundations (e.g., basement walls) to minimize the potential for flooding from water seepage (spring-like conditions), which may be present at various times during the year, particularly during spring run-off.

5.5 SETTLEMENT

5.5.1 Static Settlement

Static settlements of properly designed and constructed conventional foundations, founded as described in Section 5.4, are anticipated to be on the order of 1 inch or less. Differential settlement is expected to be half of total settlement over a distance of 30 feet.

5.5.2 Dynamic Settlement

Dynamic settlement (or seismically-induced settlement) consists of dry dynamic settlement of unsaturated soils (above groundwater) and liquefaction-induced settlement (below groundwater). During a strong seismic event, seismically-induced settlement can occur within loose to moderately dense sandy soil due to reduction in volume during, and shortly after, an earthquake event. Settlement caused by ground shaking is often non-uniformly distributed, which can result in differential settlement.

Based on the subsurface conditions encountered, dynamic settlement arising from a MCE seismic event is expected to be low; for design purposes, settlement on the order of ½ inch over 40 feet may be assumed.

5.6 EARTH PRESSURES AND LATERAL RESISTANCE

Lateral forces imposed upon conventional foundations due to wind or seismic forces may be resisted by the development of passive earth pressures and friction between the base of the footing and the supporting soils. In determining the frictional resistance against concrete, a coefficient of friction of 0.45 for sandy/gravelly native soils or structural fill should be used.

Ultimate lateral earth pressures from *granular* backfill acting against retaining walls, temporary shoring, or buried structures may be computed from the lateral pressure coefficients or equivalent fluid densities presented in Table 5.6. These lateral pressures should be assumed even if the backfill is placed in a relatively narrow gap between a vertical bedrock cut and the foundation wall. These coefficients and densities assume no buildup of hydrostatic pressures. The force of water should be added to the presented values if hydrostatic pressures are anticipated.

Clayey soils drain poorly and may swell upon wetting, thereby greatly increasing lateral pressures acting on earth retaining structures; therefore, clayey soils should not be used as retaining wall backfill. Backfill should consist of native granular soil with an Expansion Index (EI) less than 20.

Walls and structures allowed to rotate slightly should use the active condition. If the element is to be constrained against rotation (i.e., a basement wall), the at-rest condition should be used. These values should be used with an appropriate factor of safety against overturning and sliding. A value of 1.5 is typically used. Additionally, if passive resistance is calculated in conjunction with frictional resistance, the passive resistance should be reduced by ½.

Table 5.6
Lateral Earth Pressure Coefficients

	Level Backfill		2H:1V Backfill	
Condition	Lateral Pressure Coefficient	Equivalent Fluid Density (pcf)	Lateral Pressure Coefficient	Equivalent Fluid Density (pcf)
Active (Ka)	0.295	36.9	0.442	55.3
At-rest (Ko)	0.455	56.9	0.682	85.2
Passive (Kp)	3.39	424	_	_
Seismic Active	0.108	13.5	0.425	55.3
Seismic Passive	-0.357	-44.6	_	_

For seismic analyses, the *active* earth pressure coefficient provided in the table is based on the Mononobe-Okabe pseudo-static approach and only accounts for the dynamic horizontal thrust produced by ground motion. Hence, the resulting dynamic thrust pressure *should be added* to the static pressure to determine the total pressure on the wall. The pressure distribution of the dynamic horizontal thrust may be closely approximated as an inverted triangle with stress decreasing with

depth and the resultant acting at a distance approximately 0.6 times the loaded height of the structure, measured upward from the bottom of the structure.

5.7 CONCRETE SLAB-ON-GRADE CONSTRUCTION

To minimize settlement and cracking of slabs, and to aid in drainage beneath the concrete floor slabs, all concrete slabs should be founded on a minimum 4-inch layer of compacted gravel overlying properly prepared subgrade. The gravel should consist of free-draining gravel or road base with a 3/4-inch maximum particle size and no more than 5 percent passing the No. 200 mesh sieve. The layer should be compacted to at least 95 percent of the MDD as determined by ASTM D-1557.

All concrete slabs should be designed to minimize cracking as a result of shrinkage. Consideration should be given to reinforcing the slab with a welded wire fabric, re-bar, or fibermesh. Slab reinforcement should be designed by the structural engineer; however, as a minimum, slab reinforcement should consist of 4"×4" W2.9×W2.9 welded wire mesh within the middle third of the slab. We recommend that concrete be tested to assess that the slump and/or air content is in compliance with the plans and specifications. We recommend that concrete be placed in general accordance with the requirements of the American Concrete Institute (ACI). A Modulus of Subgrade Reaction of **250 psi/inch** may be used for design.

A moisture barrier (vapor retarder) consisting of 10-mil thick Visqueen (or equivalent) plastic sheeting should be placed below slabs-on-grade where moisture-sensitive floor coverings or equipment is planned. Prior to placing this moisture barrier, any objects that could puncture it, such as protruding gravel or rocks, should be removed from the building pad. Alternatively, the subgrade may be covered with 2 inches of clean sand.

5.8 MOISTURE PROTECTION AND SURFACE DRAINAGE

Surface moisture should not be allowed to infiltrate into the soils in the vicinity of the foundations. As such, design strategies to minimize ponding and infiltration near the structures should be implemented. The new home may be subject to sheet flow during periods of heavy rain or snow melt; therefore, the Civil Engineer may also wish to consider construction of additional surface drainage to intercept surface runoff, or a curtain drain to intercept seasonal groundwater flow.

We recommend roof runoff devices be installed to direct all runoff a minimum of 10 feet away from foundations. The builder should be responsible for compacting the exterior backfill soils around the foundation; failure to properly compact the basement backfill can result in excessive settlement and damage to exterior improvements such as pavement or other flatwork. Additionally, the ground surface within 10 feet of the structures should be constructed so as to slope a minimum of **five** percent away from the structure. Pavement sections should be constructed to divert surface water off the pavement into storm drains, curb/gutter, or another suitable location.

Where basements are planned, IGES recommends a perimeter foundation drain be constructed in accordance with the International Residential Code (IRC). In consideration of possible perennial or seasonal spring-like conditions in the subsurface, consideration should be given to constructing a 'curtain drain' or 'French drain' to intercept all laterally-flowing water uphill of the home.

5.9 SOIL CORROSION POTENTIAL

Laboratory testing of representative soil samples obtained from nearby lots for previous investigations (44R, 75R) indicated that the soil samples tested had soluble sulfate contents of 74 516 ppm. Accordingly, the soils are classified as having a 'low potential' for deterioration of concrete due to the presence of soluble sulfate. As such, conventional Type II Portland cement may be used for all concrete in contact with site soils.

To evaluate the corrosion potential of ferrous metal in contact with native soil, testing for resistivity, soluble chloride and pH is typically prescribed. Testing of soils on nearby lots (44R, 74R) during previous investigations indicated that the soil tested had a minimum soil resistivity of 5,071 and 9,373 OHM-cm, soluble chloride content of 8.46 and 72.0 ppm and a pH of 5.24 and 5.57. Based on these results, the onsite native soil is considered to be *mildly corrosive* to ferrous metal. To address the acidic soil conditions, we recommend a lower water/cement ratio, ~0.4, for reinforced concrete. The lower water/cement ratio will reduce permeability of the concrete and reduce the susceptibility of the reinforcing steel to acidic corrosion.

5.10 CONSTRUCTION CONSIDERATIONS

5.10.1 Over-Size Material

Rounded boulders up to 60 inches were identified in the test pits and on the ground surface; larger rocks may be present locally. The site is overlain with bouldery colluvium, largely derived from the underlying Wasatch Formation, which consists of cobbly/bouldery conglomerate. Large rocks may require special handling, such as segregation from structural fill, and disposal.

5.10.2 Groundwater

Water was observed entering the test pit at a depth of approximately 12 feet below existing grade. Furthermore, water has been observed seeping from the 2H:1V cut slope that descends toward the cul-de-sac during the site reconnaissance from both Lot 74R and Lot 75R, and significant water was observed earlier this year seeping into the foundation excavation for Lot 75R. Although this water is not considered groundwater in the conventional sense (a piezometric surface), it is very likely that this water represents a localized perched groundwater body and is in effect a localized underground spring. Water flow is expected to be maximum during spring run-off, and will likely taper off as the season progresses, although the water seepage may continue year-round. The Contractor and Civil Engineer should be aware of this seepage; the design of the structure should take into account the presence of seepage, and subterranean portions of the home should be well-drained. Temporary dewatering may be required during construction. A French Drain or a Curtain

ain may be desirable to help control water around the property. Alternatively, the Ownersh to consider designing the home as an on-grade structure (e.g., no basement) to minimize the seepage to impact the subterranean components of the home.	

6.0 CLOSURE

6.1 LIMITATIONS

The concept of risk is a significant consideration of geotechnical analyses. The analytical means and methods used in performing geotechnical analyses and development of resulting recommendations do not constitute an exact science. Analytical tools used by geotechnical engineers are based on limited data, empirical correlations, engineering judgment and experience. As such the solutions and resulting recommendations presented in this report cannot be considered risk-free and constitute IGES's best professional opinions and recommendations based on the available data and other design information available at the time they were developed. IGES has developed the preceding analyses, recommendations and designs, at a minimum, in accordance with generally accepted professional geotechnical engineering practices and care being exercised in the project area at the time our services were performed. No warrantees, guarantees or other representations are made.

The information contained in this report is based on limited field testing and our understanding of the project. The subsurface data used in the preparation of this report were obtained largely from the exploration made on Lot 74R. It is very likely that variations in the soil, rock, and groundwater conditions exist between and beyond the point explored. The nature and extent of the variations may not be evident until construction occurs and additional explorations are completed. If any conditions are encountered at this site that are different from those described in this report, IGES must be immediately notified so that we may make any necessary revisions to recommendations presented in this report. In addition, if the scope of the proposed construction or grading changes from those described in this report, our firm must also be notified.

This report was prepared for our client's exclusive use on the project identified in the foregoing. Use of the data, recommendations or design information contained herein for any other project or development of the site not as specifically described in this report is at the user's sole risk and without the approval of IGES, Inc. It is the client's responsibility to see that all parties to the project including the designer, contractor, subcontractors, etc. are made aware of this report in its entirety. The use of information contained in this report for bidding purposes should be done at the contractor's option and risk.

We recommend that IGES be retained to review the final design plans, grading plans and specifications to determine if our engineering recommendations have been properly incorporated in the project development documents. We also recommend that IGES be retained to evaluate construction performance and other geotechnical aspects of the project as construction initiates and progresses through its completion.

6.2 ADDITIONAL SERVICES

The recommendations made in this report are based on the assumption that an adequate program of tests and observations will be made during the construction. IGES staff or other qualified personnel should be on site to verify compliance with these recommendations. These tests and observations should include at a minimum the following:

- Observations and testing during site preparation, earthwork and structural fill placement.
- Consultation as may be required during construction.
- Quality control on concrete placement to verify slump, air content, and strength.

We also recommend that project plans and specifications be reviewed by us to verify compatibility with our conclusions and recommendations. Additional information concerning the scope and cost of these services can be obtained from our office.

We appreciate the opportunity to be of service on this project. Should you have any questions regarding the report or wish to discuss additional services, please do not hesitate to contact us at your convenience at (801) 748-4044.

7.0 REFERENCES

- AMEC, 2001. Report Engineering Geologic Reconnaissance/Geotechnical Study Powder Mountain Resort.
- American Geologic Institute (AGI), 2005, Glossary of Geology, Fifth Edition, revised, Neuendorf, K.K.E., Mehl, Jr. J.P., and Jackson, J.A., editors: American Geological Institute, Alexandria, Virginia, 783 p.
- Anderson, L.R., Keaton, J.R., and Bay, J.A., 1994, Liquefaction Potential Map for the Northern Wasatch Front, Utah, Complete Technical Report: Utah Geological Survey Contract Report 94-6, 169 p.
- Blake, T.F., Hollingsworth, R.A. and Stewart, J.P., Editors (2002), Recommended Procedures for Implementation of DMG Special Publication 117, Guidelines for analyzing and mitigating landslide hazards in California: organized by the Southern California Earthquake Center.
- Christenson, G.E., and Shaw, L.M., 2008a, Surface Fault Rupture Special Study Areas, Wasatch Front and Nearby Areas, Utah: Utah Geological Survey Supplement Map to Utah Geological Survey Circular 106, 1 Plate, Scale 1:200,000.
- Christenson, G.E., and Shaw, L.M., 2008b, Debris-Flow/Alluvial Fan Special Study Areas, Wasatch Front and Nearby Areas, Utah: Utah Geological Survey Supplement Map to Utah Geological Survey Circular 106, 1 Plate, Scale 1:200,000.
- Christenson, G.E., and Shaw, L.M., 2008c, Liquefaction Special Study Areas, Wasatch Front and Nearby Areas, Utah: Utah Geological Survey Supplement Map to Utah Geological Survey Circular 106, 1 Plate, Scale 1:200,000.
- Colton, R.B., 1991, Landslide Deposits in the Ogden 30' x 60' Quadrangle, Utah and Wyoming: U.S. Geological Survey Open-File Report 91-297, 1 Plate, 8 p., Scale 1:100,000.
- Coogan, J.C., and King, J.K., 2001, Progress Report Geologic Map of the Ogden 30' x 60' Quadrangle, Utah and Wyoming Year 3 of 3: Utah Geological Survey Open-File Report 380, 1 Plate, 33 p., Scale 1:100,000.
- Coogan, J.C., and King, J.K., 2016, Interim Geologic Map of the Ogden 30' x 60' Quadrangle, Box Elder, Cache, Davis, Morgan, Rich, and Summit Counties, Utah, and Uinta County, Wyoming: Utah Geological Survey Open-File Report 653DM, 1 Plate, 151 p., Scale 1:100,000.
- Crittenden, Jr., M.D., 1972, Geologic Map of the Browns Hole Quadrangle, Utah: U.S. Geological Survey Geologic Quadrangle Map GQ-968, 1 Plate, Scale 1:24,000.
- Elliott, A.H., and Harty, K.M., 2010, Landslide Maps of Utah, Ogden 30' X 60' Quadrangle: Utah Geological Survey Map 246DM, Plate 6 of 46, Scale 1:100,000.

REFERENCES (Cont.)

- Federal Emergency Management Agency [FEMA], 1997, NEHRP Recommended Provisions for Seismic Regulations for New Buildings and Other Structures, FEMA 302, Washington, D.C.
- Frankel, A., Mueller, C., Barnard, T., Perkins, D., Leyendecker, E.V., Dickman, N., Hanson, S., and Hopper, M., 1996, *National Seismic-hazard Maps: Documentation*, U.S. Geological Survey Open-File Report 96-532, June.
- Hintze, L.F., 1988, Geologic History of Utah: Brigham Young University Geology Studies Special Publication 7, Provo, Utah, 202 p.
- Hynes, M.E. and A. G. Franklin (1984). "Rationalizing the Seismic Coefficient Method" Miscellaneous Paper GL-84-13, U.S. Army Waterways Experiment Station, Vicksburg, Miss.
- IGES, Inc., 2012a, Preliminary Geotechnical Investigation, Powder Mountain Resort, Weber County, Utah, Project No. 01628-001, dated July 26, 2012.
- IGES, Inc., 2012b, Design Geotechnical Investigation, Powder Mountain Resort, Weber County, Utah, Project No. 01628-003, dated November 9, 2012.
- IGES, Inc., 2017, Geotechnical & Geologic Hazard Investigation Report (Rev 1), Lot 75R of Summit Powder Mountain Resort, 8452 E. Spring Park, Weber County, Utah: IGES Project No. 02347-001, dated June 9, 2017.
- IGES, Inc., 2018, Geotechnical and Geologic Hazard Investigation, Lot 44R of Summit Eden Phase 1C, 8645 E. Copper Crest, Summit Powder Mountain Resort, Weber County, Utah, Project No. 02732-001, dated March 19, 2018.
- International Building Code [IBC], 2015, International Code Council, Inc.
- Lund, W.R., 1990, editor, Engineering geology of the Salt Lake City metropolitan area, Utah: Utah Geological Survey Bulletin 126, 66 p.
- Milligan, M.R., 2000, How was Utah's topography formed? Utah Geological Survey, Survey Notes, v. 32, no.1, pp. 10-11.
- Sorensen, M.L., and Crittenden, Jr., M.D., 1979, Geologic Map of the Huntsville Quadrangle, Weber and Cache Counties, Utah: U.S. Geological Survey Geologic Quadrangle Map GQ-1503, 1 Plate, Scale 1:24,000.
- Stokes, W.L., 1987, Geology of Utah: Utah Museum of Natural History and Utah Geological and Mineral Survey Department of Natural Resources, Salt Lake City, UT, Utah Museum of Natural History Occasional Paper 6, 280 p.


REFERENCES (Cont.)


- U.S. Geological Survey, 2012/15, U.S. *Seismic "Design Maps" Web Application*, site: https://geohazards.usgs.gov/secure/designmaps/us/application.php, site accessed on June 18, 2018.
- U.S. Geological Survey, 2014, Topographic Map of the Huntsville Quadrangle, Huntsville, Utah: Scale 1:24,000.
- U.S. Geological Survey, 2014, Topographic Map of the Brown's Hole Quadrangle, Brown's Hole, Utah: Scale 1:24,000.
- U.S. Geological Survey and Utah Geological Survey, 2006, Quaternary fault and fold database for the United States, accessed 7-3-17, from USGS website: http://earthquakes.usgs.gov/regional/qfaults
- Utah Geological Survey, 2016, Utah Geological Survey Aerial Imagery Collection https://geodata.geology.utah.gov/imagery/
- Weber County, 2015, Natural Hazards Overlay Districts, Chapter 27 of Title 104 of the Weber County Code of Ordinances, adopted on December 22, 2015.
- Western Geologic, 2012, Report: Geologic Hazards Reconnaissance, Proposed Area 1 Mixed-Use Development, Powder Mountain Resort, Weber County, Utah, dated August 28, 2012.

AERIAL PHOTOGRAPHS


Data Set	Date	Flight	Photographs	Scale
1947 AAJ	August 10, 1946	AAJ_1B	88, 89, 90	1:20,000
1953 AAI	September 14, 1952	AAI_4K	34, 35, 36	1:20,000
1963 ELK	June 25, 1963	ELK_3	57, 58, 59	1:15,840

^{*}https://geodata.geology.utah.gov/imagery/





Base Maps: USGS *Huntsville*, *Brown's Hole*, *James Peak*, and *Sharp Mountain* 7.5-Minute Quadrangles (2017)






Geotechnical & Geologic Hazard Investigation
Lot 74R of Summit Eden Phase 1C
Summit Powder Mountain Resort
Weber County, Utah
SITE VICINITY MAP

Figure

A-1



BASE MAP:

-UNDATED 100-SCALE MAP OF PHASE 1C-1D PREPARED BY NV5

CONTOUR INTERVAL: 2'


AFTIFICIAL FILL QIS? POSSIBLE LANDSLIDE Qac COLLUVIUM APPROXIMATE GEOLOGIC CONTACTS PROPERTY BOUNDARY TEST PITS CROSS SECTION ALLUVIUM & COLLUVIUM TP-1 TEST PITS CROSS SECTION T = 50'



Geotechnical and Geologic Hazards Assessment Lot 74R of Summit Eden Phase 1C Summit Powder Mountain Resort Weber County, Utah

LOCAL GEOLOGY AND GEOTECHNICAL MAP

Figure
A-2



LITHOLOGIC UNIT DESCRIPTIONS:

- 1) A/B Soil Horizon: ~18" thick; dark yellowish brown silty CLAY with gravel (CL-ML), medium stiff, moist, low plasticity, massive; gravel and larger sized clasts comprise ~10-20% of unit; clasts are subrounded to subangular pale yellowish orange (10YR 8/6) to medium gray (N5) quartzite up to 18" in diameter, though mode size ~½ to 1"; abundant plant and tree roots; gradational, irregular basal contact.
- 2) Colluvium: ~1½' thick; dark yellowish brown (10YR 4/2) sandy lean CLAY with gravel (CL), loose to medium stiff, moist, low plasticity, massive; gravel and larger sized clasts comprise ~30-40% of unit; clasts entirely subrounded to subangular quartzite as above up to 10" in diameter, though mode size ~3-5"; common to abundant plant and tree roots; topsoil matrix; possibly poorly-developed B Horizon; sharp, irregular basal contact.
- 3) Wasatch Formation: At least ~11' thick; poorly consolidated conglomerate bedrock, largely disaggregated to moderate reddish brown (10R 4/6) silty SAND with gravel (SM) grading to poorly-graded GRAVEL with silt and sand (GP-GM), medium dense to dense, moist to wet, low plasticity fines, massive with rare faint fine bedding; gravel and larger sized clasts comprise ~30-40% of unit; clasts entirely subrounded to subangular quartzite; clasts up to 21" in diameter, though mode size ~2-4"; basal 2 feet is predominately fine- to medium-grained sand with 10-20% gravel; some plant and tree roots; water seeping out of lowermost ~2' of unit.

SCALE: 1"=5' H&V




Geotechnical & Geologic Hazard Investigation
Lot 74R of Summit Eden Phase 1C
Summit Powder Mountain Resort
Weber County, Utah
TEST PIT LOG TP-1

Figure

A-3

UNIFIED SOIL CLASSIFICATION SYSTEM



MOISTURE CONTENT

DESCRIPTION	FIELDTEST	
DRY	ABSENCE OF MOISTURE, DUSTY, DRY TO THE TOUCH	
MOIST	T DAMP BUT NO VISIBLE WATER	
WET	VISIBLE FREE WATER, USUALLY SOIL BELOW WATER TABLE	

STRATIFICATION

l	DESCRIPTION	THICKNESS	DESCRIPTION	THICKNESS
I	SEAM	1/16 - 1/2"	OCCASIONAL	ONE OR LESS PER FOOT OF THICKNESS
l	LAYER	1/2 - 12"	FREQUENT	MORE THAN ONE PER FOCT OF THICKNESS
-				

LOG KEY SYMBOLS





TEST-PIT SAMPLE LOCATION

WATER LEVEL (level after completion)

WATER LEVEL (level where first encountered)

CEMENTATION

DESCRIPTION	DESCRIPTION
WEAKELY	CRUNBLES OR BREAKS WITH HANDLING OR SLIGHT FINGER PRESSURE
MODERATELY	CRUMBLES OR BREAKS WITH CONSIDERABLE FINGER PRESSURE
STRONGLY	WILL NOT CRUMBLE OR BREAK WITH FINGER PRESSURE

OTHER TESTS KEY

С	CONSOLIDATION	SA	SIEVE ANALYSIS
AL	ATTERBERG LIMITS	DS	DIRECT SHEAR
UC	UNCONFINED COMPRESSION	Т	TRIAXIAL
S	SOLUBILITY	R	RESISTIVITY
0	ORGANIC CONTENT	RV	R-VALUE
CBR	CALIFORNIA BEARING RATIO	SU	SOLUBLE SULFATES
COMP	MOISTURE/DENSITY RELATIONSHIP	PM	PERMEABILITY
CI	CALIFORNIA IMPACT	-200	% FINER THAN #200
COL	COLLAPSE POTENTIAL	Gs	SPECIFIC GRAVITY
SS	SHRINK SWELL	SL	SWELL LOAD

MODIFIERS

DESCRIPTION	%
TRACE	<5
SOME	5 - 12
WITH	>12

GENERAL NOTES

- Lines separating strata on the logs represent approximate boundaries only. Actual transitions may be gradual.
- 2. No warranty is provided as to the continuity of soil conditions between individual sample locations.
- 3. Logs represent general soil conditions observed at the point of exploration on the date indicated.
- 4. In general, Unified Soil Classification designations presented on the logs were evaluated by visual methods only. Therefore, actual designations (based on laboratory tests) may vary

ADDADENT / DEL ATIVE DENGITY COADGE CDAINED COIL

APPARENT / I	APPARENT / RELATIVE DENSITY - COARSE-GRAINED SOIL				
APPARENT DENSITY	SPT (blows/ft)	MODIFIED CA. SAMPLER (blows/ft)	CALIFORNIA SAMPLER (blows/ft)	RELATIVE DENSITY (%)	FIELD TEST
VERY LOOSE	<4	<4	<5	0 - 15	EASILY PENETRATED WITH 1/2-INCH REINFORCING ROD PUSHED BY HAND
LOOSE	4 - 10	5 - 12	5 - 15	15 - 35	DIFFICULT TO PENETRATE WITH 1/2-INCH REINFORCING ROD PUSHED BY HAND
MEDIUM DENSE	10 - 30	12 - 35	15 - 40	35 - 65	EASILY PENETRATED A FOOT WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER
DENSE	30 - 50	35 - 60	40 - 70	65 - 85	DIFFICULT TO PENETRATED A FOOT WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER
VERY DENSE	>50	>60	>70	85 - 100	PENETRATED ONLY A FEW INCHES WITH 1/2-INCH REINFORCING ROD DRIVEN WITH 5-LB HAMMER

CONSISTENCY - FINE-GRAINED SOIL		TORVANE	POCKET PENETROMETER	FIELD TEST
CONSISTENCY	SPT (blows/ft)	UNTRAINED SHEAR STRENGTH (tsf)	UNCONFINED COMPRESSIVE STRENGTH (tsf)	
VERY SOFT	<2	<0.125	<0.25	EASILY PENETRATED SEVERAL INCHES BY THUMB. EXUDES BETWEEN THUMB AND FINGERS WHEN SQUEEZED BY HAND.
SOFT	2 - 4	0.125 - 0.25	0.25 - 0.5	EASILY PENETRATED ONE INCH BY THUMB. MOLDED BY LIGHT FINGER PRESSURE.
MEDIUM STIFF	4 - 8	0.25 - 0.5	0.5 - 1.0	PENETRATED OVER 1/2 INCH BY THUMB WITH MODERATE EFFORT. MOLDED BY STRONG FINGER PRESSURE.
STIFF	B - 15	0.5 - 1.0	1.0 - 2.0	INDENTED ABOUT 1/2 INCH BY THUMB BUT PENETRATED ONLY WITH GREAT EFFORT.
VERY STIFF	15 - 30	1.0 - 2.0	2.0 - 4.0	READILY INDENTED BY THUMBNAIL.
HARD	>30	>2.0	>4.0	INDENTED WITH DIFFICULTY BY THUMBNAIL.



Project No. 02810-001

Geotechnical & Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C

Summit Powder Mountain Resort

Weber County, Utah KEY TO SOIL SYMBOLS AND

TERMINOLOGY

Figure

A-4

Weathering

Rock Classification Should Include:			
1. 2. 3. 4. 5. 6.	Rock name (or classification) Color Weathering Fracturing Competency Additional comments indicating rock characteristics which might affect engineering properties		

Weathering	Field Test
Fresh	No visible sign of decomposition or discoloration. Rings under hammer impact.
Slightly Weathered	Slight discoloration inwards from open fractures, otherwise similar to Fresh.
Moderately Weathered	Discoloration throughout. Weaker minerals such as feldspar are decomposed. Strength somewhat less than fresh rock but cores cannot be broken by hand or scraped with a knife. Texture preserved.
Highly Weathered	Most minerals somewhat decomposed. Specimens can be broken by hand with effort or shaved with a knife. Core stones present in rock mass. Texture becoming indistinct but fabric preserved.
Completely Weathered	Minerals decomposed to soil but fabric and structure preserved. Specimens easily crumble or penetrated.

Fracturing

Spacing	Description
>6 ft	Very Widely
2-6 ft	Widely
8-24 in	Moderately
2 ½-8 in	Closely
3/4-2 ½ in	Very Closely

Bedding of Sedimentary Rocks

Splitting Property	Thickness	Stratification
Massive	>4.0 ft	Very thick bedded
Blocky	2.0-4.0 ft	Thick-bedded
Slabby	2 ½-24 in	Thin-bedded
Flaggy	½-2 ½ in	Very thin-bedded
Shaly or platy	⅓ - ⅓ in	Laminated
Papery	< 1/8 in	Thinly laminated

RQD

RQD (%)	Rock Quality
90-100	Excellent
75-90	Good
50-75	Fair
25-50	Poor
0-25	Very Poor

Competency

Class	Strength	Field Test	Approximate Range of Unconfined Compressive Strength (tsf)
I	Extremely Strong	Many blows with geologic hammer required to break intact specimen.	>2000
П	Very Strong	Hand-held specimen breaks with pick end of hammer under more than one blow.	2000-1000
Ш	Strong	Cannot by scraped or peeled with knife, hand-held specimen can be broken with single moderate blow with pick end of hammer	1000-500
IV	Moderately Strong	Can just be scraped or peeled with knife. Indentations 1-3 mm show in specimen with moderate blow with pick end of hammer.	500-250
v	Weak	Material crumbles under moderate blow with pick end of hammer and can be peeled with a knife, but is hard to hand-trim for triaxial test specimen.	250-10
VI	Friable	Material crumbles in hand.	N/A



Project No. 02810-001


Geotechnical & Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C Summit Powder Mountain Resort

Weber County, Utah KEY TO PHYSICAL ROCK

PROPERTIES

Figure

A-5





Map (GQ-968), Crittenden, Jr. (1972)

USGS Brown's Hole 7.5-Minute Geologic Quadrangle

Geotechnical & Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C Summit Powder Mountain Resort Weber County, Utah REGIONAL GEOLOGY MAP 1

1,000'

2,000'

SCALE: 1"=2,000'



4,000'

A-6a

MAP LEGEND

Qal ALLUVIAL DEPOSITS, UNDIFFERENTIATED (Holocene) -Unconsolidated gravel, sand, and silt deposits in presently active stream channels and floodplains; thickness 0-6 m COLLUVIUM AND SLOPEWASH (Holocene) - Bouldery colluvium Ocs and slopewash chiefly along eastern margin of Ogden Valley; in part, lag from Tertiary units; thickness 0-30 m ALLUVIAL FAN DEPOSITS (Holocene) - Alluvial fan deposits; postdate, at least in part, time of highest stand of former Lake Bonneville; thickness 0-30 m LANDSLIDE DEPOSITS (Holocene) - thickness 0-6 m Qls Qt. TALUS DEPOSITS (Holocene) - thickness 0-6 m WASATCH AND EVANSTON(?) FORMATIONS, UNDIVIDED TKwe (Eocene, Paleocene, and Upper Cretaceous?) - Unconsolidated pale-reddish-brown pebble, cobble, and boulder conglomerate; forms boulder-covered slopes. Clasts are mainly Precambrian quartzite and are tan, gray, or purple; matrix is mainly poorly consolidated sand and silt; thickness 0-150 m ST. CHARLES LIMESTONE (Upper Cambrian) - Includes: €sd Dolomite member - Thin- to thick-bedded, finely to medium crystalline, light- to medium-gray, white- to light-gray-weathering, cliff-forming dolomite; linguloid brachiopods common in basal 15 m; thickness 150-245 m Worm Creek Quartzite Member - Thin-bedded, fine- to mediumgrained, medium- to dark-gray, tan- to brown-weathering calcareous quartzitic sandstone; detrital grains well-sorted and well-rounded; thickness 6 m NOUNAN DOLOMITE (Upper and Middle Cambrian) - Thin- to €n thick-bedded, finely crystalline, medium-gray, light- to medium-grayweathering, cliff-forming dolomite; white twiggy structures common throughout unit; thickness 150-230 m CALLS FORT SHALE MEMBER OF BLOOMINGTON FORMATION (Middle Cambrian) - Olive-drab to light-brown shale and light- to dark-blue-gray limestone with intercalated orange to rusty-brown silty limestone; intraformational conglomerate common throughout unit; thickness 23-90 m €lu CAMBRIAN LIMESTONES, UNDIVIDED (Middle Cambrian) -Includes limestone and Hodges Shale Members of Bloomington Formation, and Blacksmith and Ute Limestones BLACKSMITH LIMESTONE (Middle Cambrian)) - Medium- to thin-bedded, light-gray to dark-blue-gray limestone; thin-bedded, flaggy-weathering, gray to tan silty limestone and interbedded

siltstone; light- to dark-gray dolomite, with some reddish siliceous



Geotechnical & Geologic Hazard Investigation
Lot 74R of Summit Eden Phase 1C
Summit Powder Mountain Resort
Weber County, Utah REGIONAL GEOLOGY MAP 1

partings; thickness 400? m

MAP LEGEND

€u


UTE LIMESTONE (Middle Cambrian) — Medium- to thin-bedded, finely crystalline, light- to dark-gray silty limestone with irregular wavy partings, mottled and streaked surfaces, worm tracks, and twiggy structures common throughout unit; oolites and Girvanella in many beds; olive-drab fissile shale interbedded throughout unit. Includes thin-bedded, gray-weathering, pale-tan to brown dolomite exposed at base of unit, 18-24 m at head of Geertsen Canyon and 0-3 m elsewhere; thickness 245? m



GEERTSEN CANYON QUARTZITE (Lower Cambrian) — Includes: Upper member — Pale-buff to white or flesh-pink quartzite, locally streaked with pale red or purple. Coarse-grained; small pebbles occur throughout unit and increase in abundance downward. Base marked by zone 30-60 m thick of cobble conglomerate in beds 30 cm to 2 m thick; clasts, 5-10 cm in diameter, are mainly reddish vein quartz or quartzite, sparse gray quartzite, or red jasper; thickness 730-820 m

€gcl


Lower member — Pale-buff to white and tan quartzite with irregular streaks and lenses of cobble conglomerate decreasing in abundance downward. Lower 90-120 m strongly arkosic, streaked greenish or pinkish. Feldspar clasts increase in size to 0.6-1.3 cm in lower part of unit; thickness 490-520 m




Pre-Tertiary normal fault – Dotted where concealed Bar and ball on downthrown side

Thrust fault — Dashed where inferred Sawteeth on upper plate






Base Map: Western Geologic (2012) Geologic Hazards Reconnaissance Report, Figure 3






Geotechnical & Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C Summit Powder Mountain Resort Weber County, Utah REGIONAL GEOLOGY MAP 2 Figure

A-7



Base Map: Coogan and King (2016) UGS Ogden 30'x60' Geologic Quadrangel Map, OFR-635DM, Plate 1





Geotechnical & Geologic Hazard Investigation Lot 74R of Summit Eden Phase 1C Summit Powder Mountain Resort Weber County, Utah REGIONAL GEOLOGY MAP 3 Figure
A-8a

MAP LEGEND

Qmc Landslide and colluvial deposits, undivided (Holocene and Pleistocene) – Poorly sorted to unsorted clay- to boulder-sized material; mapped where landslide deposits are difficult to distinguish from colluvium (slopewash and soil creep) and where mapping separate, small, intermingled areas of landslide and colluvial deposits is not possible at map scale; locally includes talus and debris flow and flood deposits; typically mapped where landslides are thin ("shallow"); also mapped where the blocky or rumpled morphology that is characteristic of landslides has been diminished ("smoothed") by slopewash and soil creep; composition depends on local sources; 6 to 40 feet (2-12 m) thick. These deposits are as unstable as other landslide units (Qms, Qmsy, Qmso).

Human disturbances

Qh, Qh? **Human disturbances (Historical)** - Mapped disturbances obscure original deposits or rocks by cover or removal; only larger disturbances that pre-date the 1984 aerial photographs used to map the Ogden 30 x 60-minute quadrangle are shown; includes engineered fill, particularly along Interstate Highways 80 and 84, the Union Pacific Railroad, and larger dams, as well as aggregate operations, gravel pits, sewage-treatment facilities, cement plant quarries and operations, brick plant and clay pit, Defense Depot Ogden (Browning U.S. Army Reserve Center), gas and oil field operations (for example drill pads) including gas plants, and low dams along several creeks, including a breached dam on Yellow Creek.

Qms, Qms?, Qmsy, Qmsy?, Qmso, Qmso?

Landslide deposits (Holocene and upper and middle? Pleistocene) – Poorly sorted clay- to boulder-sized material; includes slides, slumps, and locally flows and floods; generally characterized by hummocky topography, main and internal scarps, and chaotic bedding in displaced blocks; composition depends on local sources; morphology becomes more subdued with time and amount of water in material during emplacement; Qms may be in contact with Qms when landslides are different/distinct; thickness highly variable, up to about 20 to 30 feet (6-9 m) for small slides, and 80 to 100 feet (25-30 m) thick for larger landslides. Qmsy and Qmso queried where relative age uncertain; Qms queried where classification uncertain. Numerous landslides are too small to show at map scale and more detailed maps shown in the index to geologic mapping should be examined.

Qmg, Qmg?

Mass-movement and glacial deposits, undivided (Holocene and Pleistocene) — Unsorted and unstratified clay, silt, sand, and gravel; mapped where glacial deposits lack typical moraine morphology, and appear to have failed or moved down slope; also mapped in upper Strawberry Bowl (Snow Basin quadrangle) where glacial deposits have lost their distinct morphology and the contacts between them and colluvium and talus in the cirques cannot be mapped; likely less than 30 feet (9 m) thick, but may be thicker in Mantua, James Peak, North Ogden, Huntsville, and Peterson quadrangles.

Tw. Tw?

Wasatch Formation (Eocene and upper Paleocene) – Typically red to brownish-red sandstone, siltstone, mudstone, and conglomerate with minor gray limestone and marlstone locally (see Twl); lighter shades of red, yellow, tan, and light gray present locally and more common in uppermost part, complicating mapping of contacts with overlying similarly colored Norwood and Fowkes Formations; clasts typically rounded Neoproterozoic and Paleozoic sedimentary rocks, mainly Neoproterozoic and Cambrian quartzite; basal conglomerate more gray and less likely to be red, and containing more locally derived angular clasts of limestone, dolomite and sandstone, typically from Paleozoic strata, for example in northern Causey Dam




Project No. 02810-001

Geotechnical & Geologic Hazard Investigation
Lot 74R of Summit Eden Phase 1C
Summit Powder Mountain Resort
Weber County, Utah REGIONAL GEOLOGY MAP 3

Figure

A-8b



Particle-Size Distribution (Gradation) of Soils Using Sieve Analysis

(ASTM D6913)



Project: Silver/Powder Mountain Lot 74R Boring No.: TP-1 No: 02810-001 Station: 10 Location: Powder Mountain

Depth: 8.0' Date: 6/11/2018 Description: Brown gravel with silt and sand

By: DKS/JP

Split: Yes 3/8" Split sieve:

Moist Dry Total sample wt. (g): 28461.40 27391.06


+3/8" Coarse fraction (g): 14566.30 14255.17 -3/8" Split fraction (g): 411.98 389.47

> Split fraction: 0.480

Water content data	C.F.(+3/8")	S.F.(-3/8")	
Moist soil + tare (g):	3863.91	623.90	
Dry soil + tare (g):	3788.01	601.39	
Tare (g):	310.46	211.92	
Water content (%):	2.2	5.8	

				!
	Accum.	Grain Size	Percent	
Sieve	Wt. Ret. (g)	(mm)	Finer	
8"	-	200	-	
6"	-	150	-	
4"	-	100	100.0	
3"	1313.53	75	95.2	
1.5"	4028.67	37.5	85.3	
3/4"	9430.67	19	65.6	
3/8"	14255.17	9.5	48.0	←Split
No.4	92.50	4.75	36.6	
No.10	147.62	2	29.8	
No.20	178.52	0.85	26.0	
No.40	211.57	0.425	21.9	
No.60	244.84	0.25	17.8	
No.100	272.57	0.15	14.4	
No.140	288.16	0.106	12.5	
No.200	307.80	0.075	10.1	

No.200 Gravel (%): 63.4 Sand (%): 26.5



Entered by:_ Reviewed:_

Grain size (mm)

Minimum Laboratory Soil Resistivity, pH of Soil for Use in Corrosion Testing, and



Ions in Water by Chemically Suppressed Ion Chromatography (AASHTO T 288, T 289, ASTM D 4327, and C 1580)

Project: Buttgenbach Lot 44

No: 02732-001

Location: Powder Mountain

Date: 3/1/2018 By: BSS

e	Boring No.		TP-	2					
Sample info.	Sample								
Sa	Depth		9.0'						
ıta	Wet soil + tare (g)		144.4	41					
Water ntent da	Dry soil + tare (g)		134	32					
Water content data	Tare (g)		37.9	5					
CO)	Water content (%)		10.:	5					
ata	рН		5.5	7					
Chem. data	Soluble chloride* (ppm)		72.0	0					
hen	Soluble sulfate** (ppm)		516	5					
C									
	Pin method		2						
	Soil box	A	Miller S	Small		A	1	1	
		Approximate Soil	Resistance	Soil Box		Approximate Soil	Resistance	Soil Boy	
		condition			Resistivity	condition	Reading		Resistivity
		(%)	(Ω)	(cm)	$(\Omega\text{-cm})$	(%)	(Ω)	(cm)	$(\Omega\text{-cm})$
		As Is	53480	0.67	35832				
		+3	24660	0.67	16522				
		+6	16500	0.67	11055				
Resistivity data		+9	13990	0.67	9373				
ity 6		+12	14240	0.67	9541				
stiv									
esi									
	3.61								
	Minimum resistivity $(\Omega ext{-cm})$		937	3					

*	Doufoussad	L.,	ASSTAT		EDA	200.0
•	Performed	υy	AWAL	using	EPA	300.0

Entered by:_	
Reviewed:	

^{**} Performed by AWAL using ASTM C1580

Minimum Laboratory Soil Resistivity, pH of Soil for Use in Corrosion Testing, and



Ions in Water by Chemically Suppressed Ion Chromatography (AASHTO T 288, T 289, ASTM D4327, and C1580)

Project: Lot 75R - Powder Mountain

No: 02347-001 Location: Eden, UT Date: 7/27/2016

By: ET

									1
ple J.	Boring No.								
Sample info.	Sample		75F	}					
S	Depth								
ata	Wet soil + tare (g)		106.	77					
iter it da	Dry soil + tare (g)		96.7	'5					
Water content data	Tare (g)		37.3	3					
CO1	Water content (%)		16.9	9					
ta	рН		5.24	4					
. da	Soluble chloride* (ppm)		8.40	6					
Chem. data	Soluble sulfate** (ppm)		73.3	8					
ŭ	**								
	Pin method		2						
	Soil box		Miller S	Small					
		Approximate				Approximate			
		Soil	Resistance			Soil	Resistance		
		condition	_	_	Resistivity	condition	_	_	Resistivity
		(%)	(Ω)	(cm)	(Ω-cm)	(%)	(Ω)	(cm)	(Ω-cm)
		As Is	9850	0.67	6600				
		+3	7770	0.67	5206				
		+6	7568	0.67	5071				
Resistivity data		+9	8378	0.67	5613				
ity 6									
stiv									
esi									
²²									
	Minimum resistivity		507	1					
	$(\Omega ext{-cm})$		507	1					

^{*} Performed by AWAL using EPA 300.0

Entered by:_	
Reviewed:	

^{**} Performed by AWAL using ASTM C1580

Direct Shear Test for Soils Under Drained Conditions

(ASTM D3080)



Project: Buttgenbach Lot 44 Boring No.: TP-1 No: 02732-001 Station: 40


Location: Powder Mountain **Depth: 3.0'**


Date: 2/19/2018 Sample Description: Reddish brown clayey sand

By: EH Sample type: Arbitrary remold

Test type: Inundated Lateral displacement (in.): 0.3 Shear rate (in./min): 0.0033 Specific gravity, Gs: 2.65 Assumed

	Sam	ple 1	Samj	ole 2	Sam	ple 3
Nominal normal stress (psf)	40	000	2000		1000	
Peak shear stress (psf)	31	.00	15	30	8	60
Lateral displacement at peak (in)	0.3	300	0.2	.97	0.3	300
Load Duration (min)	6	54	6	6	8	30
	Initial	Pre-shear	Initial	Pre-shear	Initial	Pre-shear
Sample height (in)	0.994	0.929	0.998	0.964	1.003	0.985
Sample diameter (in)	2.419	2.419	2.418	2.418	2.417	2.417
Wt. rings + wet soil (g)	196.27	198.22	199.03	203.36	198.60	204.23
Wt. rings (g)	44.33	44.33	46.52	46.52	45.64	45.64
Wet soil + tare (g)	266.52		266.52		266.52	
Dry soil + tare (g)	253.87		253.87		253.87	
Tare (g)	154.02		154.02		154.02	
Water content (%)	12.7	14.1	12.7	15.9	12.7	16.8
Dry unit weight (pcf)	112.5	120.3	112.5	116.4	112.4	114.4
Void ratio, e, for assumed Gs	0.47	0.37	0.47	0.42	0.47	0.45
Saturation (%)*	71.3	100.0	71.4	100.0	71.1	100.0
φ' (deg) 37		Average o	f 3 samples	Initial	Pre-shear	
c' (psf) 75		Water	content (%)	12.7	15.6	
*Pre-shear saturation set to 100% for phase calculations		Dry unit	weight (pcf)	112.5	117.0	





Nominal normal stress (psf)

APPENDIX C

USGS Design Maps Summary Report

User-Specified Input

Report Title Lot 74R

Mon June 18, 2018 23:43:15 UTC

Building Code Reference Document 2012/2015 International Building Code

(which utilizes USGS hazard data available in 2008)

Site Coordinates 41.36292°N, 111.74712°W

Site Soil Classification Site Class C – "Very Dense Soil and Soft Rock"

Risk Category |/||/|||



USGS-Provided Output

$$S_s = 0.812 g$$

$$S_{MS} = 0.873 g$$


$$S_{DS} = 0.582 g$$


$$S_1 = 0.269 g$$

$$S_{M1} = 0.412 g$$

$$S_{D1} = 0.275 g$$

For information on how the SS and S1 values above have been calculated from probabilistic (risk-targeted) and deterministic ground motions in the direction of maximum horizontal response, please return to the application and select the "2009 NEHRP" building code reference document.





Although this information is a product of the U.S. Geological Survey, we provide no warranty, expressed or implied, as to the accuracy of the data contained therein. This tool is not a substitute for technical subject-matter knowledge.

1 of 1 6/18/2018, 5:43 PM

USGS Design Maps Detailed Report

2012/2015 International Building Code (41.36292°N, 111.74712°W)

Site Class C - "Very Dense Soil and Soft Rock", Risk Category I/II/III

Section 1613.3.1 — Mapped acceleration parameters

Note: Ground motion values provided below are for the direction of maximum horizontal spectral response acceleration. They have been converted from corresponding geometric mean ground motions computed by the USGS by applying factors of 1.1 (to obtain S_s) and 1.3 (to obtain S_1). Maps in the 2012/2015 International Building Code are provided for Site Class B. Adjustments for other Site Classes are made, as needed, in Section 1613 3 3

From Figure 1613.3.1(1) [1]

 $S_S = 0.812 g$

From Figure 1613.3.1(2) [2]

 $S_1 = 0.269 g$

Section 1613.3.2 — Site class definitions

The authority having jurisdiction (not the USGS), site-specific geotechnical data, and/or the default has classified the site as Site Class C, based on the site soil properties in accordance with Section 1613.

2010 ASCE-7 Standard – Table 20.3-1 SITE CLASS DEFINITIONS

Site Class	_ 	\overline{N} or \overline{N}_{ch}	– S _u		
A. Hard Rock	>5,000 ft/s	N/A	N/A		
B. Rock	2,500 to 5,000 ft/s	N/A	N/A		
C. Very dense soil and soft rock	1,200 to 2,500 ft/s	>50	>2,000 psf		
D. Stiff Soil	600 to 1,200 ft/s	15 to 50	1,000 to 2,000 psf		
E. Soft clay soil	<600 ft/s	<15	<1,000 psf		
	Any profile with more than 10 ft of soil having the				

Any profile with more than 10 ft of soil having the characteristics:

- Plasticity index PI > 20,
- Moisture content $w \ge 40\%$, and
- Undrained shear strength $s_{\rm u} <$ 500 psf

F. Soils requiring site response analysis in accordance with Section 21.1

See Section 20.3.1

For SI: $1ft/s = 0.3048 \text{ m/s} 1lb/ft^2 = 0.0479 \text{ kN/m}^2$

1 of 4 6/18/2018, 5:43 PM

Section 1613.3.3 — Site coefficients and adjusted maximum considered earthquake spectral response acceleration parameters

 $\label{eq:table 1613.3.3(1)} \text{VALUES OF SITE COEFFICIENT } \textbf{F}_{a}$

Site Class	Mapped Spectral Response Acceleration at Short Period								
	$S_{S} \le 0.25$	$S_S = 0.50$	$S_S = 0.75$	$S_S = 1.00$	S _s ≥ 1.25				
А	0.8	0.8	0.8	0.8	0.8				
В	1.0	1.0	1.0	1.0	1.0				
С	1.2	1.2	1.1	1.0	1.0				
D	1.6	1.4	1.2	1.1	1.0				
Е	2.5	1.7	1.2	0.9	0.9				
F	See Section 11.4.7 of ASCE 7								

Note: Use straight-line interpolation for intermediate values of S_s

For Site Class = C and $S_s = 0.812 g$, $F_a = 1.075$

TABLE 1613.3.3(2) VALUES OF SITE COEFFICIENT F_{ν}

Site Class	Mapped Spectral Response Acceleration at 1–s Period								
	$S_1 \le 0.10$	$S_1 = 0.20$	$S_1 = 0.30$	$S_1 = 0.40$	$S_1 \ge 0.50$				
А	0.8	0.8	0.8	0.8	0.8				
В	1.0	1.0	1.0	1.0	1.0				
С	1.7	1.6	1.5	1.4	1.3				
D	2.4	2.0	1.8	1.6	1.5				
E	3.5	3.2	2.8	2.4	2.4				
F	See Section 11.4.7 of ASCE 7								

Note: Use straight-line interpolation for intermediate values of S₁

For Site Class = C and S_1 = 0.269 g, F_v = 1.531

Equation (16-37):
$$S_{MS} = F_a S_S = 1.075 \times 0.812 = 0.873 \text{ g}$$

Equation (16-38):
$$S_{M1} = F_v S_1 = 1.531 \text{ x } 0.269 = 0.412 \text{ g}$$

Section 1613.3.4 — Design spectral response acceleration parameters

Equation (16-39):
$$S_{DS} = \frac{2}{3} S_{MS} = \frac{2}{3} \times 0.873 = 0.582 g$$

Equation (16-40):
$$S_{D1} = \frac{2}{3} S_{M1} = \frac{2}{3} \times 0.412 = 0.275 g$$

3 of 4 6/18/2018, 5:43 PM

Section 1613.3.5 — Determination of seismic design category

TABLE 1613.3.5(1)
SEISMIC DESIGN CATEGORY BASED ON SHORT-PERIOD (0.2 second) RESPONSE ACCELERATION

VALUE OF S _{DS}	RISK CATEGORY		
	I or II	III	IV
S _{DS} < 0.167g	А	А	А
$0.167g \le S_{DS} < 0.33g$	В	В	С
$0.33g \le S_{DS} < 0.50g$	С	С	D
0.50g ≤ S _{DS}	D	D	D

For Risk Category = I and S_{DS} = 0.582 g, Seismic Design Category = D

TABLE 1613.3.5(2)

SEISMIC DESIGN CATEGORY BASED ON 1-SECOND PERIOD RESPONSE ACCELERATION

VALUE OF S	RISK CATEGORY		
VALUE OF S _{D1}	I or II	III	IV
S _{D1} < 0.067g	А	А	А
$0.067g \le S_{D1} < 0.133g$	В	В	С
$0.133g \le S_{D1} < 0.20g$	С	С	D
0.20g ≤ S _{D1}	D	D	D

For Risk Category = I and $S_{D1} = 0.275$ g, Seismic Design Category = D

Note: When S_1 is greater than or equal to 0.75g, the Seismic Design Category is **E** for buildings in Risk Categories I, II, and III, and **F** for those in Risk Category IV, irrespective of the above.


Seismic Design Category \equiv "the more severe design category in accordance with Table 1613.3.5(1) or 1613.3.5(2)" = D


Note: See Section 1613.3.5.1 for alternative approaches to calculating Seismic Design Category.


References


- 1. *Figure 1613.3.1(1)*: https://earthquake.usgs.gov/hazards/designmaps/downloads/pdfs/IBC-2012-Fig1613p3p1(1).pdf
- 2. *Figure 1613.3.1(2)*: https://earthquake.usgs.gov/hazards/designmaps/downloads/pdfs/IBC-2012-Fig1613p3p1(2).pdf


4 of 4 6/18/2018, 5:43 PM





















c'	100	psf	Effective Cohesion (including apparent cohesion for coarse, angular soils)
φ'	30	deg	Effective Friction Angle
\mathbf{Y}_{sat}	136	pcf	Saturated Unit Weight of Soil
Y_{w}	62.4	pcf	Unit weight of water
	_	la.	
h	4	ft	Depth to shear surface
β	15.9	deg	Slope Gradient (3.5H:1V)



This model assumes c>0 and the face of the slope is saturated to depth h

