

## UPDES STORM WATER INSPECTION FORM

Revision 09/23/09

(IMPORTANT)
PLACE YOUR CITY
LOGO OR TYPE IN
THE NAME OF YOUR
CITY IN THIS BOX

BACKGROUND INFORMATION								
Site Name:	The Summit at Ski Lake 10 Date of Evaluation: 923 2010							
Site Address:	1380 South Via Cortina Huntsville, Ut 84317							
Inspected By: POCV	relle Pleaste	Y	Existing Wes	Existing Weather Conditions: (01 SUNNU				
UPDES Permit #:	UTR1	05010	Start/End Tir	Start/End Time: 12/12/2005				
Permit Effective Date:	4/15/	Permit Expir	Permit Expiration Date: 4/15/2007			7		
Total Project Area:			Total Disturb	Total Disturbed Area: 4 acres				
Describe present phase o construction:	t WPPC	ars to be	e compete					
Type of Inspection: (place bold letters In box)	(ox) Subdivision Commercial Industrial Linear (road/pipe/power) Land Disturbance							
Reason for Inspection: (Place bold letters in box)	Scheduled	Response to complaint / tip inspection List Receiving Waters:						
Date of last rain event:	1/22/2010	Duration:	Approximate Rainfall (in):					
CONTACT INF	ORMATION							
	NAMES	P	HONE NUME	BERS	S E-MAIL			
Operator:	Ronald J. Canta	nzaro	801-391-4682		skilakeinfo@aol.com			
Operator Co-permittee:			SOLOCI 1002					
Onsite Facility Contact:								
Important Contacts:	ERMINATION (N	IOT)						
		YES	NO		COMM	IENTS		
Has the site been permanently stabilized according to permit						Children do		
requirements?		**************************************			T.			
Have all temporary BMP's	s been removed?							
Have post-construction el with approved project dra								
Is the site acceptably clea								
is the site acceptably clear								
Municipal Inspector: EPA Form 3560-3 SEV Codes and De			Signature:					
Inspection	SW sampling Inspector	(S) State	Type Code					
Code (Place X in box):	SW non- Code (Place X in box):	(L) Local	(place # in box):		1 - Municipal	2 - Industrial	3 - Federal	
7.1.1 33.1,1	sampling	(2) 20001	- 1	ditional abou	ata of porrative piets	uran and abankl	ioto includina	
Place X by applicable Violation			(Attach ac	(Attach additional sheets of narrative, pictures and checklists, including Single Event Violation codes, as necessary)				
2 L F J 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		ngle Event Violation (		Storm Water				
CODE	DESCR		CODE DESCRIPTION					
DOR11	Discharge without a permit		BR19B		Failure to properly operate and maintain BMP's			
DOR18	Failure to apply for a Notice	DOR12		Failure to submit required permit information				
BOR12	Failure to conduct inspection	EOR16		Failure to submit required report (non-DMR)				
BOC17	Failure to develop any or a	P AOR22 EOR14		Narrative effluent violation				
BOC18	Failure to implement SWP Failure to maintain records	AOR12		Noncompliance with section 308 information request  Numeric effluent violation				
BOR41 COR11	Failure to maintain records	BOR42		Violation of a mileston	O DESCRIPTION OF THE PROPERTY OF			
BR19A	Failure to properly install/in	DOTAL		1.5idion of a fillesto	io in an order			

SWPPP INFORMATION	YES	NO	COMMENTS
Has a pre-construction review of the SWPPP been conducted by the County or Local Jurisdiction? If yes, name the entity and person who performed the review in comments section.(Check with Engineer)	X		chad mayer hoffer
During the pre-construction review, has the SWPPP been reviewed for post-construction elements? (i.e. grass swales, permanent detention basins, etc;.) List all controls in comments section.	X		
3. Is a SWPPP located on the construction site?		X	unable to locate
Is the SWPPP posted or easily accessible to inspectors?		X	()
5. Is a current NOI and copy of the State permit included with the SWPPP?		X	_ (1
Are the names and telephone numbers of the current responsible contact people listed in the SWPPP?		X	(1
Did the "Operator" sign the SWPPP with authorization and certification statements?		X	'I
Does the SWPPP contain the site description, sequence of construction activities, and areas of the site to be disturbed?		Χ	()
Does the SWPPP contain locations of storm drains, surface drainage patterns, and locations of storm water discharges?		Χ	lı .
Does the SWPPP include the site map, sediment, and erosion control design drawings, showing both structural and non structural BMPs?		χ	11
11. Does the SWPPP and/or site map address waste control & disposal, off site tracking, sanitary concerns, exposure to construction materials, laydown or storage areas, administrative trailers, etc.?		Χ	11

(Attach additional sheets of narrative, pictures and checklists, as necessary)

BMP/HOUSEKEEPING INFORMATION	YES	NO	COMMENTS
Are all sediment & erosion control BMP's that are deployed on the site updated and marked on the site map? (BMPs that are no longer necessary should be crossed out and dated, new BMPs drawn in and dated.)		Χ	unable to locate SWPPP
Does the SWPPP contain updated submittals, specifications, and engineering for BMPs (both structural and non-structural)?		X	((
Are on-site inspection reports included with the SWPPP? (i.e. in compliance with state permit requirements)		×	n n
4. Are on-site inspections being performed by a qualified person on a bi-weekly basis and within 24 hours after a measurable weather event, and/or at the required interval identified in the SWPPP?		×	Н
5. Have all on-site corrective action items from previous inspections been addressed and documented within the timeframe allotted by the inspector?		×	11
6. Are off-site flows entering the construction site?		X	
7. Is there evidence of, or the potential for, increased pollutant (i.e., sediment, fuel, concrete waste, portable toilet waste, etc.) loading to enter the storm water conveyance system as a result of the lack of maintenance or improper BMP installation?	X		reels have formed on the down hill side of ragsediments
8. Are construction products, chemicals, and supplies managed properly with good housekeeping, pollution prevention, and proper waste management?	X		12 13211124-1-
Have any areas been left dormant, disturbed, and exposed for more than 14 to 21 days without stabilization (except for snow cover or frozen ground)?	X		downwill side of road
Does repair/maintenance of existing sediment and erosion control BMPs need to occur?	X		redegitate
Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site to downstream locations?		×	sediment has not left the
12. Are vehicles tracking sediment off the construction site onto nearby roads or parcels of land?		X	
13. If applicable, is soil, construction material, landscaping items, or other debris evident on the streets?		X	
14. Are BMPs properly located?	X		Stabilization intensures necessar
15. Are there locations where additional BMPs should be installed that are not identified in the SWPPP?	X		downhill side of rd
16. Have post-construction elements i.e. (grass swales, permanent detention basins, etc.) been installed per plans and inspected ? (list all controls in comments section)		Χ	site is not stable
17. Do locations exist where BMPs could be removed?		X	
18. Does your site evaluation indicate a need to update and document the SWPPP report and accompanying sediment and erosion control drawings within the next seven (7) days?	X		

(Attach additional sheets of narrative, pictures and checklists, as necessary)

## CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE

Site Name: The SUMMIT at 94 Lake 10 Date of Evaluation:	923/2010					
Detail Report Identify the problem and its location. If appropriate, describe (in general terms) what needs to be completed. However, only if qualified (e.g., you are a designer) should you be mandating specific BMPs to install.	Correction due by:					
"post swppp wil required documentation (b)-weekly's inspections)	9/23/2010					
Estabaltie enosion on downill side of va	9/23/2010					
3						
4.						
5						
6.						
7.						
8.						
9.						
10.						
Inspector: I certify that this document and all attachments were prepared under my direction. The information submitted is, to the best of my know accurate, and complete.	vledge and belief, true,					
Rechelle Preaster 8x299-8372 Norlillak						
(Print Name) (Phone Number) (Signature)  (VOICH MUNGALV IS)  (Title or Position) (Date)	abalana					
Operator/Operator Representative: I have received a copy of this Inspection Form						
Lonald J. Cantanzaro enailed to: Stilateinto e aol.com						
(Print Name) (Signature)						
Wesident 9-13-2010 (Date)						



PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Curtis Christensen, P.E. County Engineer

RE: The Summit at Ski Lake 10

Random Storm Water Inspection performed of the site on September 23, 2010.




Downhill side of road is not stable



Erosion is evident



PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Curtis Christensen, P.E. County Engineer



Reels have formed due to the erosion



Uphill side of road is not stable



PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Curtis Christensen, P.E. County Engineer



Sediment has occurred from the erosion

