



Intermountain GeoEnvironmental Services, Inc.
12429 South 300 East, Suite 100, Draper, Utah 84020 ~ T: (801) 748-4044 ~ F: (801) 748-4045

August 18, 2015

Summit Powder Mountain
c/o Ms. Andrea Milner
3632 North Wolf Creek Drive
Eden, Utah 84310

IGES Project No. 01628-008

Subject: Addendum to Geotechnical Report
The Ridge Nests Development
Powder Mountain Resort
Weber and Cache Counties, Utah


Reference: IGES, Inc., 2014, Geotechnical Investigation, The Ridge Nests Development, Powder Mountain Resort, Weber and Cache Counties, Utah Project No. 01628-008, dated September 16, 2014

Ms. Milner:

It has recently come to our attention that there is an error in the referenced geotechnical report; in Section 5.9 Soil Corrosion Potential, the second paragraph indicates "...a *corrosion engineer* should also provide an assessment of any concrete that will be in contact with native soils." This is incorrect; it was our intention to indicate that an assessment of metal, not concrete, was recommended. This sentence should correctly read "...a *corrosion engineer* should also provide an assessment of any **metal** that will be in contact with native soils."

If you have any questions please contact the undersigned at your convenience (801) 748-4044.

Respectfully Submitted,
IGES, Inc.



David A. Glass, P.E.
Senior Geotechnical Engineer