

SWPPP COMPLIANCE INSPECTION FORM



Project Name:	Reed Baron	Reed Baron Address: 2548 North Elkhorn Trail		il	Date:	4/4/201	3
Owner:	Reed Baron	Contractor (Gen/Sub):	Reed Baron	eed Baron		time: 1:00 PM	
Site Contact:	Reed Baron	Phone:	602-692-3572		Stop time:	1:15 PI	М
UPDES Permit #:	UTR360513 Expiration:	6/11/2013 Weather: Su	nny Cloudy Raining	Snowing O	ther: 64°		
Date of last rain event:	4/1/2013	Duration:	Approx. Rainfall (in):		0.59in		
Inspected By (Print):	Kelci Huffaker/Rochelle	e Pfeaster Local Jurisdiction		Weber			
Reason for Inspection:	- PROPERTY AND ADDRESS OF THE PARTY OF THE P		ng Waters:	Pinev			
	sampling	(S) State		-			
	on-sampling Inspector Code (circle	e): Type Code	(circle): 1 - Municipa	2 - Industrial	3 - State		
	SWPPP, EROSION, SEDII	WENT AND HOUSEKEEPIN	G BMP's INFORMAT	ION	Y	ES NO	N/A
1. Is the SWPPP on site	and accessible, or is the SWPPP lo	cation posted in an obvious place and	reasonably accessible (in a	short time)?		X	
		ping BMP's installed on the site as sh				X	
		onditions (modifications dated & initia /PPP, SWPPP amendment Log, etc.)		n site map, discon	ntinued	X	
		a qualified person on a weekly or biwe		quired by permit?	(Inspector	х	
		action, new BMPs, removed BMPs, di		the increases?		- 0400	
		been addressed and documented wit entrolled, managed, or diverted around			fence.	X	
upgradient boundary div	ersion, down gradient boundary sedi	ment control, etc.)			onec,		х
7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?						X	
8. Is there evidence of vehicles tracking soil off the construction site?						X	
9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a storm drain or water body?						x	
10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface						x	
roughening, pipe slope drain, dust control, etc)? 11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, waddles,							
straw bails, curb cut-bac	NA SUPERIOR DE LA CONTRACTOR DE LA CONTR			- Ad		X	
	(1987년) 일본 시간 시간 전 경기 시간 전 경기 시간 (1987년 1987년 198	ekeeping controls (clean track out pac concrete wash out area, proper curb r	[이 사이다 : 10 - 10 10 10 10 10 10 10 10 10 10 10 10 10	teriais manageme	ent,	x	
		activities for 14 to 21 days without sta		ozen ground)?		х	
14. Are there places who	ere BMPs are needed and should be	installed or not needed and should be	removed?		j.	x	
	COMMENTS AN	ID CORRECTIVE ACTIONS	FOR SWPPP COMP	LIANCE			
Identify the problem and its	location. If appropriate, describe (in gene	ral terms) what needs to be completed. Ho to install. Include the date when correct		are a designer) shou	ild you be manda	ting specific	BMPs
T. 0WDDD .							
The SWPPP was not on							
The silk fence was not p	roperly installed and in need of repair	r in multiple locations					_
	all applicable SEV codes:						
		vere prepared under my direction or superv iry of the person or persons who manage th					eriy
information submitted is, to t of fine and imprisonment for	경기 시간 사람이 아니는 아니는 아들은 아니는 사람이 없는 아니라 아니는 사람이 아니는 사람이 살아 없다.	accurate, and complete. I am aware that th	ere are significant penalties for su	bmitting false inform	ation, including th	ne possibility	y
are improved to			121-4	1/11			
Inspector: K	Kelci Huffaker/Rochelle Pfeaster		Kelu H	allokeen		4/9/201	3
	(Print Name)	(Title)	1	(Signature)		(Date))
	121 SSM		250 40	1 80000	202	Secretar	
Operator:	Reed Baron (Print Name)	Owner (Title)	Emailed to	c: rayminfo1@gma (Signature)	ail.com	4/9/201 (Date)	_
modified 8/12/10	(Contradis)	(1100)		(Signaturo)		(Date)	