



Larry Slagkowski
Weber County Surveyor
2380 Washington Blvd. #240
Ogden, UT 84401

RE: Development Parcel D, Village Nests
Response to Surveyor's Comments

Mr. Slagkowski,

The following are comments and responses pertaining to the Village Nests Plat from your review and received on November 7, 2013.

Sheet 1:

1. Update Surveyors Certificate.

Response: Updated Surveyors Certificate with Weber County's Language.

2. Are building outside of lots?

Response: No, A few Building pads are adjacent to the lot lines; however, the actual buildings are at least 2' inside of building pads.

3. Consider using a single bearing for the ties to the point of beginning

Response: Keep ties the same, to keep consistency with other Plats.

4. Check ties between Units 15 and 18.

Response: Checked all ties for Units 15,17 and 18. Found less than .01' of error.

5. Information on road is missing on Phase 1D submittal.

Response: Information for road on Phase 1D preliminary Submittal was updated.

6. Ties on this Plat are the same as Phase 1D with different points of beginning.


Response: Updated ties for this Plat.

7. Are these building not right angles? Check building dimensions

Response: Updated building pad dimensions.

OFFICES NATIONWIDE

Best Regards,

A handwritten signature in black ink, appearing to read "Richard W. Miller". The signature is fluid and cursive, with a large initial 'R'.

Richard Miller, PLS
Survey Manager

NIVIS

OFFICES NATIONWIDE