

SWPPP COMPLIANCE INSPECTION FORM



Project Name:	Project Name: Powder Mtn Road and Utility Project			Address: Summit Pass [Date: 7/15/2014		
Owner:	Weber County		Contractor (Gen/Sub):	Geneva Rock Products	S	Start tim	ne: 3	:00	
Site Contact: Dexter Tan Phone: 435-890-9893 Stop time:								30	
UPDES Permit	#: UTR36442	25 Expiration:	7/23/2014 Weat	her: Sunny Clou	dy Raining Sr	nowing Other:			
Date of last rain	n event: unknown		Duration: n/a	Approx. Ra					
Inspected By (F	a et al.	huler		Jurisdiction or County:					
						interior de la company			
Reason for Inspection	SW-sampling	duled Compla	int/Tip Random (S)-State	Receiving Waters:	miscellaneous mou	untainside drainages			
Code (circle):	SW non-sampling	Inspector Code (circle):	(L) Local	Type Code (circle):	1 - Municipal	2 - Industrial 3 - 5	State		
		P, EROSION, SEDIM					YES	NO	N/A
1. Is the SWPP	P on site and accessit	ole, or is the SWPPP loca	ation posted in an obviou	s place and reasonably	accessible (in a shor	t time)?		X	
2. Are erosion of	control, sediment contr	ol, and good housekeepir	ng BMP's installed on th	e site as shown in the S	WPPP?				×
BMPs crossed	off site map, new BMP	details & spec's in SWP	PP, SWPPP amendmer	nt Log. etc.)?	ap, new bivies on sit	e map, discontinued			×
4. Are on-site in	nspections being perfor	rmed and recorded by a c	qualified person on a we	ekly or biweekly basis, re		ed by permit? (Inspect	or		×
		ms/repairs, corrective act m previous inspections be				inepactor?			~
		the construction site cont							
upgradient bou	ndary diversion, down	gradient boundary sedime	ent control, etc.)	97%	200		X	X	
		narge such as mud flows		construction site in dow	nstream locations?			X	
		ng soil off the construction						X	
storm drain or v		landscaping items, or oth	ner debris piled on imper	vious surfaces (roads, d	irives) that could be v	vashed with SW to a		X	
10. Is there a ne		, or improve erosion contr ntrol, etc)?	rol BMPs (temporary sta	bilization, erosion blanke	ets, mulch, vegetated	strips, rip rap, surface	×		
		, or improve sediment cor	ntrol BMPs (silt fence, ch	neck dams, fiber rolls, se	ediment trap/basin, in	let protection, wattles,	×		
	b cut-back, etc?	, or improve good housek	reening controls (clean t	rack out had sweening	construction materia	als management			-
		ed down, fueling areas, co				as management,	X		
13. Are there di	sturbed areas that hav	e not had construction ac	ctivities for 14 to 21 days	without stabilization? (e	xcept snow or frozen	ground)?		Х	
14. Are there pl	aces where BMPs are	needed and should be in	stalled or not needed ar	d should be removed?				×	
	em and its location. If appl	ropriate, describe (in general	to install. Include the date		qualified (e.g., you are a		mandating	specific	BMPs
(2.10.	Stake don	n port-a-		., - 0-					
((. N	aintoi.	silt fence							
10. 7	Lat card	1 1 1		ster Just	10:	'25' 6			
10.	Last Conn	Co into	(- 11	,		s an issue	•		
	location o	+ project h	ulps in th	at the in	react of	dust on			
	others is	minimal							
			(I						
	30 2 0.33		-						
									-

			•						
Inspector plea	ase list all applicable	SEV codes:	BURB						
l certify under pen	alty of law that this docum	nent and all attachments were	e prepared under my direction	on or supervision in accorda	ance with a system desig	gned to assure that qualif	ed personr	el prope	erly
gathered and eval information submit	uated the information subi	mitted. Based on my inquiry o nowledge and belief true, acc	of the person or persons wh	o manage the system, or th	nose persons directly res	sponsible for gathering the	e informatio	n, the	
Inspector:	Dana (Q. Shuler	Engineer. W	/eber County	(Dana	Q. Shuler)	1151	14	
		t Name)		tle)		gnature)	- 1 1	(Date)	
Operator:	email	d to Don	des Ton						
modified 8/12/10	(Print	t Name)	(T)	tle)	(Si	gnature)		(Date)	

(Attach additional sheets of narrative, pictures and checklists, as necessary)



ADDITIONAL COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE



Site Name:	Powder Mtn Road and Utility Project	Date of Evaluation:	7/15/2014 Page	of
Site Address:	Summit Pass	COS O STANIS COST		
				and the second s
n/a	And			
				AND II
	The second secon			
	**************************************			3
	All regions	106.46.00.00.00.00.00.00.00.00.00.00.00.00.00		181.00

			1.0	
	4.00			
			AW	2000
1-2	PARA P.			
				WW9167
		*		

				4.500
	A STATE OF THE STA			
			1	

			Access to the contract of the	
	EDA Corm 2560	3 SEV Codes and Descr	intions	
DOR11	Discharge without a permit	BR19B	Failure to properly operate and mainta	ain BMP's
DOR18	Failure to apply for a Notice of Termination	BR19A	Failure to properly install/implement E	
BOR12	Failure to conduct inspections	EOR16	Failure to submit required report (non	
BOC17	Failure to develop any or adequate SWPPP/SWMP	AOR22	Narrative effluent violation	
BOC18	Failure to implement SWPPP/SWMP	DOR12	Failure to submit required permit info	ormation
BOR41	Failure to maintain records	AOR12	Numeric effluent violation	
COR11	Failure to monitor	BOR42	Violation of a milestone in an order	