Weber County

☐ Storm Drain ☐ Roadway

☐ Testing

☐ Secondary Water

Substan. Compl. Insp.

Public Works / Engineering



ENGINEERING INSPECTION REPORT

REPORT LEFT __

Work has been buried

Reinspection fee

STOP VORK

Inspector (Ann M. Engineering Division 2380 Washington Blvd. Ste. 240 Fax (801) 399-8862 Ogden, Utah 84401 Phone (801) 399-8374 LAND USE JOB ADDRESS 4160 W. 900 SOLUTO PERMIT NO. Public Works Project CONTRACTOR/OWNER LAPP CONSTRUCTION DATE 7/31/2014 APPT. TIME 11:00 Single Family Subd. P.R.U.D. PROJECT NAME WEST WEBER TURNELLARY ☐ Commercial/Site Plan REAS□N F□R INSPECTI□N 🙀 Called 🔲 Routine 🔲 Complaint Phone 🔔 □ Other DVERTIME INSPECTION ___ TYPE OF INSPECTION Asphalt PERSON CONTACTED: ___ ☐ Curb & Gutter Sidewalk COMMENTS ☐ Driveway Approch Agound ☐ Sewer Inspection To Easure THERE □ Water STATED THEY WIFEE ☐ Telephone Cable T.V. Gas Storm Drain ASTHAUT Power ☐ Other PROJECT PROGRESS PLACE Platted ☐ Pre-Construction ☐ £{EKPW ☐ Contracts ____ Date Forwarded __ Responsible Agency — Water Sanltary Sewer

FOR AN INSPECTION APPOINTMENT, CALL 24 HOURS IN ADVANCE (801) 399-8374

Prior violations not corrected

Work in Compliance

Work not ready

Prior Violations Corrected

 ${\color{red} igwedge}$ Items listed in comments will be reinspected at the next inspection

WORK IN

COMPLIANCE

UNABLE TO

MAKE INSP.

WORK IN

VIOLATION

Before the work covered by this permit begins, the holder shall make proper provisions for protecting the public with necessary barricades, lights, and with all other appurtenances necessary to safeguard the users of such roadway, sidewalk and other facilities. It is further understood and agreed that the holder of this permit is responsible for any liability or personal injury resulting from such construction. Holder agrees to execute an indemnity agreement running to Weber County, indemnifying the County against all claims, demands, costs, damages, attorney's fees and other expenses of kind occasioned by said construction.

Cannot contact persons requesting insprction

Approved plans not available as required

Make corrections as noted in comments

Work must be reinspected before continuing