

# U P W A L L                      D E S I G N

A R C H I T E C T S  
1025 EAST HOLLYWOOD AVENUE SALT LAKE CITY, UTAH 84105 (801) 485-0708 FAX(801) 485-6992

9 August, 2016

Weber Fire District  
2023 W 1300 N, Ogden, UT 84404  
Phone: (801) 782-3580

Attention: Brandon Thueson, Fire Marshal

Re: Geary Hillside Review Lot 37R Plan Review Comments – 28 July, 2016

Mr. Thueson,

The Following responses address the Plan Review Comments referenced above.

**Specific Comments:**

4. *Submit a completed "Fire Hazard Severity Form" (appendix C of the 2006 Utah Wildland Urban Interface Code).*

Response:

The "Fire Hazard Severity Form" is enclosed.

6. *Roof materials: Plan notes indicated that the roof will have wood shake shingles. These materials are not compliant with the UWUI code. Adjust as needed to conform to the requirements.*

Response:

Reference to wood shake shingles has been removed from sheet A4.0

7. *Rooftop garden shall be maintained as outlined in section 317 of the International Fire Code*

Response:

Note has been added to sheet A4.1

Please let me know if you have any questions.

Sincerely,



Josh Arrington  
Project Manager, Upwall Design Architects