

Hooper Irrigation Company

P.O. Box 184

Hooper, UT 84315

Phone (801) 985-8429 Fax (801)985-3556

Email: HooperIrrigationCo @ msn.com

Board of Directors:

President Theo G Cox, Vice President Rex Hancock, Treasurer John Diamond , Dave Favero, Clint Naisbitt, Stan Fowers, and Dale Fowers

11/28/16

Taylor Vista Subdivision
4700 W 2550 S (approximate)
Taylor, Utah 84401

Re: Secondary Water

To whom it may concern:

The above mentioned Subdivision has sufficient shares of Hooper Irrigation "A" Stock to connect to the Pressurized Secondary System which is available in this location. The requirement for connecting to Secondary Water is a $\frac{1}{2}$ share for each lot as well as a \$3,500 connection fee per lot. A preliminary plat map has been reviewed and preliminary approval has been given. Currently, Hooper Irrigation Company can and will serve Taylor Vista Subdivision with Pressurized Irrigation Water when all standards and guidelines for Hooper Irrigation have been met and approved including all water turned in and fees paid.

If you have any further questions please call the Company Office at (801)985-8429.

Sincerely,



Michelle Pinkston
Board Secretary