

SWPPP COMPLIANCE INSPECTION FORM




Project Name:	Reed Baron	Address:	2548 N Elkhorn Trail Eder	orn Trail Eden, Utah Date		9/5/2012		2
Owner:	Private	Contractor (Gen/Sub):	Reed Baron		Start time: 3:47 PM		Λ	
Site Contact:	Reed Baron	Phone:	602-692-3572		Stop time:			
UPDES Permit #:	WARRING WALL TO ANALYSIS AND AND ANALYSIS ANALYSIS AND ANALYSIS AND ANALYSIS AND ANALYSIS AND ANALYSIS AND AN							
Date of last rain event:	9/1/2012	Duration:	Approx. Rainfall (in):	onoming of	0.41"			
Inspected By (Print):	Rochelle Pfeas	24 600 27 20	etion or County:	Wohen	2			
	100000000000000000000000000000000000000			Weber				
Reason for Inspection: Inspection SW sam		plaint/Tip Random Rece	iving Waters:	Weber	River			
Code (circle): SW non-sa	Inspector Code (circl	e): (L) Local Type Co	de (circle): 1 - Municip		3 - State			
SW	PPP, EROSION, SEDI	MENT AND HOUSEKEEP	NG BMP's INFORMAT	TION	8	YES	NO	N/A
1. Is the SWPPP on site and	accessible, or is the SWPPP lo	ocation posted in an obvious place a	nd reasonably accessible (in a	short time)?		х		
		eping BMP's installed on the site as					X	
		conditions (modifications dated & init		on site map, discor	ntinued		x	
BMPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log, etc.)? 4. Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector								
name &qualifications, weather, problems/repairs, corrective action, new BMPs, removed BMPs, discharges, etc.)							X	
5. Have all corrective action items from previous inspections been addressed and documented within the time frame allotted by the inspector?							X	
Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence, upgradient boundary diversion, down gradient boundary sediment control, etc.)								х
7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?							х	
8. Is there evidence of vehicles tracking soil off the construction site?						X		
9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a						x		
storm drain or water body? 10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface						^	-	
roughening, pipe slope drain, dust control, etc)?							Х	
11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, waddles, straw bails, curb cut-back, etc?						x		
		sekeeping controls (clean track out p	ad, sweeping, construction m	aterials manageme	ent.		-	
litter/trash control, port-o-pott	ties staked down, fueling areas,	concrete wash out area, proper cur	b ramps, spill prevention, etc)?	?		X		
		activities for 14 to 21 days without		rozen ground)?			х	
14. Are there places where B	BMPs are needed and should be	installed or not needed and should	be removed?				х	
There was sort of a SWPPP	on site for me to look at but I di	aral terms) what needs to be completed. to install. Include the date when conduit see the plan itself or any inspec	rections are made. tions, I did see a log of change	es which looks to be	e current. The	was	pecific	BMPs
	*	it. Looks like the silf fence is still in	leed of repair. Please get the s	site perimeter clear	ned up and ma	ake		
necessary repairs for my nex	t inspection.							
Inspector, please list all ap					11-1-12-1		,	,
gathered and evaluated the inform	mation submitted. Based on my inqu ast of my knowledge and belief true,	were prepared under my direction or supe iry of the person or persons who manage accurate, and complete. I am aware that	the system, or those persons dire	ctly responsible for ga	athering the info	rmation	, the	5.50
Inspector:	Rochelle Pfeaster	Project Manager/R	si // Octo	bell	4-	11-1	6	
	(Print Name)	(Title)	1 000	(Signature)	- (-	(1	Date)	
Operator:	Reed Baron	Contact Person	mailed to:	303 N 200 W Bright	ham City		2/201	2
	(Print Name)	(Title)		(Signature)		(1	Date)	



PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Jared Andersen, P.E. County Engineer

September 12, 2012

An inspection of the project site was done on September 5, 2012, the following pictures is what I saw.



Tracking on the county road



Dirt in the gutter



PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Jared Andersen, P.E. County Engineer




Silt Fence in need of repair





PUBLIC WORKS /ENGINEERING (801) 399-8374 FAX: (801) 399-8862 Jared Andersen, P.E. County Engineer



Log of changes, no SWPPP

