


THERE IS A CLOSURE ERROR ON THE INTERIOR ROADS C62 COMING FROM BOTH THE SOUTH & THE NORTH I CANNOT FINISH MY INTERIOR DWS AND CHECKS UNTIL A SOLUTION IS FOUND FOR THE DWS

THESE ACCORDING TO THE RECORDS AND SHOULD HAVE BEEN PART OF THE SURVEY TO BE ADJUSTED TO THE HIGH ELEVATION

SET #5x24" REBAR & CAP W/ DSW

- = SET R.O.W. MONUMENT
- = SET CL MONUMENT
- = LIMITED COMMON AREA
- = ROAD DEDICATION
- = PRIVATE OWNERSHIP
- = EXISTING PAVEMENT (COMMON AREA)
- = COMMON AREA



**EDGEWATER BEACH
RESORT PHASE 1 -1ST AMENDMENT**

A PLANNED RESIDENTIAL UNIT DEVELOPMENT (P.R.U.D.)
PART OF THE SOUTHWEST QUARTER OF SECTION
13, TOWNSHIP 6 NORTH, RANGE 1 EAST, SALT
LAKE BASE AND MERIDIAN, U.S. SURVEY
WEBER COUNTY, UTAH
AUGUST, 2012



Project Info.

Surveyor:
R. KUNZ
Designer:
N. ANDERSON
Begin Date:
07-11-12
Name:
EDGEWATER BEACH
RSRT. PH 1 AMD. PRUD
Number:
5917-15
Revision:
1"=20'
Checked:

Weber County Recorder

Entry No. _____ Fee Paid _____
And Recorded, Filed For Record _____
At _____ In Book _____
Of The Official Records, Page _____
Recorded For: _____
Weber County Recorder
Deputy:

ADJORNERS NAME AND ENTRY # OF DOCUMENT CONVEYING THIS STRIP SEE NOTE 3 PRIOR REVIEW

DATA L. LIND KLOTZ HOW WAS I EXPANDED? SEE NOTE FROM 12 REVIEW