

SWPPP COMPLIANCE INSPECTION FORM



Project Name: Sheep Creek	10+ 63 Address: 4022 & 4500 N, Eden Date: 1	0/2	31
Owner:	Contractor (Gen/Sub): Brandon & Nate Start time:	2:3	0
Site Contact: Brandon Bailey	12151er Phone 3-5/20/721-7355 Stop time:		10
JPDES Permit #: UTBBU4191 Expira			
Date of last rain event:	Duration: Approx. Rainfall (in):		
nspected By (Print):	Local Jurisdiction or County: Weber County		
Reason for Inspection: Scheduled (Complaint/Tip Random Receiving Waters:		
nspection SW sampling Inspector Code /	circle): (S) State Type Code (circle): (1 Municipal 2 Industrial 2 Sec	te	
	EDIMENT AND HOUSEKEEPING BMP's INFORMATION	F . I.	NO
	PP location posted in an obvious place and reasonably accessible (in a short time)?	153	NO
. Are erosion control, sediment control, and good hous	ekeeping BMP's installed on the site as shown in the SWPPP?	1-1	
. Has the SWPPP been updated to reflect the current s MPs crossed off site map, new BMP details & spec's in	site conditions (modifications dated & initialed on site map, new BMPs on site map, discontinued		
. Are on-site inspections being performed and recorded	by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector	-	\dashv
ame &qualifications, weather, problems/repairs, correc	tive action, new BMPs, removed BMPs, discharges, etc.)		
 Have all corrective action items from previous inspects. Are SW flows entering and leaving the construction significant. 	ions been addressed and documented within the time frame allotted by the inspector? te controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence,		\rightarrow
pgradient boundary diversion, down gradient boundary	sediment control, etc.)		X
	flows or soil deposits from the construction site in downstream locations?		X
. Is there evidence of vehicles tracking soil off the cons			X
. Is there soil, construction material, landscaping items torm drain or water body?	, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a		8
0. Is there a need to repair, maintain, or improve erosio	n control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface	1	(-
oughening, pipe slope drain, dust control, etc)? 1. Is there a need to repair, maintain, or improve sedim.	ent control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, wattles,	-	\triangle
traw bails, curb cut-back, etc?			٤l
2. Is there a need to repair, maintain, or improve good h	nousekeeping controls (clean track out pad, sweeping, construction materials management, eas, concrete wash out area, proper curb ramps, spill prevention, etc)?		,
 Are there disturbed areas that have not had construct 	tion activities for 14 to 21 days without stabilization? (except snow or frozen ground)?	-+	X
4. Are there places where BMPs are needed and should			5
COMMENT	S AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE	/	
KUPDES Permit ha	as Expired		
Peregitate site to 70	%	-	
·			
pector, please list all applicable SEV codes:	were prepared under my direction or supervision in accordance with a system designed to assure that qualified per		
ered and evaluated the information submitted. Based on my inq mation submitted is, to the best of my knowledge and belief true	uiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, accurate, and complete. I am aware that there are significant penalties for submitting false information, including to	mation th	
e and imprisonment for knowing violations.			
pector: CALH HARVET	PST / MILLE IA	/20/	1
(Print Name)	(Title) (Signature)	(Da	(5) te)
	1		
rator: Note Mueller	Emailed to: mountain primehomes &	yan	101