



Larry Slagkowski  
Weber County Surveyor  
2380 Washington Blvd. #240  
Ogden, UT 84401

RE: Summit Eden Phase 1B  
Response to Surveyor's Comments

Mr. Slagkowski,

The following are comments and responses pertaining to the Summit Eden Phase 1B Plat from your review received on December 27, 2013.

**Sheet 1:**

1. Update Location of Subdivision.  
*Response: Updated Location of Subdivision to S 1/2 of Section 5, SE 1/4 of Section 5 and N 1/2 of Section 8.*
2. Still a problem with the cul-de-sac and future extension of heartwood Drive.  
*Response: Updated annotation, C50 was incorrect*
3. Date and Agency for each found monument.  
*Response: Updated Monument descriptions with date and condition, all sheet all phases.*
4. Show Slope Easements.  
*Response: Slope Easements will not be shown on Subdivision Plats.*
5. Show acreage for each County, both road and private lots.  
*Response: Updated Acreage and square feet, in table and labels.*

**Sheet 2:**


1. L54 not in line table.  
*Response: Added L 54 to Table.*
6. Dimension Boundary adjacent to Lot 31.  
*Response: Annotation corrected.*
7. Still several problem with Heartwood Drive.  
*Response: All annotation checked and corrected along cul-de-sac and Heartwood Drive.*

OFFICES NATIONWIDE

5217 SOUTH STATE STREET, STE 300 | MURRAY, UT 84107 | WWW.NV5.COM | OFFICE 801.743.1300 | FAX 801.743.0300

CONSTRUCTION QUALITY ASSURANCE - INFRASTRUCTURE ENGINEERING - MUNICIPAL OUTSOURCING - ASSET MANAGEMENT - ENVIRONMENTAL SERVICES

Best Regards,

A handwritten signature in black ink, appearing to read "Richard W. Miller". The signature is fluid and cursive, with a large initial "R" and "M".

Richard Miller, PLS  
Survey Manager

NIVIS

OFFICES NATIONWIDE