

modified 8/12/10

SWPPP COMPLIANCE INSPECTION FORM



Project Name: LOT 34 Chmson Ridge Address: 5023 E Whispering Pines Date: 7	120	/10	5
Owner: Kurt Bovero Contractor (Gen/Sub): Land to Sky Construction Start time:	9:	30)
Site Contact: Luft Bovero Phone: (80) 497-1746 Stop time:	9:	40	>
UPDES Permit #: UT 12367111 Expiration: 4 21 / 15 Weather: Sunny Cloudy Raining Snowing Other:			
Date of last rain event: Duration: Approx. Rainfall (in):	NAME OF THE OWNER.		
Inspected By (Print): Kelci Carsen Local Jurisdiction or County: Weber County			
Reason for Inspection: Scheduled Complaint/Tip Random Receiving Waters:			
Inspection SW sampling Code (circle): SW non-sampling Inspector Code (circle): (S) State Type Code (circle): 1 - Municipal 2 - Industrial 3 - State			
SWPPP, EROSION, SEDIMENT AND HOUSEKEEPING BMP'S INFORMATION	YES	NO	N/A
1. Is the SWPPP on site and accessible, or is the SWPPP location posted in an obvious place and reasonably accessible (in a short time)?		V	1,1175
2. Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP?		^	V
3. Has the SWPPP been updated to reflect the current site conditions (modifications dated & initialed on site map, new BMPs on site map, discontinued BMPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log, etc.)?			1
4. Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector			X
name &qualifications, weather, problems/repairs, corrective action, new BMPs, removed BMPs, discharges, etc.) 5. Have all corrective action items from previous inspections been addressed and documented within the time frame allotted by the inspector?			X
6. Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence,	X		
upgradient boundary diversion, down gradient boundary sediment control, etc.)	X		
7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?		X	
8. Is there evidence of vehicles tracking soil off the construction site?9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a		X	
storm drain or water body?		X	
10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface roughening, pipe slope drain, dust control, etc)?		V	
11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, wattles,		\triangle	
straw bails, curb cut-back, etc?		X	
12. Is there a need to repair, maintain, or improve good housekeeping controls (clean track out pad, sweeping, construction materials management, litter/trash control, port-o-potties staked down, fueling areas, concrete wash out area, proper curb ramps, spill prevention, etc)?		V	
13. Are there disturbed areas that have not had construction activities for 14 to 21 days without stabilization? (except snow or frozen ground)?		$\langle \cdot $	\neg
14. Are there places where BMPs are needed and should be installed or not needed and should be removed?		X	\neg
COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE			
Identify the problem and its location. If appropriate, describe (in general terms) what needs to be completed. However, only if qualified (e.g., you are a designer) should you be mar to install. Include the date when corrections are made.	dating s	oecific i	ВМРѕ
NIA CINDOD AN CITO			-
THE STATE OF STATE			\dashv
MILL LIDDEC DOMALL LANG LOVDING			\dashv
That tornes terrible has expired			_
700/ 010-1 100-100 00 -11-0 0110 10 10010-1-1-1-0-1-0			
10% and more of the Site is reveal tated please			
tile for an NOI with the State?			
	-		
			7
			\neg
			\neg
spector, please list all applicable SEV codes:			\dashv
ertify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified pe thered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the infor	rsonnel	properl	y
ormation submitted is, to the best of my knowledge and belief true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including	mation, I the poss	the ibility	
fine and imprisonment for knowing violations.	- 11 Viscili (1870)	esed#E	
energy Kola Lakapia PCI Kinka ala Anii	-1	7.	
(Print Name) (Title) (Signature)	<u> </u>	20	Ц
	(0)	ate)	\dashv
perator: Kurt Bovero Emailed to: landto Sky construction @ ama	lik	CAV	ml
odified 8/12/10 (Print Name) (Title) (Signature)	(D:	ate)	44