

## SWPPP COMPLIANCE INSPECTION FORM



Project Name: Clay C	Address: 1452	S Sweetwater Rd	Date: 9/14	1/15	
Owner: Look Homes	Contractor (Gen/Sub):		Start time: 10	:30	
Site Contact: Matt Cook	Phone: 435-	764-4779		:40	
UPDES Permit #: YTF371Z33	Expiration: 5/22/16 Weather: Sunny		ner:		
Date of last rain event:	Duration:	Approx. Rainfall (in):			
Inspected By (Print):	Local Jurisdiction o	or County: Weber County			
Reason for Inspection: Scheduled		Waters: Snith Creek			-
Inspection SW sampling Inspector C	(S) State		and the second second		
Code (circle). SW non-sampling	(L) Local		3 - State		
SWPPP, EROSIO	N, SEDIMENT AND HOUSEKEEPING BA	MP's INFORMATION	YE	s No	N/A
1. Is the SWPPP on site and accessible, or is the S	SWPPP location posted in an obvious place and rea	asonably accessible (in a short time)?		X	
Are erosion control, sediment control, and good     Has the SWPPP been undated to reflect the our	housekeeping BMP's installed on the site as shown rent site conditions (modifications dated & initialed o	in the SWPPP?			K
BMPs crossed off site map, new BMP details & spe	ec's in SWPPP, SWPPP amendment I og etc \2		West and the second		X
<ol><li>Are on-site inspections being performed and rec</li></ol>	orded by a qualified person on a weekly or hiweekly	basis, reporting items required by permit? (	Inspector	+	
5. Have all corrective action items from previous in	orrective action, new BMPs, removed BMPs, discha spections been addressed and documented within the	arges, etc.)			X
Are SW flows entering and leaving the construct	ion site controlled, managed, or diverted around the	ne time frame allotted by the inspector?	000	K	
upgradient boundary diversion, down gradient bour	ndary sediment control, etc.)		x X		
7. Is there evidence of sediment discharge such as	mud flows or soil deposits from the construction site	e in downstream locations?		X	
8. Is there evidence of vehicles tracking soil off the	construction site?			X	
storm drain or water body?	items, or other debris piled on impervious surfaces (			X	
10. Is there a need to repair, maintain, or improve e	erosion control BMPs (temporary stabilization, erosio	on blankets, mulch, vegetated strips, rip rap,	surface	-	
roughening, pipe slope drain, dust control, etc)?	ediment control BMPs (silt fence, check dams, fiber			X	
straw balls, curb cut-back, etc?				16	
12. Is there a need to repair, maintain, or improve g	ood housekeeping controls (clean track out pad, sw	eeping, construction materials managemen	t,	-	
13. Are there disturbed areas that have not had con	ng areas, concrete wash out area, proper curb ramps struction activities for 14 to 21 days without stabiliza	s, spill prevention, etc)?		X	
14. Are there places where BMPs are needed and s	should be installed or not needed and should be rem	noved?		X	
	ENTS AND CORRECTIVE ACTIONS FOR				-
Supply reeds to be o	N site. See item #1				
					$\neg$
					$\neg$
					-
					$\dashv$
pector, please list all applicable SEV codes:					_
iei eu and evaluated the information submitted. Dased on n	ments were prepared under my direction or supervision in a ny inquiry of the person or persons who manage the systen of true, accurate, and complete. I am aware that there are s	m or those persons directly responsible for mathemi	M- 1 6		у
pector: ZACH FARVEY (Print Name)	PSI (Title)		9/14/15	_	
1 1 2	(Tite)	(Signature)	(1	Date)	
erator: Natt Cook ified 8/12/10 (Print Name)	enailed to:	cook. homes @ hota	mil-com	1	
	()	(Signature)	(1	Date)	1