

SWPPP COMPLIANCE INSPECTION FORM



Retreat

Project Name: Tanno		Add	ress: 3/03 E	Piveries	JCT Eden	Date: 4/	1	16	
Owner: Paul Bern	an	Contractor (Gen/S			3.524	Start time:	io	:45	
Site Contact:		Ph	one: 435-91	01/213	6	Stop time:	10.	50	,
UPDES Permit #: UTP37	3517 Expiration	1: 1/11/17 V	Veather: Sunny	Cloudy Ra	ining Snowing Ot	ther:			
Date of last rain event:		Duration:		Approx. Rainfall	(in):				
Inspected By (Print):			Local Jurisdiction or C	ounty: We	ber Court	1			
Reason for Inspection:	Scheduled Com	nplaint/Tip Randor			/				
Inspection SW sampling		(S) State			2				
Code (circle): SW non-samp	ling Inspector Code (circ	(L) Local	Type Code (circle)): 1- Mi	unićipať 2 - Industria	ıl 3 - Stat	te		
	PPP, EROSION, SED						YES	NO	N/A
1. Is the SWPPP on site and ac					e (in a short time)?		K		
2. Are erosion control, sediment	control, and good houseke	eping BMP's installed or	the site as shown in	the SWPPP?			K		
Has the SWPPP been update BMPs crossed off site map, new	BMP details & spec's in SV	conditions (modification WPPP, SWPPP amendi	s dated & initialed on s ment Log. etc.)?	site map, new B	MPs on site map, discon	tinued	X		
4. Are on-site inspections being	performed and recorded by	a qualified person on a	weekly or biweekly ba	sis, reporting ite	ems required by permit?	(Inspector			
name &qualifications, weather, p 5. Have all corrective action item	s from previous inspections	action, new BMPs, rem	oved BMPs, discharge	es, etc.)			X		
6. Are SW flows entering and lea	iving the construction site c	ontrolled, managed, or	diverted around the sit	e2 (e.g. perime	ted by the inspector?	9000	×		
upgradient boundary diversion, o	own gradient boundary sed	liment control, etc.)				erice,	K		
7. Is there evidence of sediment			the construction site in	downstream lo	cations?			X	
3. Is there evidence of vehicles to								4	
d. Is there soil, construction mat storm drain or water body?								4	
10. Is there a need to repair, mai	ntain, or improve erosion co	ontrol BMPs (temporary	stabilization, erosion b	lankets, mulch,	vegetated strips, rip rap	, surface		(
oughening, pipe slope drain, dus I1. Is there a need to repair, mai		control BMPs (silt fence	check dame fiber rol	ls sadiment to	n/hasia inlat acatastics			X	
traw bails, curb cut-back, etc?						1		X	
2. Is there a need to repair, main	itain, or improve good hous	sekeeping controls (clea	n track out pad, sweep	ping, construction	on materials managemen	nt,		4	
tter/trash control, port-o-potties s 3. Are there disturbed areas tha	have not had construction	activities for 14 to 21 da	, proper curb ramps, s	pill prevention,	etc)?			6	_
4. Are there places where BMPs					v or mozem ground):			4	
Pinkulan kanadan berahan berah		ND CORRECTIVE	-	-	DITANICE				
									\dashv
pector, please list all applicab	le SEV codes:								\dashv
tify under penalty of law that this doct erad and evaluated the information su mation submitted is, to the best of my le and imprisonment for knowing viola	iment and all attachments were ibmitted. Based on my inquiry o knowledge and belief true, acc	of the person or persons wi	o manage the system of	r those persons d	ractly resmonsible for nathe	ring the inform			
pector: Zac	- HARVEY nt Name)	PS.	tle)	4	(Signature)	>4/	5/	16 Ite)	
	-1. 1 1	101	1				(50	/	\dashv