

Operator:



SWPPP COMPLIANCE INSPECTION FORM Reynolds Home 3123 E

Alaret Link Menty		[17					
Start time:	4	:25					
Site Contact: 3hane Strong 435-265-8811 Phone: 435-774-0314 Stop time:	4:	30					
UPDES Permit #: UT HR 81247 Expiration: 6/21/18 Weather: Sunny Cloudy Raining Snowing Other:							
Date of last rain event: Duration: Approx. Rainfall (in):							
Inspected By (Print): Local Jurisdiction or County:							
Reason for Inspection: Scheduled Complaint/Tip Random Receiving Waters:							
Inspection SW sampling Code (circle): SW non-sampling Inspector Code (circle): (S) State (L) Local Type Code (circle): 1 - Municipal 2 - Industrial 3 - State	te						
SWPPP, EROSION, SEDIMENT AND HOUSEKEEPING BMP'S INFORMATION	YES	NO N	N/A				
1. Is the SWPPP on site and accessible, or is the SWPPP location posted in an obvious place and reasonably accessible (in a short time)?		A1073043 1113	1				
2. Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP?							
. Has the SWPPP been updated to reflect the current site conditions (modifications dated & initialed on site map, new BMPs on site map, discontinued MPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log, etc.)?							
Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector							
ame &qualifications, weather, problems/repairs, corrective action, new BMPs, removed BMPs, discharges, etc.)							
5. Have all corrective action items from previous inspections been addressed and documented within the time frame allotted by the inspector? 6. Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence,			_				
upgradient boundary diversion, down gradient boundary sediment control, etc.)							
7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?			_				
8. Is there evidence of vehicles tracking soil off the construction site?							
9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a storm drain or water body?							
10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface							
roughening, pipe slope drain, dust control, etc)? 11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, wattles,							
straw bails, curb cut-back, etc?							
12. Is there a need to repair, maintain, or improve good housekeeping controls (clean track out pad, sweeping, construction materials management,		_	-				
itter/trash control, port-o-potties staked down, fueling areas, concrete wash out area, proper curb ramps, spill prevention, etc)? 13. Are there disturbed areas that have not had construction activities for 14 to 21 days without stabilization? (except snow or frozen ground)?							
14. Are there places where BMPs are needed and should be installed or not needed and should be removed?							
COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE dentify the problem and its location. If appropriate, describe (in general terms) what needs to be completed. However, only if qualified (e.g., you are a designer) should you be man	ndaling s	necific Blu	ID.				
to install. Include the date when corrections are made.	daming of	JOUING DIVI	<i>r</i> 3				
House site excavated materials stockpiled							
around site		-					
No SWAPP posted							
Porta-John on site unstaked.			\neg				
Telenhome No 435-224 1214							
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			\dashv				
Call along & Wain H			\dashv				
Call placed to Visionary Homes			4				
person awsered and transfer to a recov	ding		4				
Message Left with statement of no SWP	م م						
Jana 10/42 hove number of 801-399-8054							
Bhane Strong			1				
H35-265-8871			٦				
#ternsento. / will /			٦				
2 112			1				
0 8/2/19			\dashv				
spector, please list all applicable SEV codes:			\dashv				
ertify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personal and available to information submitted. Because my legacy of the accordance with a system designed to assure that qualified personal and available to the control of the accordance with a system designed to assure that qualified personal and available to the control of the accordance with a system designed to assure that qualified personal and available to the control of th	rsonnel	properly	\forall				
hered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons drectly responsible for gathering the information submitted is, to the best of my knowledge and belief true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including	mation,	the ibility					
ine and imprisonment for knowing violations.	10 2033	omy					
pector: E. Fransen Sr. Eng Kustle							

(Title)



ADDITIONAL COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE WEBER COUNTY re



-		Commence of the Commence of th		
Site Name:	Reynold	Home	Date of Evaluation:	Page of
Site Address:	7	, , , , ,		
One Address.				
6	alled and	d Spole to S	Shane	
	ho	indicated to	1.1.	+ bad book
	21111	marca. La m	car a pa	THE THE
	parier.			
	L a	sked for the	semit n	umber he needed to
	looke it	and I a	world for	umber he needed to him to cap it in.
3	41 1-	1.)). / /	+1 6	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	ye indica	eted He nad	8 he 00%	x and would have
~5	uch POST	ed tommerro	J.	

7.	Sullar	H. Parad	it and	Inff mixer. T
7	1 11	Hally 19 / OWN 4	1 una	12 1 1 7 7
ria	a the p	er mi + no.	andw	ould chick the 5110
70	mosors	w p. M.		ould chick The site
		7 /) 1		
	(1) 11.11.	^	
		- Jupa		
		8/3,	12017	
		//	O 3-894- 0. CM2	

			30-113-00	
	· · · · · · · · · · · · · · · · · · ·			
		FDA F	> (FILO	D
ODB11 T	Discharge withou		-3 SEV Codes and	
OOR11	Discharge withou	The state of the s	BR19B	Failure to properly operate and maintain BMP's
OOR18		or a Notice of Termination	BR19A	Failure to properly install/implement BMP's
3OR12	Failure to conduc		EOR16	Failure to submit required report (non-DMR)
BOC17		p any or adequate SWPPP/SWMP	AOR22	Narrative effluent violation
BOC18		nent SWPPP/SWMP	DOR12	Failure to submit required permit information
3OR41	Failure to mainta	The same of the sa	AOR12	Numeric effluent violation
COR11	Failure to monito	ſ	BOR42	Violation of a milestone in an order