

SWPPP COMPLIANCE INSPECTION FORM



Project Name:	В	ryne	Addres	S:	2608 East 6500 So	utn	Date:	4/4/201	3
Owner:	Scott	Sessions	Contractor (Gen/Sub)	:	Scott Sessions Ceder	Cove	Start time:	12:22 P	M
Site Contact:	\$	Scott Sessions	Phon	e:	801-725-0002		Stop time:	12:30 P	М
UPDES Permit #:	UTR36	S1611 Expiration:	4/15/2013 Wea	ather: Sunny	Cloudy Raining	Snowing Oth	er: 61°		
Date of last rain eve	ent:	4/1/2013	Duration:		Approx. Rainfall (in):		.59"		
Inspected By (Print	199	elci Huffaker/Rochelle F	331	cal Jurisdiction or		Weber C			
Reason for Inspecti				Receiving V		Weber I			
Inspection	SW sampling	died Comple	(S) State	Receiving v	alers.	Weberi	Kivei		
	W non-sampling	Inspector Code (circle):	(L) Local	Type Code (circ			3 - State		
	Harrison and the second second	ROSION, SEDIM					YES	NO	N/A
		e, or is the SWPPP loca				a short time)?	X	-	
 Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP? Has the SWPPP been updated to reflect the current site conditions (modifications dated & initialed on site map, new BMPs on site map, discontinued 								-	
BMPs crossed off s	ite map, new BMP	details & spec's in SWP	PP, SWPPP amendme	ent Log, etc.)?	AN ANTONIO AND AN ANTONIO AND		(Inspector		
		ns/repairs, corrective ac			-American Company		X		
N. Karanta Markey Production and Control	CANADA SECURIO PER	previous inspections b		CALL CONTRACTOR STATE C		The production of the product of the	estable 1	-	Х
		he construction site con radient boundary sedim		erted around the	site? (e.g. perimeter	controls, berms, slit fe	ence,		х
		arge such as mud flows		e construction site	in downstream locati	ons?		x	
8. Is there evidence of vehicles tracking soil off the construction site?								х	
		andscaping items, or ot	her debris piled on impe	ervious surfaces (roads, drives) that cou	old be washed with SV	V to a	x	
storm drain or water body? 10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface								x	
roughening, pipe slope drain, dust control, etc)? 11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, waddles,									
straw bails, curb cu						32		Х	
		or improve good housel d down, fueling areas, co					nt,	x	
		not had construction a				frozen ground)?		х	
14. Are there places	s where BMPs are r	needed and should be in	nstalled or not needed a	ind should be ren	ioved?			Х	
Move Porta-John ba	ack and ancor dowr	1							
								_	
Inspector, please	THE PARTY OF THE P		l						
gathered and evaluate	d the information subnis, to the best of my kn	ent and all attachments wer nitted. Based on my inquiry nowledge and belief true, ac ns.	of the person or persons v	vho manage the sys	stem, or those persons dir	rectly responsible for gat	hering the informati	on, the	
					11/	1. 4.00	1)		
Inspector:		Rochelle Pfeaster Name)	r	Title)	Kel	a Hulla	fer	4/9/201 (Date)	
	(Fint	ramoj		i ide)		(Signature) v		(Date)	_
Operator:		Sessions Name)		ntractor	Emailed	to: mel1945@gma	il.com	4/9/201	_
modified 8/12/10	(Print	Name)	(Title)		(Signature)		(Date)	