

## SWPPP COMPLIANCE INSPECTION FORM



					-			
Project Name:	The Summit at Ski Lake - Phase 9 and 1	1 Address:	6750 E Via Cortina, Hunstville, UT 84310	Date:	6	/25/20	13	
Owner:	Ray Bowden Contractor (Gen/Sub): Conrock Recycling Inc. Start tin		Start time:	9:00 AM		м		
Site Contact:	Contact: Ryan Bowden Phone: 801-731-4725 Stop time					9:40 AM		
UPDES Permit #	: UTR358707 Expiration:	6/30/2013 Weather:	Sunny Cloudy Raining Snow	25.000				
Date of last rain	event:	Duration:	Approx. Rainfall (in):					
Inspected By (Pri	int): Michael Tuttle		risdiction or County:	Wahar Causty			_	
No. 10 - Van III	NAME OF THE PARTY			Weber County				
Reason for Inspe Inspection	SW sampling	olaint/Tip Random (S) State	Receiving Waters: P	ineview Reservoir				
E 100 EE 250	SW non-sampling Inspector Code (circle	e): (L) Local Typ	e Code (circle): 1 - Municipal 2	- Industrial 3 - Sta	ate			
	A MARIE THE PROPERTY OF THE PARTY OF THE PAR		PING BMP's INFORMATION		YES	NO	N/A	
1. Is the SWPPP				1612	X	NO		
Is the SWPPP on site and accessible, or is the SWPPP location posted in an obvious place and reasonably accessible (in a short time)?     Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP?						-		
3. Has the SWPF	P been updated to reflect the current site of	conditions (modifications dated	& initialed on site map, new BMPs on site may	ap, discontinued	x			
BMPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log, etc.)?  4. Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit?								
(Inspector name	&qualifications, weather, problems/repairs,	corrective action, new BMPs.	removed BMPs, discharges, etc.)	y permit?	х			
<ol><li>Have all correct</li></ol>	ctive action items from previous inspections	been addressed and docume	nted within the time frame allotted by the insp		х			
6. Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence.								
upgradient boundary diversion, down gradient boundary sediment control, etc.)  7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?								
	ce of vehicles tracking soil off the construct		istruction site in downstream locations?			Х		
9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a						Х		
storm drain or wa	ater body?					х		
<ol> <li>Is there a nee roughening pipe</li> </ol>	ed to repair, maintain, or improve erosion co slope drain, dust control, etc)?	ontrol BMPs (temporary stabiliz	ation, erosion blankets, mulch, vegetated stri	ps, rip rap, surface		х		
		control BMPs (silt fence, check	dams, fiber rolls, sediment trap/basin, inlet	protection, waddles,	x			
straw bails, curb cut-back, etc?								
12. Is there a need to repair, maintain, or improve good housekeeping controls (clean track out pad, sweeping, construction materials management, litter/trash control, port-o-potties staked down, fueling areas, concrete wash out area, proper curb ramps, spill prevention, etc)?						х		
13. Are there disturbed areas that have not had construction activities for 14 to 21 days without stabilization? (except snow or frozen ground)?						х		
14. Are there places where BMPs are needed and should be installed or not needed and should be removed?						x		
	COMMENTS A	ND CORRECTIVE ACTI	ONS FOR SWPPP COMPLIANCE					
Identify the proble	em and its location. If appropriate, describe (in ge	eneral terms) what needs to be con-	apleted. However, only if qualified (e.g., you are a d	lesigner) should you be	manda	ting spe	cific	
		BMPs to install. Include the date v	when corrections are made.					
The SWPPP is or	n site, but I didn't look at it because there w	as a wasp nest growing in the	box. Please remove wasp nest.					
It appears that the	e check dams are more than 50% full, and	need to be cleaned out.						
	e list all applicable SEV codes:							
cerury under penalt gathered and evalua	y of law that this document and all attachments w led the information submitted. Based on my inqu	vere prepared under my direction o iry of the person or persons who m	r supervision in accordance with a system designed anage the system, or those persons directly respon	I to assure that qualified	d persor	nnel pro	perly	
nformation submitte	ed is, to the best of my knowledge and belief true,	accurate, and complete. I am awai	re that there are significant penalties for submitting	false information, includ	ding the	possibil	lity	
л.нн <del>е</del> апо imprisoni	ment for knowing violations.		11 0					
	Make at Tour		-//m /2	-	l <sub>point</sub> o			
nspector:	Michael Tuttle (Print Name)	Enginee (Title)		lta)		25/201	3	
		(Title)	(Signatu	ne)		(Date)		
Operator:	e-mailed to conrockrecycling@gmail.com							
nodified 8/12/10	(Print Name)	(Title)	(Signatu	ire)		(Date)	_	