

## SWPPP COMPLIANCE INSPECTION FORM



2202 / 2	_ 7		
Project Name: No 274 UPOW HOLDENGS Address: 2797 US 89 Platsmy Date: 8/	11111		
Owner: VALL MACKUES Contractor (Gen/Sub): CHRZS THERELECTO CONSTRUCTION Start time:	Щi	40	
Site Contact: TARTO THURGOIS Phone: SUI-497-6813 Stop time:			
UPDES Permit #: CCTIZ 365335 Expiration: 10/03/14 Weather: 8unny Cloudy Raining Snowing Other:			
Date of last rain event: Duration: Approx. Rainfall (in):			
Inspected By (Print): CHAND MEYERHUTPER Local Jurisdiction or County: WEBED CAUNTY			
Reason for Inspection: Scheduled Complaint/Tip Random Receiving Waters: Vocate Data Haran Canal	. Le	PIPPE	7
Inspection SW sampling Code (circle): SW non-sampling Inspector Code (circle): (S) State Type Code (circle): 1 - Municipal 2 - Industrial 3 - State	ie		
SWPPP, EROSION, SEDIMENT AND HOUSEKEEPING BMP's INFORMATION	YES	NO	N/A
1. Is the SWPPP on site and accessible, or is the SWPPP location posted in an obvious place and reasonably accessible (in a short time)?		X	
<ol> <li>Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP?</li> <li>Has the SWPPP been updated to reflect the current site conditions (modifications dated &amp; initialed on site map, new BMPs on site map, discontinued</li> </ol>		X	
BMPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log, etc.)?		X	
4. Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector name &qualifications, weather, problems/repairs, corrective action, new BMPs, removed BMPs, discharges, etc.)		X	
5. Have all corrective action items from previous inspections been addressed and documented within the time frame allotted by the inspector?		V	-
6. Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence.	X		_
upgradient boundary diversion, down gradient boundary sediment control, etc.)  7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?	^		-
8. Is there evidence of vehicles tracking soil off the construction site?		X	-
9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a		X	_
storm drain or water body?  10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface		X	
roughening, pipe slope drain, dust control, etc)?		X	
11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, wattles, straw bails, curb cut-back, etc?		V	
12. Is there a need to repair, maintain, or improve good housekeeping controls (clean track out pad, sweeping, construction, materials management.			-
litter/trash control, port-o-potties staked down, fueling areas, concrete wash out area, proper curb ramps, spill prevention, etc)?		X	
<ul><li>13. Are there disturbed areas that have not had construction activities for 14 to 21 days without stabilization? (except snow or frozen ground)?</li><li>14. Are there places where BMPs are needed and should be installed or not needed and should be removed?</li></ul>		X	<u> </u>
COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE		X	
Identify the problem and its location. If appropriate, describe (in general terms) what needs to be completed. However, only if qualified (e.g., you are a designer) should you be man	ndatina :	specific	BMPs
to install. Include the date when corrections are made.			
Cours Not FEOD SCUPPP OU STRE TO KNOW ZF SOME OF THE ABOVE ARE Y/W			
SPIE IS MOSTLY RE-VEGITATED AND IN GOED SITTING A LOT OF THE CONT	2015		
ARE PERFERENT OK THAT THEY HAVE BEEN PERMUED			
ONE DOT. Paus le Storted BMP'S Wan NEED TO BE IN PLACE POR	Tota	-7	
Wark	350		
THERE IS A PORT-A-BYS THAT APPEARS TO BE LOCATED OFF THIS STIE BE	7 1	914	
BS PART OF THE PROTECT. THE SHOULD BE STAKEN DOWN OF SOME WAY OF KEE	PZWG	7,	r
FROM BEZUG TISPEN OUTR.			
STIE IS PRETTY CLUSTON AT TEME OF INSPECTION			
If THE SUPP WAS ACCESSEDLY I COULD RELIEW ALL THE FORDER TOOM!			
nspector, please list all applicable SEV codes:			
certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified p athered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the info	ersonne	l prope	erly
nformation submitted is, to the best of my knowledge and belief true, accurate, and complete. I am aware that there are significant penaltjes for submitting false information, including	the pos	sibility	- 1
f.fine and imprisonment for knowing violations.			
respector: Citan Mayory (Cef///) 8/31/20	215		
(Print Name) (Fittle) (Signature)	(	Date)	$\dashv$
			$\neg$
Operator:			
odified 8/12/10 (Print Name) (Title) (Signature)	(1	Date)	





