

Project POWDER MOUNTAIN HOUSE

Energy Code: Utah Energy Conservation Code

Location: Elwood, Utah
Construction Type: Single-family
Project Type: New Construction

Orientation: Bldg. faces 0 deg. from North

Conditioned Floor Area: **5,151 ft2** Glazing Area **29%**

Climate Zone: **6 (6833 HDD)**

Permit Date: Permit Number:

Construction Site: 8645 East Copper Crest Eden, UT 84310 Owner/Agent: TOM BUTTGENBACH TOM WISCOMBE ARCHITECT 2404 WILSHIRE BLVD LOS ANGELES, CA 90057 213-647-7238

PLAN REVIEW ACCEPTANCE FOR COMPLIANCE WITH THE APPLICABLE CONSTRUCTION CODES IDENTIFIED BELOW. **X**STRUCTURAL BUILDING MECHANICAL **X** PLUMBING **X** ENERGY **X** ELECTRICAL **ACCESSIBILITY** FIRE PLAN REVIEW ACCEPTANCE OF DOCUMENTS DOES NOT AUTHORIZE CONSTRUCTION TO PROCEED IN VIOLATION OF ANY FEDERAL, STATE, OR LOCAL REGULATIONS. BY: MEM DATE: 02/25/19 WEST COAST CODE CONSULTANTS, INC.

Designer/Contractor:
MARK SHAMIM
SHAMIM ENGINEERING
CONSULTANT INC.
5530 CORBIN AVE.
TARZANA, CA 91356
818-188-6778

MARK@SHAMIMENGINEERING.COM

Compliance: Passes using UA trade-off

Compliance: 3.0% Better Than Code Maximum UA: 1897 Your UA: 1840

The % Better or Worse Than Code Index reflects how close to compliance the house is based on code trade-off rules. It DOES NOT provide an estimate of energy use or cost relative to a minimum-code home.

Envelope Assemblies

Assembly	Gross Area or Perimeter	Cavity R-Value	Cont. R-Value	U-Factor	UA
Ceiling 1: Cathedral Ceiling	2,078	52.0	0.0	0.020	39
Skylight 1: Metal Frame with Thermal Break:Triple Pane with Low-E	135			0.550	74
Ceiling 2: Flat Ceiling or Scissor Truss	397	54.0	0.0	0.025	10
Ceiling 3: Flat Ceiling or Scissor Truss	1,248	54.0	0.0	0.025	31
Wall 1: Wood Frame, 16" o.c. Orientation: Front	955	26.0	9.0	0.033	28
Window 1: Metal Frame with Thermal Break:Triple Pane with Low-E Orientation: Front	40			0.320	13
Door 1: Solid Orientation: Front	30			0.710	21
Door 2: Solid Orientation: Front	23			0.710	16
Wall 2: Wood Frame, 16" o.c. Orientation: Front	745	32.0	9.0	0.031	23
Wall 3: Wood Frame, 16" o.c. Orientation: Right side	970	26.0	9.0	0.033	17
Window 3: Metal Frame with Thermal Break:Triple Pane with Low-E Orientation: Right side	465			0.320	149

Project Title: POWDER MOUNTAIN HOUSE

Data filename: M:\server\1-Project2018\POWDER MOUNTAIN HOUSE\RESCheck file\POWDER MOUNTAIN

HOUSE-R3.rck

Report date: 02/18/19 UNTAIN Page 1 of 9

Assembly	Gross Area or Perimeter	Cavity R-Value	Cont. R-Value	U-Factor	UA
Wall 4: Wood Frame, 16" o.c. Orientation: Right side	475	32.0	9.0	0.031	15
Wall 5: Wood Frame, 16" o.c. Orientation: Back	2,000	26.0	9.0	0.033	23
Window 5: Metal Frame with Thermal Break:Triple Pane with Low-E Orientation: Back	1,290			0.320	413
Wall 6: Wood Frame, 16" o.c. Orientation: Back	300	32.0	9.0	0.031	9
Wall 7: Wood Frame, 16" o.c. Orientation: Left side	340	26.0	9.0	0.033	8
Window 6: Metal Frame with Thermal Break:Triple Pane with Low-E Orientation: Unspecified	100			0.320	32
Wall 8: Wood Frame, 16" o.c. Orientation: Left side	750	32.0	9.0	0.031	23
Basement Wall 1: Solid Concrete or Masonry Orientation: Front Wall height: 12.0' Depth below grade: 12.0' Insulation depth: 12.0'	1,193	1.6	15.0	0.035	42
Basement Wall 2: Solid Concrete or Masonry Orientation: Right side Wall height: 12.0' Depth below grade: 12.0' Insulation depth: 12.0'	750	1.6	15.0	0.035	26
Basement Wall 3: Solid Concrete or Masonry Orientation: Left side Wall height: 12.0' Depth below grade: 12.0' Insulation depth: 12.0'	840	1.6	15.0	0.035	29
Floor 1: Slab-On-Grade:Heated Insulation depth: 1.0'	904		15.0	0.884	799

Mechanical Equipment

Description	Fuel type	Efficiency
Air Source		8.2 HSPF, 14 SEER
Other (Except Gas-Fired Steam)		96 AFUE

Compliance Statement: The proposed building design described here is consistent with the building plans, specifications, and other calculations submitted with the permit application. The proposed building has been designed to meet the Utah Energy Conservation Code requirements in REScheck Version 4.6.5 and to comply with the mandatory requirements listed in the REScheck Inspection Checklist.

Name - Title	Signature	Date



Requirements: 94.0% were addressed directly in the RES*check* software

Text in the "Comments/Assumptions" column is provided by the user in the REScheck Requirements screen. For each requirement, the user certifies that a code requirement will be met and how that is documented, or that an exception is being claimed. Where compliance is itemized in a separate table, a reference to that table is provided.

Section # & Req.ID	Pre-Inspection/Plan Review	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
103.1, 103.2 [PR1] ¹	Construction drawings and documentation demonstrate energy code compliance for the building envelope.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
302.1, 403.6 [PR2] ²	Heating and cooling equipment is sized per ACCA Manual S based on loads calculated per ACCA Manual J or other methods approved by the code official.	Heating: Btu/hr Cooling: Btu/hr	Heating: Btu/hr Cooling: Btu/hr	☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.

Additional Comments/Assumptions:

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Project Title: POWDER MOUNTAIN HOUSE

Report date: 02/18/19

Data filename: M:\server\1-Project2018\POWDER MOUNTAIN HOUSE\RESCheck file\POWDER MOUNTAIN Page 3 of 9

HOUSE-R3.rck

Section # & Req.ID	Foundation Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
402.1.1 [FO1] ¹	Slab edge insulation R-value.	R Unheated Heated	R Unheated Heated	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2, 402.2.9 [FO2] ¹	Slab edge insulation installed per manufacturer's instructions.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
402.1.1 [FO3] ¹	Slab edge insulation depth/length.	ft	ft	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
402.1.1 [FO4] ¹	Conditioned basement wall insulation R-value. Where interior insulation is used, verification may need to occur during Insulation Inspection. Not required in warm-humid locations in Climate Zone 3.	R R	R R	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2 [FO5] ¹	Conditioned basement wall insulation installed per manufacturer's instructions.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
402.2.8 [FO6] ¹	Conditioned basement wall insulation depth of burial or distance from top of wall.	ft	ft	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2.1 [FO11] ²	A protective covering is installed to protect exposed exterior insulation and extends a minimum of 6 in. below grade.			□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.
403.8 [FO12] ²	Snow- and ice-melting system controls installed.			□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.

1	High Impact (Tier 1)	2	Medium Impact (Tier 2)	3	Low Impact (Tier 3)

Page 4 of 9

Section #	Framing / Rough-In Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
& Req.ID 402.1.1, 402.3.4 [FR1] ¹	Door U-factor.	U	U	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
402.1.1, 402.3.1, 402.3.3, 402.3.6, 402.5 [FR2] ¹	Glazing U-factor (area-weighted average).	U	U	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.1.3 [FR4] ¹	U-factors of fenestration products are determined in accordance with the NFRC test procedure or taken from the default table.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
402.1.1, 402.3.3, 402.3.6, 402.5 [FR5] ¹	Skylight U-factor.	U	U	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
402.4.3 [FR20] ¹	Fenestration that is not site built is listed and labeled as meeting AAMA /WDMA/CSA 101/I.S.2/A440 or has infiltration rates per NFRC 400 that do not exceed code limits.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Exception: Site-built window, skylights, and doors.
402.4.4 [FR16] ²	IC-rated recessed lighting fixtures sealed at housing/interior finish and labeled to indicate ≤2.0 cfm leakage at 75 Pa.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
403.2.1 [FR12] ¹	Supply ducts in attics are insulated to ≥R-8. All other ducts in unconditioned spaces or outside the building envelope are insulated to ≥R-6.	R R	R R	□Complies □Does Not □Not Observable □Not Applicable	
403.2.2 [FR13] ¹	All joints and seams of air ducts, air handlers, and filter boxes are sealed.			□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.
403.3 [FR17] ²	HVAC piping conveying fluids above 105 °F or chilled fluids below 55 °F are insulated to ≥R-3.	R	R	□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.
403.3.1 [FR24] ²	Protection of insulation on HVAC piping.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
403.4.2 [FR18] ²	Hot water pipes are insulated to ≥R-3.	R	R	□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
403.5 [FR19] ²	Automatic or gravity dampers are installed on all outdoor air intakes and exhausts.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Section # & Req.ID	Insulation Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
303.1 [IN13] ²	All installed insulation is labeled or the installed R-values provided.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
402.1.1, 402.2.5, 402.2.6 [IN3] ¹	Wall insulation R-value. If this is a mass wall with at least ½ of the wall insulation on the wall exterior, the exterior insulation requirement applies (FR10).	R Wood Mass Steel	R	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2 [IN4] ¹	Wall insulation is installed per manufacturer's instructions.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.

Section # & Req.ID	Final Inspection Provisions	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
402.1.1, 402.2.1, 402.2.2, 402.2.6 [FI1] ¹	Ceiling insulation R-value.	R Wood Steel	R Wood Steel	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.1.1.1, 303.2 [FI2] ¹	Ceiling insulation installed per manufacturer's instructions. Blown insulation marked every 300 ft ² .			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
402.2.3 [FI22] ²	Vented attics with air permeable insulation include baffle adjacent to soffit and eave vents that extends over insulation.			□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.
402.2.4 [FI3] ¹	Attic access hatch and door insulation ≥R-value of the adjacent assembly.	R	R	□Complies □Does Not □Not Observable □Not Applicable	
402.4.2 [FI8] ²	Wood-burning fireplaces have tight fitting flue dampers and outdoor air for combustion.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
403.2.2 [FI4] ¹	Duct tightness test result of <=10 cfm/100 ft2 across the system or <=7.5 cfm/100 ft2 without air handler @ 25 Pa. For rough-in tests, verification may need to occur during Framing Inspection.	cfm/100 ft ²	cfm/100 ft ²	□Complies □Does Not □Not Observable □Not Applicable	Exception: Requirement is not applicable.
403.2.2.1 [FI24] ¹	Air handler leakage designated by manufacturer at <=2% of design air flow.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
403.1.1 [FI9] ²	Programmable thermostats installed on forced air furnaces.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Exception: Requirement is not applicable.
403.1.2 [FI10] ²	Heat pump thermostat installed on heat pumps.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
403.4.1 [FI11] ²	Circulating service hot water systems have automatic or accessible manual controls.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
403.5.1 [FI25] ²	All mechanical ventilation system fans not part of tested and listed HVAC equipment meet efficacy and air flow limits.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.
403.9.1 [FI12] ³	Readily accessible switch on heaters for swimming pools or permanent in-ground spas.			□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.

1 High Impact (Tier	1) 2	Medium Impact (Tier 2)	3	Low Impact (Tier 3)

Section # & Req.ID	Final Inspection Provisions	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
403.9.2 [FI19] ³	Timer switches on heaters and pumps serving pools and permanent spas.			□Complies □Does Not	Requirement will be met.
•	permanent spas.			□Not Observable □Not Applicable	
403.9.3 [FI20] ³	Heated pools and permanent spas have a vapor retardant			□Complies □Does Not	Requirement will be met.
•	cover.			□Not Observable □Not Applicable	
401.3 [FI7] ²	Compliance certificate posted.			□Complies □Does Not	Requirement will be met.
•				□Not Observable □Not Applicable	
303.3 [FI18] ³	Manufacturer manuals for mechanical and water heating			□Complies □Does Not	Requirement will be met.
•	systems have been provided.			□Not Observable □Not Applicable	



Insulation Rating	R-Value	
Above-Grade Wall	35.00	
Below-Grade Wall	16.60	
Floor	15.00	
Ceiling / Roof	52.00	
Ductwork (unconditioned spaces):		

Glass & Door Rating	U-Factor	SHGC
Window	0.32	
Door	0.71	
Skylight	0.55	
Heating & Cooling Equipment	Efficiency	
Air Source	8.2 HSPF,	
Other (Except Gas-Fired Steam)	96 AFUE	
Water Heater:		

Name: _____ Date:

Comments