

September 4, 2023

Name of client: Louis and Matt Meyer

Location of property: 10909 E Highway 39, Huntsville UT. Evaluation # 15498

Date of test(s): September 1-2, 2023

I hereby certify to the best of my knowledge that the percolation tests have been conducted on the above property in accordance with requirements specified in the administrative rule, and that the percolation rates, calculated as specified by said rule, are as follows.

Percolation Test #	Perc. Test	Test Hole	Time Interval Used	Final Stabilized
	Depth	Diameter (in)	for Drop	Percolation Rate
	_			Minutes/Inch
Exploration Pit #1	34"	10	10 Minutes	10.0
Exploration Pit #2	33"	12	10 Minutes	8.0
Exploration Pit #3	24"	10	10 Minutes	8.0
Exploration Pit #4	25"	12	10 Minutes	10.0
Exploration Pit #5	29"	10	10 Minutes	13.33

REEVE & ASSOCIATES, INC.

J. Nate Reeve, PE, PSE Principal / President nreeve@reeve-assoc.com

Solutions You Can Build On™

Civil Engineering • Land Planning • Structural Engineering • Landscape Architecture • Land Surveying • Construction Surveying 5160 South 1500 West • Riverdale, Utah 84405 • Tel: 801-621-3100 • Fax: 801-621-2666 nreeve@reeve-assoc.com