

PERC TABLE		
HOLE #	DEPTH, in.	SOILS EVALUATION WEBER COUNTY HEALTH DEPT. #15456
1	0-21"	Sandy Loam, Granular Structure
	21-40"	Sandy Loam, Blocky Structure
		Groundwater Encountered at 40"
2	0-27"	Sandy Loam, Granular Structure
	27-50"	Sandy Loam, Blocky Structure
3	0-23"	Sandy Loam, Granular Structure
	23-46"	Sandy Loam, Blocky Structure