



Shupe Environmental Solutions Inc

Mailing Address

P. O. Box 199, Huntsville, Utah 84317

Carl R Shupe
801-814-3036
cshupe001@gmail.com

DOPL Licensed Environmental Health Scientist
DWQ Certified Onsite Wastewater Level 3
DOPL Licensed Contractor

5630685-2001
00464-OSP-3
12011279-5501

O&M CONVENTIONAL TRENCH INSPECTION REPORT

System Information

2022 Jan 01

Site Address: 4673 W 2200 South St Taylor

Owner: Fowers, Kristen

System Evaluation

Site Assessment and Observations

- Evaluate presence of odor within 10 ft of perimeter of system: None
 Mild Strong Sour Chemical Location:
- Was any surfacing, ponding, or breakouts noted? Yes No
- Was any construction, utility work, or changes in drainage patterns noted? Yes No
- Were any components damaged, missing, or modified? Yes No
- Were any lids or riser covers not present or not secure? Yes No
- Was evidence present of traffic on onsite wastewater system? Yes No

Meter Readings

Not Applicable

Estimated Hydraulic Flow Rate

375 gpd

Number of Occupants: 3 plus ten daycare students

Water Meter Reading:

O&M Activities

Septic Tank

- Current Operating Condition Acceptable?
- Effluent filter percent plugged? N/A%
Depth of scum (at outlet)? <1 inches
Depth of sludge (at outlet)? <1 inches
Depth below outlet invert? 48 inches

Absorption System

- Distribution device accessible?
- Distribution device free of solids, roots?
- Observation ports present, operational?
- Ponding, settling, and animal activity absent?

Comments:

2022 01 01 Recommend replacing the concrete septic tank lids at next tank pump service. Concrete lids are 20 inches in diameter.

System Status upon Departure

- Acceptable Maintenance Performed Maintenance Needed

Verify:

- Controls are set on the appropriate mode.
- Power is on to all components.
- All component lids are secure.
- All tools have been gathered from the site.

Certified Service Provider

I am Level III certified in accordance with Rule R317-11. I have inspected the onsite wastewater treatment and disposal system at the address above. I have conducted the required Field Testing and sample collection in accordance with R317-4. The information reported is true, accurate and complete and indicates the condition of the above onsite wastewater treatment system at the time of the O&M service visit. It does not guarantee that it will continue to function satisfactorily.

2022 Jan 01

DATE OF SIGNATURE

CARL R SHUPE
DOPL LICENSED ENVIRONMENTAL HEALTH SCIENTIST 5630685-2001
DWQ CERTIFIED ONSITE WASTEWATER LEVEL 3 00464-OSP-3
DOPL LICENSED CONTRACTOR 12011279-5501

Additional Comments:

Next Inspection:

-
-

Operational Checklists Completed

Site Assessment Form

On File (2022)

Tanks

Septic Tank, 804 gallons,

Final Treatment and Dispersal

Gravity Distribution, Absorption Trench,

2022 Jan 01













