



North  
TANK

203 West 14<sup>th</sup> Street, Ogden, Utah 84404  
PH (801) 392-1166 Fax (801) 392-4466

### SEPTIC SYSTEM REPORT

Date: 10/3/23 Technicians Name: Lakota Scadden  
Property Address: 2630 N Hwy 39  
System Age: 22 yrs? Occupied:  Yes  No (if no) Length of Time Vacant: trailer park  
Number of Bedrooms: NA Last Pump Date: never Recent Weather Conditions: WET

Liquid level in tank:  Above Normal  Normal  Below Normal Sludge Depth: 2 inch  
Gallons Pumped: 1,250 Depth of tank lid: 2 feet

Type of System:  Septic Tank (# of tanks     )  
 Cesspool  Aeration System  Other  
Type of Tank:  Steel  Concrete  Fiberglass  
Type of Absorption Area:  Leach Field  Raised Mound  Seepage Pit (# of pits     )  Other

System Component	Condition	Comments
Tank or Cesspool	<input checked="" type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	_____
Absorption Area	<input checked="" type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	_____
Baffles (if visible)	<input type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	<u>N/A</u>
<i>If applicable</i> Holding Tank (if present)	<input type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	<u>N/A</u>
Pump (if present)	<input type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	<u>N/A</u>

List of repairs if needed:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*There is no implied warranty with this report. Report only states condition of the septic system components visible to technician at the time of service.*



South Tank

203 West 14<sup>th</sup> Street, Ogden, Utah 84404  
PH (801) 392-1166 Fax (801) 392-4466

### SEPTIC SYSTEM REPORT

Date: 10/3/23 N Hwy 39 Technicians Name: Dakota Scadden  
Property Address: 2630 N Hwy 39  
System Age: 22 Occupied:  Yes  No (if no) Length of Time Vacant: trailer park  
Number of Bedrooms: N/A Last Pump Date: never Recent Weather Conditions: wet

Liquid level in tank:  Above Normal  Normal  Below Normal Sludge Depth: 2 inch

Gallons Pumped: 1,250 Depth of tank lid: 18 inch

**Type of System**  
 Septic Tank (# of tanks     )  
 Cesspool  
 Aeration System  
 Other

**Type of Tank:**  
 Steel  
 Concrete  
 Fiberglass

**Type of Absorption Area:**  
 Leach Field  
 Raised Mound  
 Seepage Pit (# of pits     )  
 Other

**System Component**  
Tank or Cesspool

Absorption Area

Baffles (if visible)

*If applicable*  
Holding Tank (if present)

Pump (if present)

**Condition**  
 Acceptable  Unacceptable  
 Acceptable  Unacceptable  
 Acceptable  Unacceptable  
 Acceptable  Unacceptable  
 Acceptable  Unacceptable

**Comments**  
N/A  
N/A, incoming baffle good  
N/A  
N/A

List of repairs if needed:

*Warranty with this report. Report only states condition of technician at the time of service.*