

SWPPP COMPLIANCE INSPECTION FORM

and the
WEBER COUNTY
ate: 9/15/14
tart time: 2:05
top time: 2:15
r.

ttuntsville	DEILC	JUNI	<u>I</u>	
Project Name: Frehner Fesidence Address: 306 N Maple Dr. Date:	9/10	5/1	1	
Owner: Tracy & Sherie Contractor (Gen/Sub): Harmony Homes Start time	2:	05	7_	
Site Contact: Brad Gill Phone: (801) (628-2190 Stop time		15		
UPDES Permit #: UTP 366343 Expiration: 2 4 15 Weather: Sunny Cloudy Raining Snowing Other:		,		
Date of last rain event: Duration: Approx. Rainfall (in):				
Inspected By (Print): Velci Huffaleer Local Jurisdiction or County: Weber County				
	DOV			
Inspection SW sampling Inspector Code (sizela) (S) State				
Code (circle): SW non-sampling 2 industrial 3 - 3th	ate			
SWPPP, EROSION, SEDIMENT AND HOUSEKEEPING BMP'S INFORMATION	YES	NO	N/A	
1. Is the SWPPP on site and accessible, or is the SWPPP location posted in an obvious place and reasonably accessible (in a short time)?		X		
 Are erosion control, sediment control, and good housekeeping BMP's installed on the site as shown in the SWPPP? Has the SWPPP been updated to reflect the current site conditions (modifications dated & initialed on site map, new BMPs on site map, discontinued 		X		
BMPs crossed off site map, new BMP details & spec's in SWPPP, SWPPP amendment Log. etc.)?		X		
4. Are on-site inspections being performed and recorded by a qualified person on a weekly or biweekly basis, reporting items required by permit? (Inspector	r	1		
name &qualifications, weather, problems/repairs, corrective action, new BMPs, removed BMPs, discharges, etc.) 5. Have all corrective action items from previous inspections been addressed and documented within the time frame allotted by the inspector?		~		
6. Are SW flows entering and leaving the construction site controlled, managed, or diverted around the site? (e.g. perimeter controls, berms, silt fence		X		
upgradient boundary diversion, down gradient boundary sediment control, etc.)		X		
7. Is there evidence of sediment discharge such as mud flows or soil deposits from the construction site in downstream locations?		X		
8. Is there evidence of vehicles tracking soil off the construction site?9. Is there soil, construction material, landscaping items, or other debris piled on impervious surfaces (roads, drives) that could be washed with SW to a	X			
storm drain or water body?	X			
10. Is there a need to repair, maintain, or improve erosion control BMPs (temporary stabilization, erosion blankets, mulch, vegetated strips, rip rap, surface roughening, pipe slope drain, dust control, etc)?		X		
11. Is there a need to repair, maintain, or improve sediment control BMPs (silt fence, check dams, fiber rolls, sediment trap/basin, inlet protection, wardles		/		
straw bails, curb cut-back, etc?	X			
12. Is there a need to repair, maintain, or improve good housekeeping controls (clean track out pad, sweeping, construction materials management, litter/trash control, port-o-potties staked down, fueling areas, concrete wash out area, proper curb ramps, spill prevention, etc)?	X			
13. Are there disturbed areas that have not had construction activities for 14 to 21 days without stabilization? (except snow or frozen ground)?	1/-	X		
14. Are there places where BMPs are needed and should be installed or not needed and should be removed?		X		
COMMENTS AND CORRECTIVE ACTIONS FOR SWPPP COMPLIANCE				
Identify the problem and its location. If appropriate, describe (in general terms) what needs to be completed. However, only if qualified (e.g., you are a designer) should you be no to install. Include the date when corrections are made.	nandating :	pecific l	3MPs	
NO SWPPP on Site			_	
140 OVITE OIL SILE			-	
Area ground site needs to be swept				
ried ground site needs to be swept			_	
			\neg	
			\neg	
			\dashv	
			-	
			\dashv	
nspector, please list all applicable SEV codes:			\dashv	
certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified	d personne	l proper	īv I	
athered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information submitted is, to the best of my knowledge and belief true, accurate, and complete. I am aware that there are significant penaltien for submitting false information, include	oformation	Ib.	<u> </u>	
f. fine and imprisonment for knowing violations.	ng the pos	sibility		
Male: Marchan		,		
1spector: Fe a threater Visi was was	9/	15/1	4	
(Print Name) (Title) (Signature)	1	Date)		
Brad Gill Imailed to harmanilla Cahalan	ril	ANV	M	
Operator: 1 100 5111 1110 FEQ 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ull.)ata)	11	